



Shire of  
**Narrogin**  
*Love the life*

## BRIDGES ASSET MANAGEMENT PLAN

2020-2030



# Contents

Shire of Narrogin Bridges Asset Management Plan 2020-2030 .....	1
Introduction .....	1
Asset Knowledge .....	2
Current Asset Performance .....	2
Understanding Community Expectations & Demand .....	3
Asset Lifecycle Management .....	4
Financial Sustainability.....	4
Grant Funding .....	4
Bridge Asset Management Plan Financial Summaries.....	7
Appendices	
1.    Main Roads WA Report: LGA Roles and Responsibilities 2020 by Anthony Humphreys .....	19
2.    Main Roads WA Report: Development of a Network Level Bridge Criticality and Risk Assessment Model by Neil Telfer .....	33
3.    Bridge 3125 Whimbin Rock Road over Arthur River: L2 Inspection .....	63
4.    Bridge 4551 Tarwonga Road over Wangelling Gully: L2 Inspection .....	87
5.    Bridge 3122 Tarwonga Road over Torbling Brook: L2 Inspection.....	113
6.    Bridge 3128A Manaring Road over Williams River: L2 Inspection .....	133
7.    Bridge 3142 Havelock Street over Narrogin Brook: L2 Inspection .....	157
8.    Bridge 9250 Pioneer Drive Pedestrian Bridge : L2 Inspection .....	175
9.    Bridge 4629 Doney Street Pedestrian Bridge: L2 Inspection .....	235
10.   Main Roads WA – 10 Year Bridge program .....	275
11.   Shire of Narrogin Annual L1 Bridge Inspections 2020 .....	279
12.   Shire of Narrogin Annual Bridge Routine Maintenance Checklist Template .....	293
13.   Shire of Narrogin Five Year Bridge Preventative Maintenance Checklist Template.....	295

## Acknowledgments:

The author would like to thank and acknowledge the input and supply of information from:

Mr Anthony Humphreys – MRWA Asset Management Structures;  
Mr John Warburton – Manager Operations, Shire of Narrogin;  
Mr Dale Stewart – Chief Executive Officer, Shire of Narrogin; and  
Mrs Wendy Russell – Executive Support Officer, Shire of Narrogin.

## Author:

Mr Torre Evans – Executive Manager Technical & Rural Services Shire of Narrogin.



# Preamble

## Shire of Narrogin Bridges Asset Management Plan 2020-2030

The Shire of Narrogin has a network of seven (7) bridges on road reserves to assist in promoting connectivity across the Shire for heavy vehicles, vehicles, cyclists and pedestrians. Like other infrastructure asset classes, for which the Shire has responsibility, it is critical that these assets are managed appropriately and responsibly. This asset management plan is intended to assist the Shire as it works towards more sustainable provision and management of its assets.

The seven (7) bridges include:

- Whinbin Rock Road (3125) over Arthur River;
- Tarwonga Road Bridge (South) (4551) over Wangelling Gully;
- Tarwonga Road Bridge (North) (3122) over Torbling Brook;
- Manaring Road Bridge (3128A) over Williams River;
- Havelock Street Bridge (3142) within the Narrogin Townsite;
- Pedestrian Railway Bridge (9250) connecting the Eastern side of Town with the Railway Station and CBD, over Pioneer Drive; and
- Pedestrian Doney Street Bridge (4629) allowing access from Doney Street through Gnarojin Park to Pioneer Drive, over Narrogin Brook.

### Introduction

- This Plan forms part of a suite of asset management plans (10 Year Road, Footpath and Plant Replacement etc.) that identify the requirements of the life cycle of an asset and form a guide for long term financial planning to preserve these assets in an acceptable condition for use.
- It has been developed to provide a strategic and practical framework for the management, protection and care of the Shire's bridges.
- A list of the Shire's bridge structures considered in this Plan is provided, demonstrating the recommended amounts of funding annually to preserve the asset.
- A number of bridge structures within the Shire are the responsibility of other authorities, and therefore not included in this Plan. Examples include bridges on Main Roads WA (MRWA) arterial roads, railway bridges and culverts under railway lines.
- Minor bridge structures on parks and reserves are excluded from this plan and will be considered in the costings of the Parks and Gardens Asset Management Plan soon to be drafted.
- Development and adoption of this Plan meets a number of Council objectives as well as the requirements of State and Federal Governments to allow the Shire to be eligible for grant funding when demonstrating a maintenance schedule over a ten year period.

- Implementation of this Plan is in line with the Shire's Strategic Community Plan 2017-2027:
  - 1.3 An effective well maintained transport network.
  - 1.3.1 Maintain and improve road network in line with resource capacity.
  - 3.4 A well maintained built environment.
  - 3.4.1 Improve and maintain built environment.

### **Asset Knowledge**

- The Shire is responsible for the management of seven (7) separate bridge structures on Shire road reserves worth approximately \$1,911,721 (current replacement cost February 2020) (valuation by Griffin Valuations 2019).
- In 2019/20, the Shire budgeted \$58,652 on bridge maintenance. This equates to an average of \$8,323.14 per structure. In the same year, \$31,040 was spent on renewal. It is envisaged with this Bridge Asset Management Plan, that between the years 2020 and 2030, the Shire's average spend to maintain its bridge assets will be \$40,782.00.
- Data regarding the Shire's bridge structures is stored within the W Drive.
- Annual formal inspections of all Shire managed bridges are carried out and formally recorded by trained personnel. All identified works and scheduled maintenance i.e. visual check, tightening of nuts and bolts, cleaning of scuppers, pruning of vegetation and the renewal of signage and barriers are undertaken by the Shire's works crew or suitably qualified contractors.
- Five (5) yearly preventative maintenance is carried out by an experienced contractor, due to these works being more specialised and requiring specific tools. These tasks include fungal treatment, termite inspections and treatment, bolt shimming, pile repairs, corbel repairs, pile banding and jacking.
- L2 inspections are formal inspections conducted by Main Roads WA engineers every five years for timber bridges and 7 years for steel bridges and are provided to the Shire for action or budgeting purposes.
- This Ten Year Program, has been developed to recognise the use and requirements of each structure and is expected to be used in future years to facilitate prioritisation of the Shire's renewal, upgrade, inspection and maintenance programs.

### **Current Asset Performance**

- Over the past four (4) years, a condition audit (Level 2 Inspection) has been undertaken in accordance with the requirements described in the Main Roads WA Road Structures Inspection Manual on six (6) of the Shire's Bridges. The one remaining bridge being the Doney Street pedestrian bridge has not had an L2 inspections conducted on it since 2003, at which time it had major refurbishment and became non trafficable. It is worth mentioning that refurbishment works are scheduled to be conducted on the Railway pedestrian bridge in the 2019/20 financial year.
- Both bridges on Tarwonga Road and the Manaring Road Bridge were considered to be in good condition.
- Whinbin Rock Road Bridge was found to be in a fair condition.

- Havelock Street Bridge had no conditioning data recorded.
- In addition to the Level 2 Inspection, the Shire inspects all bridges on a 12 monthly cycle in accordance with MRWA recommendations and guidelines – L1 inspections. This annual inspection routine, demonstrates that the Shire has a formal maintenance program in place which in turn, allows the Shire to be eligible for MRWA grant funding for bridge preservation.
- A review of maintenance history, since 2016, suggests that less than 20 issues per bridge are identified each year. The majority of issues are identified by annual and L2 inspections. Often, the items identified result in no action because the defect does not meet documented intervention levels or the defect reported is a known issue that is already being addressed by staff. Any items identified for action are scheduled for repair unless urgent, whereby immediate action is taken for the safety of the bridge users.
- The performance of the Shire's reactive bridge maintenance has been to a good standard however reactive maintenance required is minimal due to the Shire's annual L1 inspection routine and MRWA L2 bi-annual inspection routine.

### **Understanding Community Expectations & Demand**

- The Shire's bridge assets have been constructed to support the Shire's road and path network, whilst ensuring stormwater runoff is not obstructed. Community expectations and demand for bridges therefore arise from demand for improvements in water management or the connectivity of the Shire's roads and/or pathways.
- Stakeholders include: local residents and businesses, farmers, transport industry, people passing through the Shire, the Shire's Insurers and other authorities including neighbouring Shire's, MRWA, Western Power, Water Corporation and other utilities.
- The Shire currently investigates community expectations and demand in a number of ways:
  - Informal interactions between Shire officers and the community as part of normal daily activities.
  - Review of community requests.
  - Community consultation undertaken during the development of strategic documents.
  - Road traffic counters to inform on usage volume and type.
- It is recognised that further strategic service planning work is required to better understand current and future community needs.
- Recommended improvement actions:
  - Consider demand forecasting and levels of service in all future Transport and Traffic and Integrated Water Management service planning work, eg the Secondary Freight Route initiative.

## **Asset Lifecycle Management**

- A coordinated approach to the management of all phases of the service and asset lifecycles is considered necessary to sustainably meet community needs and preserve the asset for its intended purpose.
- Transport services and general traffic make use of the Shire's bridges.
- These services were established long ago and will continue into the foreseeable future to service the Town and Region.
- This Plan focuses on analysing the Shire's approach to asset lifecycle management and the required funding to do so to preserve the asset for its intended use.
- The Plan also demonstrates:
  - Maintenance and renewal cost estimates into designs to enable improved estimation of lifecycle costs associated with new works.
  - The use of routine inspection strategies by trained and qualified inspectors to identify the assets maintenance and renewal requirements and allow for costing for the management of the assets life cycle.

## **Financial Sustainability**

- Financial sustainability requires a balance between the delivery of new assets and the maintenance, renewal or disposal of existing assets.
- Funding allocations at each stage of the asset lifecycle impact the standard to which the assets perform.
- Funding will also be dependent on the Shire's annual budget process. Bridges form an important part of a rural community for connectivity and it is recommended that funding the preservation of these assets is given high priority by Council.
- This plan will be factored into the Shire's Long Term Financial Plan (LTFP) which identifies the Shires long term financial strategy to maintain the organisations assets in a sustainable financial manner.

## **Grant Funding**

Following a load assessment analysis carried out by MRWA during a L2 inspection, bridge structures that are deficient will require Emergency Repairs to restore the load carrying capacity of the bridge and/or a load posting.

Given the significance of the structure on the road network a Local Government may consider it appropriate to adopt the load limit for the bridge. If this option is preferred, Main Roads will arrange for the installation of the load limit signage. If a load limit is not acceptable then Emergency Repairs are required and these works will need to be funded by the Local Government. If the Local Government can demonstrate that they have an ongoing programme of Preventative Maintenance for their bridge structures then the Local Government is eligible for a funding contribution of 2/3 Main Roads and 1/3 Local Government, subject to a number of conditions.



Preventative Maintenance is the responsibility of the Local Governments to fund and undertake. The WA Local Government Grants Commission (WALGGC) provides a contribution towards these activities. This money is included in the Local Government's Road Preservation Grant. The funds are calculated on bridge deck area and \$m<sup>2</sup> rate depending on the type of structure.

The Commonwealth provides Financial Assistance Grant funding (FAGS) to the WALGGC in the form of Untied Funds for Local Roads. Of these funds (excluding Roads to Recovery funding), 7% is set aside for Special Projects and two thirds of the 7% is provided for Specific Works on Local Government bridges and one third for Remote Aboriginal Access Roads. The State provides a one third matching contribution from the Agreement for every two thirds provided by the Commonwealth.

In special circumstances funds are also provided for bridgeworks that are either totally funded through MRWA Programs or contributions arranged with Local Government.

MRWA's contribution for bridgeworks funded from the WALGGC is limited to a maximum of one third of the estimated total cost of the work and is only available after the Local Government's two third share is expended.

WALGGC prompts all Local Governments to submit project applications on an annual basis. Funds are allocated by the WALGGC based on recommendations provided by the Bridge Committee. The Bridge Committee comprises representatives from Main Roads WA, WALGGC and WALGA. The Committee receives recommendations from Main Roads WA on the priorities of projects under consideration. Delivery of projects is generally managed by Main Roads WA but Local Governments have the option to manage the projects themselves.


Special Project funds are only allocated for Specific Works on bridges which are defined as planned proactive work items normally scheduled at least two years in advance to maintain the integrity of bridge structural components. Funds may also be allocated for bridge reconstruction where the existing bridge has reached the end of its economic life. Funding only covers like for like replacement costs. The Special Project funds do not cover routine or preventative maintenance or new bridge construction where there is no existing bridge.

In order to be eligible for Special Project funds a Local Government must be able to show that annual visual inspections have been performed in accordance with the Level 1 Bridge Inspection Framework and also that adequate routine and preventative maintenance have been undertaken to prevent undue deterioration.

Page intentionally left blank

## Bridge Asset Management Plan Financial Summaries

Municipal Expenditure	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28	2028/29	2029/30	Average
Operating	\$ 34,883.00	\$ 46,733.00	\$ 55,733.00	\$ 41,293.00	\$ 50,904.00	\$ 31,064.00	\$ 34,714.00	\$ 34,014.00	\$ 41,014.00	\$ 37,474.00	\$ 40,782.60
Net Capital Expenditure	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -
Transfer to / (From) Bridge Reserve	\$ 14,035.00	\$ 1,549.00	\$ (7,451.00)	\$ 1,989.00	\$ (10,122.00)	\$ 9,718.00	\$ 6,068.00	\$ 6,768.00	\$ (232.00)	\$ 3,308.00	
Net Municipal Expenditure	\$ 48,918.00	\$ 48,282.00	\$ 48,282.00	\$ 43,282.00	\$ 40,782.00	\$ 40,782.00	\$ 40,782.00	\$ 40,782.00	\$ 40,782.00	\$ 40,782.00	\$ 43,345.60
Reserve Fund Balance	\$ 14,035.00	\$ 15,584.00	\$ 8,133.00	\$ 10,122.00	\$ -	\$ 9,718.00	\$ 15,786.00	\$ 22,554.00	\$ 22,322.00	\$ 25,630.00	



# 2020/2021

## OPERATING EXPENDITURE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Labour	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	<b>\$1,400.00</b>
Labour Overhead	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	<b>\$1,680.00</b>
Plant Cost	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	<b>\$1,750.00</b>
Materials ( Specific Repairs )	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	<b>\$4,900.00</b>
Contractors ( 5 Year Preventative Mtc )			\$8,150.00					<b>\$8,150.00</b>
Contractors ( Termites )	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	<b>\$14,000.00</b>
Insurance	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	<b>\$3,003.00</b>

**Total Operating Expenditure** **\$34,883.00**

## CAPITAL EXPENDITURE/REVENUE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Expenditure	0	0	0	0	0	0	0	<b>0</b>
Revenue	0	0	0	0	0	0	0	<b>0</b>

**Total Capital Expenditure** **0**

**Transfer to / from Bridge Reserve** **\$14,035.00**

**Total Cost To Muni 2020/21** **\$48,918.00**



## 2021/22

### OPERATING EXPENDITURE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Labour	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	<b>\$1,400.00</b>
Labour Overhead	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	<b>\$1,680.00</b>
Plant Cost	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	<b>\$1,750.00</b>
Materials ( Specific Repairs )	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	<b>\$4,900.00</b>
Contractors ( 5 Year Preventative Mtc )				\$9,000.00		\$11,000.00		<b>\$20,000.00</b>
Contractors ( Termites )	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	<b>\$14,000.00</b>
Insurance	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	<b>\$3,003.00</b>

**Total Operating Expenditure** **\$46,733.00**

### CAPITAL EXPENDITURE/REVENUE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Expenditure	\$15,001.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	<b>\$15,001.00</b>
Revenue	-\$15,001.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	<b>-\$15,001.00</b>

**Total Capital Expenditure** **0**

**Transfer to / from Bridge Reserve** **\$1,549.00**

**Total Cost To Muni 2021/22** **\$48,282.00**

## 2022/23

### OPERATING EXPENDITURE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Labour	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	<b>\$1,400.00</b>
Labour Overhead	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	<b>\$1,680.00</b>
Plant Cost	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	<b>\$1,750.00</b>
Materials ( Specific Repairs )	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	<b>\$4,900.00</b>
Contractors ( 5 Year Preventative Mtc )					\$11,000.00		\$18,000.00	<b>\$29,000.00</b>
Contractors ( Termites )	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	<b>\$14,000.00</b>
Insurance	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	<b>\$3,003.00</b>

**Total Operating Expenditure** **\$55,733.00**

### CAPITAL EXPENDITURE/REVENUE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Expenditure	0	0	0	0	0	0	0	<b>0</b>
Revenue	0	0	0	0	0	0	0	<b>0</b>

**Total Capital Expenditure** **0**

**Transfer to / from Bridge Reserve** **-\$7,451.00**

**Total Cost To Muni 2022/23** **\$48,282.00**

## 2023/24

### OPERATING EXPENDITURE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Labour	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	<b>\$1,400.00</b>
Labour Overhead	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	\$240.00	<b>\$1,680.00</b>
Plant Cost	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	\$250.00	<b>\$1,750.00</b>
Materials ( Specific Repairs )	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00	<b>\$4,900.00</b>
Contractors ( 5 Year Preventative Mtc )	\$14,560.00							<b>\$14,560.00</b>
Contractors ( Termites )	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	\$2,000.00	<b>\$14,000.00</b>
Insurance	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	\$429.00	<b>\$3,003.00</b>

**Total Operating Expenditure** **\$41,293.00**

### CAPITAL EXPENDITURE/REVENUE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Expenditure	\$0.00	\$0.00	\$0.00	\$270,000.00	\$0.00	\$0.00	\$0.00	<b>\$270,000.00</b>
Revenue	\$0.00	\$0.00	\$0.00	-\$270,000.00	\$0.00	\$0.00	\$0.00	<b>-\$270,000.00</b>

### Manaring Road Bridge 3128A Converted To Culvert

**Total Capital Expenditure** **0**

**Transfer to / from Bridge Reserve** **\$1,989.00**

**Total Cost To Muni 2023/24** **\$43,282.00**

## 2024/25

### OPERATING EXPENDITURE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Labour	\$200.00	\$200.00	\$200.00		\$200.00	\$200.00	\$200.00	<b>\$1,200.00</b>
Labour Overhead	\$240.00	\$240.00	\$240.00		\$240.00	\$240.00	\$240.00	<b>\$1,440.00</b>
Plant Cost	\$250.00	\$250.00	\$250.00		\$250.00	\$250.00	\$250.00	<b>\$1,500.00</b>
Materials ( Specific Repairs )	\$700.00	\$700.00	\$700.00		\$700.00	\$700.00	\$700.00	<b>\$4,200.00</b>
Contractors ( 5 Year Preventative Mtc )		\$27,990.00						<b>\$27,990.00</b>
Contractors ( Termites )	\$2,000.00	\$2,000.00	\$2,000.00		\$2,000.00	\$2,000.00	\$2,000.00	<b>\$12,000.00</b>
Insurance	\$429.00	\$429.00	\$429.00		\$429.00	\$429.00	\$429.00	<b>\$2,574.00</b>

**Total Operating Expenditure** **\$50,904.00**

### CAPITAL EXPENDITURE/REVENUE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Expenditure	0	0	0	0	0	0	0	<b>0</b>
Revenue	0	0	0	0	0	0	0	<b>0</b>

**Total Capital Expenditure** **0**

**Transfer to / from Bridge Reserve** **-\$10,122.00**

**Total Cost To Muni 2024/25** **\$40,782.00**



## 2025/26

### OPERATING EXPENDITURE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Labour	\$200.00	\$200.00	\$200.00		\$200.00	\$200.00	\$200.00	<b>\$1,200.00</b>
Labour Overhead	\$240.00	\$240.00	\$240.00		\$240.00	\$240.00	\$240.00	<b>\$1,440.00</b>
Plant Cost	\$250.00	\$250.00	\$250.00		\$250.00	\$250.00	\$250.00	<b>\$1,500.00</b>
Materials ( Specific Repairs )	\$700.00	\$700.00	\$700.00		\$700.00	\$700.00	\$700.00	<b>\$4,200.00</b>
Contractors ( 5 Year Preventative Mtc )			\$8,150.00					<b>\$8,150.00</b>
Contractors ( Termites )	\$2,000.00	\$2,000.00	\$2,000.00		\$2,000.00	\$2,000.00	\$2,000.00	<b>\$12,000.00</b>
Insurance	\$429.00	\$429.00	\$429.00		\$429.00	\$429.00	\$429.00	<b>\$2,574.00</b>

**Total Operating Expenditure** **\$31,064.00**

### CAPITAL EXPENDITURE/REVENUE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Expenditure	0	0	0	0	0	0	0	<b>0</b>
Revenue	0	0	0	0	0	0	0	<b>0</b>

**Total Capital Expenditure** **0**

**Transfer to / from Bridge Reserve** **\$9,718.00**

**Total Cost To Muni 2025/26** **\$40,782.00**

## 2026/27

### OPERATING EXPENDITURE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Labour	\$200.00	\$200.00	\$200.00		\$200.00	\$200.00	\$200.00	<b>\$1,200.00</b>
Labour Overhead	\$240.00	\$240.00	\$240.00		\$240.00	\$240.00	\$240.00	<b>\$1,440.00</b>
Plant Cost	\$250.00	\$250.00	\$250.00		\$250.00	\$250.00	\$250.00	<b>\$1,500.00</b>
Materials ( Specific Repairs )	\$700.00	\$700.00	\$700.00		\$700.00	\$700.00	\$700.00	<b>\$4,200.00</b>
Contractors ( 5 Year Preventative Mtc )						\$11,800.00		<b>\$11,800.00</b>
Contractors ( Termites )	\$2,000.00	\$2,000.00	\$2,000.00		\$2,000.00	\$2,000.00	\$2,000.00	<b>\$12,000.00</b>
Insurance	\$429.00	\$429.00	\$429.00		\$429.00	\$429.00	\$429.00	<b>\$2,574.00</b>

**Total Operating Expenditure** **\$34,714.00**

### CAPITAL EXPENDITURE/REVENUE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Expenditure	0	0	0	0	0	0	0	<b>0</b>
Revenue	0	0	0	0	0	0	0	<b>0</b>

**Total Capital Expenditure** **0**

**Transfer to / from Bridge Reserve** **\$6,068.00**

**Total Cost To Muni 2026/27** **\$40,782.00**

# 2027/28

## OPERATING EXPENDITURE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Labour	\$200.00	\$200.00	\$200.00		\$200.00	\$200.00	\$200.00	<b>\$1,200.00</b>
Labour Overhead	\$240.00	\$240.00	\$240.00		\$240.00	\$240.00	\$240.00	<b>\$1,440.00</b>
Plant Cost	\$250.00	\$250.00	\$250.00		\$250.00	\$250.00	\$250.00	<b>\$1,500.00</b>
Materials ( Specific Repairs )	\$700.00	\$700.00	\$700.00		\$700.00	\$700.00	\$700.00	<b>\$4,200.00</b>
Contractors ( 5 Year Preventative Mtc )					\$11,100.00			<b>\$11,100.00</b>
Contractors ( Termites )	\$2,000.00	\$2,000.00	\$2,000.00		\$2,000.00	\$2,000.00	\$2,000.00	<b>\$12,000.00</b>
Insurance	\$429.00	\$429.00	\$429.00		\$429.00	\$429.00	\$429.00	<b>\$2,574.00</b>

**Total Operating Expenditure** **\$34,014.00**

## CAPITAL EXPENDITURE/REVENUE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Expenditure	0	0	0	0	0	0	0	<b>0</b>
Revenue	0	0	0	0	0	0	0	<b>0</b>

**Total Capital Expenditure** **0**

**Transfer to / from Bridge Reserve** **\$6,768.00**

**Total Cost To Muni 2027/28** **\$40,782.00**

## 2028/29

### OPERATING EXPENDITURE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Labour	\$200.00	\$200.00	\$200.00		\$200.00	\$200.00	\$200.00	<b>\$1,200.00</b>
Labour Overhead	\$240.00	\$240.00	\$240.00		\$240.00	\$240.00	\$240.00	<b>\$1,440.00</b>
Plant Cost	\$250.00	\$250.00	\$250.00		\$250.00	\$250.00	\$250.00	<b>\$1,500.00</b>
Materials ( Specific Repairs )	\$700.00	\$700.00	\$700.00		\$700.00	\$700.00	\$700.00	<b>\$4,200.00</b>
Contractors ( 5 Year Preventative Mtc )							\$18,100.00	<b>\$18,100.00</b>
Contractors ( Termites )	\$2,000.00	\$2,000.00	\$2,000.00		\$2,000.00	\$2,000.00	\$2,000.00	<b>\$12,000.00</b>
Insurance	\$429.00	\$429.00	\$429.00		\$429.00	\$429.00	\$429.00	<b>\$2,574.00</b>

**Total Operating Expenditure** **\$41,014.00**

### CAPITAL EXPENDITURE/REVENUE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Expenditure	0	0	0	0	0	0	0	<b>0</b>
Revenue	0	0	0	0	0	0	0	<b>0</b>

**Total Capital Expenditure** **0**

**Transfer to / from Bridge Reserve** **-\$232.00**

**Total Cost To Muni 2028/29** **\$40,782.00**



## 2029/30

### OPERATING EXPENDITURE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Labour	\$200.00	\$200.00	\$200.00		\$200.00	\$200.00	\$200.00	<b>\$1,200.00</b>
Labour Overhead	\$240.00	\$240.00	\$240.00		\$240.00	\$240.00	\$240.00	<b>\$1,440.00</b>
Plant Cost	\$250.00	\$250.00	\$250.00		\$250.00	\$250.00	\$250.00	<b>\$1,500.00</b>
Materials ( Specific Repairs )	\$700.00	\$700.00	\$700.00		\$700.00	\$700.00	\$700.00	<b>\$4,200.00</b>
Contractors ( 5 Year Preventative Mtc )	\$14,560.00							<b>\$14,560.00</b>
Contractors ( Termites )	\$2,000.00	\$2,000.00	\$2,000.00		\$2,000.00	\$2,000.00	\$2,000.00	<b>\$12,000.00</b>
Insurance	\$429.00	\$429.00	\$429.00		\$429.00	\$429.00	\$429.00	<b>\$2,574.00</b>

**Total Operating Expenditure** **\$37,474.00**

### CAPITAL EXPENDITURE/REVENUE

TYPE	Whinbin Rock Rd 3125	Tarwonga Rd 4551	Tarwonga Rd 3122	Manaring Rd 3128A	Havelock St 3142	Doney st Footbridge 4629	Main Footbridge 9250	Total
Expenditure	0	0	0	0	0	0	0	<b>0</b>
Revenue	0	0	0	0	0	0	0	<b>0</b>


**Total Capital Expenditure** **0**

**Transfer to / from Bridge Reserve** **\$3,308.00**

**Total Cost To Muni 2029/30** **\$40,782.00**

# Bridges Reserve

	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28	2028/29	2029/30
<b>Opening Balance</b>	0	14,035	15,584	8,133	10,122	0	9,718	15,786	22,554	22,322
Operating	(34,883)	(46,733)	(55,733)	(41,293)	(50,904)	(31,064)	(34,714)	(34,014)	(41,014)	(37,474)
Net Capital Expenditure	0	0	0	0	0	0	0	0	0	0
Transfer to / (From) Bridge Reserve	48,918	48,282	48,282	43,282	40,782	40,782	40,782	40,782	40,782	40,782
<b>Closing Balance</b>	14,035	15,584	8,133	10,122	0	9,718	15,786	22,554	22,322	25,630



**Main Roads WA Report:  
LGA Roles and Responsibilities 2020**  
by Anthony Humphreys

## Bridge Roles and Responsibilities:

### Bridge Owners

- Local Government Authority:
  - Bridge on the local road network.
- Main Roads:
  - Typically bridges on Highways and main roads.
  - With the exception of a few:
    - Significant bridges on local roads and
    - Bridges over rail lines on local roads.
- Department of Parks and Wildlife (formally Department of Environment and Conservation):
  - Typically on forestry and logging roads.
- Private:
  - Bridge on private land, records kept for future enquires over ownership.
- Water Corporation:
  - Bridges on local roads over drainage channels.
- Harvey Water:
  - Bridges on local roads over irrigation channels (applicable in the South West Region)
- Public Transport Authority:
  - Railway bridges over a road.

### Detail and Annual Visual Inspections

Level 2 or Detail inspections are undertaken by Main Roads to determine the load carrying capacity of bridges that can be accessed by the General Public. The frequencies of these inspections are every 5 years for Timber bridges and 7 years for Steel or Concrete bridges. From this report the following is determined:

- Load capacity of the structure
- Preventative Maintenance activities required to preserve bridge.
- Specific Work activities to maintain the load carrying capacity of the structure.

A copy of this report is issued to the Local Government.

Main Roads recommends that Local Government undertake Level 1 or Annual Visual Inspections of their bridges to identify any problems that may occur in between the detailed inspection cycle and their responsibility under nonfeasance. If the Local Government has any concerns over any issues please contact me and I will inspect and or arrange a future detailed inspection. For details on how to undertake inspections and associated forms refer to the "Useful Information" section.

## Emergency Repairs and Load Posting

Following the load assessment analysis, structures that are deficient will require Emergency Repairs to restore the load carrying capacity of the bridge and/or a load posting.

Given the significance of the structure on the road network a Local Government may consider it appropriate to adopt the load limit for the bridge. If this option is preferred, Main Roads will arrange for the installation of the load limit signage.

If a load limit is not acceptable then Emergency Repairs are required and these works will need to be funded by the Local Government. If the Local Government can demonstrate that they have an ongoing programme of Preventative Maintenance for their structures then the Local Government is eligible for a funding contribution of 2/3 Main Roads and 1/3 Local Government, subject to a number of conditions, see page 22 of the link below:

[https://www.mainroads.wa.gov.au/Documents/State Road Funds to Local Government Procedures.RCN-D13^23169676.PDF](https://www.mainroads.wa.gov.au/Documents/State%20Road%20Funds%20to%20Local%20Government%20Procedures.RCN-D13^23169676.PDF)

1. The Local Government will provide Main Roads with evidence that it has undertaken preventative maintenance on the **affected** bridge.
2. Main Roads and the Local Government are to agree on the scope of works required.
3. The Local Government will provide Main Roads with an agreed cost estimate for undertaking the repairs.
4. Main Roads will authorise the repair work prior to commencement
5. The Local Government will complete the repairs and invoice Main Roads for the 2/3 of the agreed estimated cost.
6. Main Roads will confirm that the standard of repair work is acceptable prior to arranging payment from the Emergency Bridge Fund.

## Preventative Maintenance

Preventative Maintenance is the responsibility of the Local Governments to fund and undertake.

The WA Local Government Grants Commission (WALGGC) provides a contribution towards these activities (refer attached policy). This money is included in the Local Government's Road Preservation Grant. The funds are calculated on bridge deck area and \$m2 rate depending on type of structure.

Preventative maintenance includes the following activities:

- Routine Maintenance:
  - Activities required to preserve the structure.
  - The frequency of this type of maintenance is typically annual and includes:
    - cleaning of scuppers, drainage, expansion joints
    - vegetation and debris clearing
    - termite inspection and treatment
    - guardrail maintenance
    - signage etc.
- Periodic Maintenance
  - Rate \$100/m<sup>2</sup>
  - Activities required to preserve the structure.
  - The frequency of this type of maintenance is 5 yearly and includes:
    - fungicide treatment to stingers, piles, sill beams etc
    - timber end grain sealing
    - fastener maintenance
- Specific Works - minor
  - Activities required to preserve the structure.
  - Rate \$3000 to \$5000 per bridge
  - The frequency of this type of maintenance is undertaken as required and includes:
    - repair splits in piles and stringers including bolting and banding
    - abutment sheeting repairs
    - shimming and packing of stringers and halfcaps etc

For details of the "Timber Bridge Preventative Maintenance Standards" refer to the "Useful Information" section.

Note: Plastic Plug Colours

Colour	Grey	Red	Blue	Yellow	Green	White	Pink
Year	2021	2015 2022 2029	2016 2023 2030	2017 2024 2031	2018 2025 2032	2019 2026 2033	2020 2027 2034

A key reason for implementation of this system was for the safety of bridge inspectors – hot liquids on skin don't mix.

Another benefit is it easy to see when the bridge was last treated.

Costs for LGA's to consider when developing their 5 year Preventative Maintenance schedule, detail break down:

	Rate per m2 deck area	Annualised rate per m2 deck area
Routine Maintenance, undertaken annually	\$5 in rural areas \$15 urban areas	\$5 in rural areas \$15 urban areas
Routine Maintenance - termite treatment (timber) undertaken every two years	\$12	\$6
Periodic Maintenance, undertaken on a 5 year cycle (timber)	\$130	\$26
Minor Specific Repairs, undertaken with Periodic Maintenance	\$25	\$5
Periodic Maintenance, undertaken on a 5 year cycle (concrete) There is not Periodic Maintenance that is done on a cyclic basis for concrete bridges, the works are more Routine Maintenance and Minor Specific Repairs.	\$10	\$2
Reconstruction, bridge replacement	\$6000 to \$10,000 \$14,000 further from Perth 7hrs+	N/A
Concrete Overlays	\$2500-simple overlays \$3500 substantial substructure repairs as well.	N/A

## Insurance

Insurance is prudent.

## Specific Works

Specific Works are repairs to maintain the carrying capacity of the structure and are either complex and/or expensive. These are typically once-off repairs.

Specific Works activities can be funded and undertaken by the Local Government. However, if the Local Government is prepared to wait for Main Roads to arrange funding, projects can be funded:

1. On an as-needs basis – higher priority projects get funding first.
2. If the Local Government can demonstrate that Preventative Maintenance is being undertaken on its bridges. (a condition for WALGGC funding)

Funding Sources for Specific Works are:

- Bridge Maintenance Programme (Special Projects):
  - The funding split is 1/3 Main Roads and 2/3 Grants Commission.
  - Refer attached policy.
    - Grants Commission funding is typically like for like, so if a structure is to be widened then the Local Government will need to find additional funds to widen the structure prior to the works proceeding.
- Local Government funds
- Regional Road Group
- Roads to Recovery
- Black Spot.

## Issues for Consideration

- Preventative Maintenance – 5 year plan.
- Timing of works on your road network – tie in with bridge works.
- Bridges with 1 to 3 spans - look to replace with culvert or concrete overlay – check for value for money; undertake waterways assessments to determine suitability of a culvert replacement
- Bridges with a headroom of less than 1.20m – look at replacing with a culvert.. These bridges are causing an Occupational Health and Safety Issue with the Bridge Inspectors and Bridge Contractors.
- Bridges of 8+ spans - look to preserve and maintain, as the cost of replacement is very high.



## Useful information:

The Main Roads website contains a number of useful documents:

Web Site: [www.mainroads.wa.gov.au](http://www.mainroads.wa.gov.au)

→ Building Roads

→ Standards & Technical

→ Structures Engineering

→ Asset Management

- Structures Location Map Books
- Structure Definitions
- Inventory Forms
- Inspection Guidelines
  - Level 1 Bridge & Culvert Inspection – documents and forms.
  - Level 2 Culvert Inspection – document and from
- Asset Management Plan
- Attachment of Services to Existing Structures
- Miscellaneous Asset Management Documents
  - Termite Inspection Plate (see attached)
  - Periodic Maintenance Plate (see attached)
  - Bridge Number Tag (see attached)
  - Vegetation Clearance Envelope (see attached)
  - Timber Bridge Preventative Maintenance Standards

→ Main Roads Drawings

→ Standard Contact Drawings


- Culverts – Box
- Culverts – Pipe
- Guardrail

## Contact Details

Anthony Humphreys  
Asset Manager Structures

Ph: 9892 0534  
Mobile: 0408955908  
Email: [anthony.humphreys@mainroads.wa.gov.au](mailto:anthony.humphreys@mainroads.wa.gov.au)

# Bridge Programming Process (LGA)



## WA Local Government Grants Commission

### POLICY FOR ALLOCATION OF SPECIAL PROJECT FUNDS FOR BRIDGES

Under the current principles, 93% of the Federal road funds are allocated to local governments in accordance with road asset preservation needs. The remaining 7% is allocated as Special Projects, two thirds for bridges and one third for roads serving remote Indigenous communities.

The cost of preventive maintenance and annual routine maintenance of bridges is taken into account in calculating road asset preservation needs. The current rates are \$24.60 per square metre for timber bridges and \$12.30 per square metre for steel and concrete bridges. The cost of specific maintenance, refurbishment and replacement of bridges is not taken into account because funds are specifically provided for these works through the Special Project funds.

The Commission's policy for allocating the Special Project funds for bridges recognises that there are a large number of Local Government bridges in poor condition, and that the preservation of these bridges must be given priority in allocating the Special Project funds.

The Commission's policy on Special Project funds for bridges restricts funding to only preservation type projects, recognising that some of these projects may involve some upgrading, and preservation includes replacement when the existing bridge has reached the end of its economic life.

Bridges must meet the following definition to be eligible for Special Projects funds:

A bridge is defined as:

*A structure with a clear opening in any span of greater than 3 metres measured between the faces of piers and or abutments.*

*A structure with a clear span of less than 3 metres where the deck is supported on timber stringers. This provision is in recognition of the higher maintenance costs and management requirements of timber structures.*

A footpath attached to a road bridge or a footbridge over a road is eligible for Special Project funds. A free-standing footbridge over a river is not eligible.

The Commission will not allocate funds for the construction of a new bridge where there is no existing bridge, or where an existing bridge has not reached the end of its economic life.

The Commission considers recommendations of the Bridge Committee in allocating the Special Project funds. The Committee is made up of representatives of Main Roads WA, the Western Australian Local Government Association and the WA Local Government Grants Commission.

The Bridge Committee makes its recommendations after considering technical advice and priority ratings from Main Roads WA. These ratings take into account bridge condition data and issues such as safety considerations which are identified through liaison with local governments.

The Bridge Committee will not support grants for the repair or replacement of a bridge if the bridge has not been given the degree of routine and preventive maintenance necessary to prevent undue deterioration. For timber bridges, owners are referred to the Main Roads WA document "Timber Bridge Maintenance and Refurbishment – Preventive Maintenance Standards".

## **Commission Policy**


***That Special Project funds be allocated to only preservation type projects. These include:***

- 1. Specific maintenance and refurbishment aimed at preserving the bridge.***
- 2. Replacement of an existing bridge where it has reached the end of its economic life.***
  - ❑ Where a bridge is replaced with a new bridge, the new structure must be of a similar geometric standard to the existing bridge; e.g. a single lane bridge is replaced with a single lane bridge. Replacement may include minor upgrading and widening [up to one metre] to meet current design and safety standards.***
  - ❑ Where widening greater than one metre is required to meet current design standards or to satisfy local government policies, the additional cost of the widening will be met by the local government.***
  - ❑ A bridge that has reached the end of its economic life may be replaced with a culvert or a floodway where engineering investigations show that this is the best solution.***
- 3. In special circumstances, and where the existing bridge has not reached the end of its economic life, the Commission may agree to the Special Project funds allocated for the preservation of the existing bridge being put towards the construction of a new bridge of a higher standard than the existing structure. This provision would apply where a local government is able to access the additional funds needed for the new bridge from other sources.***


3 August 2015

\\clives\bridges\policy\policy amended 2015.docx

50 E N  
NUMERALS  
& LETTERS




50 E N  
NUMERALS  
& LETTERS



NOTES:

- SIGN DIMENSIONS (IN mm) :  
SIZE 320 x 110 CORNER RADIUS 25 BORDER 8 + 5  
SIGN PANEL AREA = 0.03466 m
- COLOURS : BLACK LEGEND ON WHITE RETROREFLECTIVE BACKGROUND
- RETROREFLECTIVE CLASS OF MATERIAL : CLASS 1
- GRAFFITI PROTECTION: NOT REQUIRED
- ALL SIGN MATERIALS AND MANUFACTURE TO BE IN ACCORDANCE WITH MAIN ROADS SPECIFICATION 601.
- SIGN HOLES : DRILL ø4 HOLES TOP & BOTTOM CENTRALLY ON PANEL
- THERE ARE TO BE NO ZERO's (0) BEFORE BRIDGE NUMBER.

G6 2




BRIDGE NUMBER TAG  
ARRANGEMENT

(TO BE PLACED AT BOTH BRIDGE  
ABUTMENTS)


3	12/12/12	ADDED BRIDGE TAG HEIGHT DIMENSION.	T.S.
2	29/10/12	CHANGED RETROREFLECTIVE CLASS TO 1 & ADDED CROSSING NAME SIGN TYPE.	T.S.
1	24/4/12	ADDED HOLE DIMENSION.	T.S.

**MRWA - STRUCTURES ENGINEERING**


BRIDGE NUMBER	DRAWING NUMBER	AMEND.
-	1230-0487-3	




GENERAL PLAN VIEW FOR CLEARING AROUND STRUCTURES



ELEVATION - SINGLE STRUCTURE



ELEVATION - DUAL STRUCTURE



ELEVATION - SPLIT STRUCTURE

LEGEND:

NO TRUNKS >  $\phi 100\text{mm}$ .  
MAXIMUM INTERVENTION  
LEVEL IS 300mm

NO OVERHANGING BRANCHES  
FOR 6m ABOVE DECK SURFACE

NOTE:  
WHERE THERE IS LESS  
THAN 10m TO ROAD  
RESERVE BOUNDARY,  
CLEARING SHALL BE TO  
BOUNDARY ONLY

THIS DRAWING IS AN AMENDMENT OF THE  
APPROVED DRAWING.

No.	DATE	DESCRIPTION	AUTHORISED
1	02/05/13	AMENDED MAXIMUM INTERVENTION LEVEL FROM 100mm TO 300mm.	Edmunds
AMENDMENTS			

PLANNING AND TECHNICAL SERVICES DIRECTORATE  
STRUCTURES ENGINEERING

Don Aitken Centre  
Waterloo Crescent, East Perth WA 6004

Telephone (08) 9323 4111 Fax (08) 9323 4136

APPROVED

DESIGNED  
VERIFIED DAVID WILSON 18/6/12  
DRAWN M. GUEVARRA JUNE 2012  
CHECKED W.GILES  
DATUM  
FILE NO.

VEGETATION CLEARANCE ENVELOPES  
FOR BRIDGES



DRAWING NUMBER  
1230-1666-1

AMEND.  
Page | 30

SCALE  
A2



Page intentionally left blank



**Main Roads WA Report:  
Development of a Network Level Bridge  
Criticality and Risk Assessment Model  
by Neil Telfer**

# Development of a Network Level Bridge Criticality and Risk Assessment Model

Neil Telfer, July 2018

## 1. Background

Main Roads are developing an Asset Management System (AMS) aligned with the ISO55000 Series of standards. As part of the system development Main Roads have produced an Asset Management Policy (D17#1030856) with the following principles included;

- Apply a risk-based whole of lifecycle approach in the acquisition, operation, maintenance and disposal of our assets.
- Prioritise our investments based on appropriate consideration of customer outcomes, cost and risk.

To assist in delivering on these principles, a Network Level Criticality and Risk Assessment for Bridges is required.

## 2. Scope

### 2.1. Stage 1

A Network Level Criticality and Risk Assessment for Bridges should be a 'low definition' assessment based on explicit Bridge Data held in corporate asset data systems and is Stage 1 in progressing on to developing further Multi Criteria Assessment for the prioritisation of Maintenance and Capital projects.

### 2.2. Stakeholder Review

Review feedback and acceptance of the Criticality and Risk model by the Regional Stakeholders.

### 2.3. Stage 2

Stage 2 will use Criticality and Risk Assessment ratings from Stage 1 with additional criteria used in existing manual MS Excel based MCA tools as per the Bridge Management Manual, to produce automated prioritisation for Maintenance and Capital (renewal and improvement) Programs.

### 2.4. Stakeholder Review

Review feedback and acceptance of the Maintenance and Capital MCA model by the Regional Stakeholders.

### 2.5. Interim Implementation

The scope of Stage 1 and Stage 2 is therefore to identify existing explicit data sources from corporate data systems that can be used to perform a 'low definition' Risk Assessment that broadly conforms to Main Roads (and Transport Portfolio) Risk Management Process.

The scope includes the production of a 'proof of concept' data model constructed using Microsoft Power BI. Power BI reports are used to display the Criticality and Risk Assessment criteria ratings/scores. The Power BI Dashboard shall be connected to the BMS SQL Server and run on a scheduled refresh.

### 2.6. Final Implementation

On approval of the concept, the assessment will be embedded into the Bridge Management System (BMS) where the full Risk Management process will be made available for Asset

Managers to transparently apply and record risk treatment and mitigation measures in accordance with the risk treatment hierarchy and Main Roads Risk Management Process. This will allow transparent reporting and communication of the management of bridge risks at a local regional and state level.


The final implementation is identified and funding is available in the Bridge Management System Business Case Phase 2 Development Business case at D17#462340.

### 3. Purpose

A 'low definition' assessment is one that uses broadly available explicit data on network demand and bridge configuration, performance and condition. A risk assessment framework can be developed using accepted bridge inspection, condition and performance data as an evaluation of likelihood of risk and using network demand and use as a measure of the consequence of any bridge related hazard occurring. The 'low definition' risk assessment should identify the 'critical bridges' on Main Roads network for further 'higher definition' risk assessment and management. The 'low definition' risk assessment is intended to focus attention and effort rather than be a comprehensive Risk Assessment.

'Explicit Data' refers to Main Roads corporate data with processes used in the control of that data are often subject to management and audit under our Integrated Management System (IMS) making it reliable and well managed. Main Roads has a wealth of Asset inventory, condition, demand and performance data most of which is held in IRIS. Further corporate data is held in Systems such as Oracle Finance, BEARS, and Bridge Management System (BMS) etc. Using 'explicit data' removes the subjective nature of risk assessment, improves repeatability and allows the Network Level Risk Assessment for Bridges to be systemised and embedded into the corporate BMS. Flow on tools such as Risk Management Measures and Multi Criteria Analysis (MCA) can be developed to assist in prioritisation for Route Planning and Investment Planning.

Main Roads and the WA Transport Portfolio base their Risk Assessment Processes on ISO31000. The Risk Process is shown below.



#### 4. Context of Bridge Criticality

Bridge Criticality is a measure of how important the bridge is in maintaining a high performing road network. Closures or restrictions to these bridges would have considerable **Consequence** on the performance of the Network.

#### 5. Context of Bridge Related Risks

For a Network Level Risk Assessment for Bridges it is important to set the context for the Risk Assessment. The context for this low definition assessment is;

*“The potential for Bridge related issues to effect Main Roads ability to provide a safe, reliable and sustainable road based transport system.”*

Under this context the criteria identified for risk assessment are those which may impact upon;

- Safety:
  - Age
  - Bridge Type
  - Inspection status
  - Condition
  - Barrier containment
- Reliability:
  - Level of service
    - strength,
    - width,
  - Currency of Load Rating
  - ~~Vertical Clearance~~
- Sustainability:
  - Planned Past and Future Maintenance
  - Asset Consumption Ratio

Under this context, it is important to understand that a bridge with a resulting Network Level High Risk rating does not mean the bridge is at risk of failure or collapse. Rather that the bridge is a Critical Asset to the delivery of Main Roads services and warrants a high standard of management due to its potential (risk) to adversely affect service delivery and customer satisfaction.

## 6. Measures of Bridge Criticality (consequence) to Network Operation

### 6.1. Commonwealth Class

Main Roads has varying responsibility for management of all bridges including on Local Authority Roads and bridges belonging to other Government Departments and Government Trading Enterprises (GTE), such as DBCA and Water Corporation.

6.1 Commonwealth Class	Commonwealth Class Score
National Highway	5
State Road	4
Local Road	3

### 6.2. Functional Class

The consequence to service delivery of any bridge risk materialising is broadly related to the number of customers who could be affected. While vehicle count data is not available for each and every bridge on the network, the functional class is dependent on the volume and type of traffic using the bridge. The functional class of the road being carried and, if applicable, the road being crossed are important for the bridge risk assessment.

The Functional Class of the road being supported is available in IRIS and BMS.

6.2 Functional Class	Functional Class Score
1 Inter Capital City Highway	5
2 Rural Highway	4
3 Main Road	3
4 Rural Local Road	2
5 Rural Special Purpose Road	1
6 Urban Highway	5
7 Significant Urban Local Road	4
8 Urban Local Road	3
9 Urban Special Purpose Road	1

### 6.3. Link Subcategory

As with Functional Class above, the Link Subcategory of the road being carried and any road being crossed is important for the risk assessment.

The Link Subcategory of the road being supported is available in IRIS.

6.3 Link Subcategory	Link Subcategory Score
MI	5
MFF	5
AW+	4
AW	4
BW+	3
BW	3
CW	2
DW	1

#### 6.4. Crossing Type

The type of obstacle crossed is relevant to the possible consequences of a lack of containment or structural failure in terms of number of people affected. A structural failure, bridge strike or barrier penetration affecting train or road travel below a bridge would carry a higher consequence than an incident over water or a dry river bed when considering the risk context of network operation and service delivery across the transport portfolio. The risk to road and rail user safety would be greater due to vehicle penetration of a barrier over road/rail or structural failure than over water or a dry river bed as the latter would most likely involve fewer vehicles.

The Crossing Type is captured in the IRIS Bridge Inventory and in BMS.

6.4 Crossing Type	Crossing Type Score
Over Road and Rail	5
Over Rail	5
Over Road and Water	4
Over Road	4
Over Water	3
Under Road	3
Ramp	3
Pedestrian Underpass	2
Stock Underpass	1
(blank)	1

#### 6.5. Primary Function

The primary function data set for a bridge is the purpose of the structure. Structures carrying a road over other roads, rail or water are more critical in terms of maintaining reliable transport than pedestrian bridges or stock underpasses etc.

6.5 Primary Function	Primary Function Score
Road and Rail Bridge	5
Road Tunnel	5
Road Bridge	4
Rail Bridge	4
Rail Tunnel	4
Over Road	3
Pedestrian Bridge	2
(blank)	1

### 6.6. Deck Area

Bridge Deck Area can be an indication of the consequence of any bridge related risk occurring as it is generally accepted that the larger a structure, the more complex and time consuming any intervention to reinstate service would be.

The Deck Area is captured in the IRIS Bridge Inventory and in BMS.

6.6 Deck Area	Deck Area Score
>2000m <sup>2</sup>	5
1000m <sup>2</sup> to 2000m <sup>2</sup>	4
500m <sup>2</sup> to 1000m <sup>2</sup>	3
200m <sup>2</sup> to 500m <sup>2</sup>	2
<200m <sup>2</sup>	1
	1

### 6.7. Current Replacement Cost

The Current Replacement Cost (CRC) is the cost to replace a damaged or destroyed asset. While the context of the Criticality Assessment is impact on network service delivery, the replacement cost of an asset is useful explicit data relating to financial consequence. As with bridge size, the replacement cost could also be an indicator of the financial cost of repair or rehabilitation and the duration it is out of service after a bridge risk has occurred.

Subsequent 'higher definition' risk assessment or MCA can refine the financial consequence through calculation of Road User Cost (RUC) or Net Present Value (NPV) assessment of investment options.

The CRC is maintained in the Oracle Asset Register which is managed to AASB requirements.

6.7 Current Replacement Cost	Current Replacement Cost Score
Current Replacement Cost >\$10M	5
Current Replacement Cost \$5M to \$10M	4
Current Replacement Cost \$1M to \$5M	3
Current Replacement Cost \$500,000 to \$1M	2
Current Replacement Cost < \$0.5M	1



## 7. Measures of Bridge Characteristics Indicating Likelihood of Risk to Network Operation

The following criteria contribute the 'likelihood' of bridge configuration or condition to the risk assessment process.

### 7.1. Age

The likelihood of an issue occurring with a bridge can be linked to age due to deterioration over time and the potential for design standards to be superseded.

Main Roads maintains good bridge age data within IRIS and BMS.

7.1 Age	Age Score
Over 80 Years Old	5
60-80 Years Old	4
40 to 60 Years old	3
10 to 40 Years Old	2
Less than 10 Years Old	1
Not Known	3

### 7.2. Bridge Type

The Bridge Type can be used as a measure of criticality when the rate of deterioration, design approach, durability and robustness of the structure are considered.

7.2 Bridge Type	Bridge Type Score
Timber	5
Timber Hybrid	5
Steel/Concrete Composite	4
Steel	4
Prestressed Concrete	4
Reinforced Concrete	3
Tunnel	3
Sign Gantry	2
Culvert	1

### 7.3. Inspection Status

Bridge inspection is a risk management measure used to ensure that bridge condition is in line with design durability standards and is on track to realise its expected useful life. Bridges that have not, or cannot be inspected in line with Main Roads scheduled inspection regime may present an increased likelihood of an (unknown) issue affecting network performance.

Main Roads records inspection cycles within IRIS. A BMS Inspection Planning and Management module is also under development.

7.3 Inspection Status	Inspection Status Score
Structure never Inspected	5
Full Detailed Inspection >24mths overdue	4
Full Detailed Inspection 12-24mths overdue	3
Full Detailed Inspection 0-12mths overdue	2
Full Detailed Inspection Current (All Elements)	1



#### 7.4. Condition

Bridges in poor condition would generally be expected to present a greater likelihood of having an issue that would affect network performance.

Main Roads also records Condition State (CS) information for bridges at individual component level. This is available for most components of timber bridges and all components of non-timber bridges.

Where the CS of a bridge component is poor a Work Item (WI) is assigned during the inspection process. WI's are created as part of the inspection process to alert Asset Managers to work that may be required. WI's are given a priority rating and Asset Managers can review these WI and elect to down grade priority, delete the Work Item or escalate the Work Item to a Work Stage and include in a planned maintenance or capital project in the Program Management module of BMS.

The condition criteria considers the severity of the defect and the importance of the component group to structural stability. The scores are based on a matrix of CS and Component Group.

7.4 Condition	Any Component in Condition State			
Component Group	CS4	CS3	CS2	CS1
CG1	5	5	3	1
CG2	4	3	2	1
CG3	3	2	1	1
Bridge/Other	2	1	1	1

Asset Managers are encouraged to practice good housekeeping with regard to WI's in BMS to ensure the Risk Assessment is accurate.

### 7.5. Containment

Bridge Barriers provide containment of errant vehicles both on the approaches to the bridge and while on the bridge itself. Main Roads bridge inventory captures the barrier types on approaches and on the bridge, it also collects the length of barrier off the bridge. \*\*Refer Section 17 of SE Design Manual\*\*

7.5 Barrier Containment	BC Score
None	5
W Beam	4
Thriebeam	3
RHS Rails	2
Tric-Bloc Concrete Barrier	1
Other Concrete Profiles	1
Reinforced Concrete Barrier (Type F)	1
Constant Slope Concrete Barrier	1
(blank)	4

### 7.6. Strength and Load Management

Main Roads maintains Investigatory Criteria (IC) and Key Performance Measures on Bridge Strength using the Actual and Required Rating Indexes (ARI/RRI). Data on Load Posting and Propping of understrength bridges is also available. These are held in IRIS and BMS.

7.6 Strength and Load Management	Score
Load Posted	5
Propped	5
Fails Strength IC – ARI<RRI	5
Pass Strength IC – ARI>=RRI	1

### 7.7. Load Rating Status

Bridges are Load Rated to assess their capability to carry heavy or permit loads on an as needs basis. Older load ratings can be performed to older codes or older vehicle configurations. The older the load rating the more likely codes or usage requirements have been superseded and should be revisited.

7.7 Load Rating Status	Score
Structure never Load Rated	5
Load Rating >120 mths old	4
Load Rating 60 to 120 mths old	3
Load Rating 24 to 60 mths old	2
Load Rating <24 mths old	1
Not Known	4

### 7.8. Width

Main Roads maintains Investigatory Criteria (IC) and Key Performance Measures on Bridge width. This is held in IRIS.

7.5 Bridge Width	Score
Fails Width IC	5
Bridge Width between kerbs <5.0m	4
Meets Width IC	1

### 7.9. Vertical Clearance

Clearance is Maximum and Minimum Headroom are collected as part of the as constructed and bridge inspection processes.

Where bridges have reduced or close clearances over road, HVS maintains a list of bridges which have limiting clearance for selected routes based on specific headroom over lanes.

This data is held at;

<https://www.mainroads.wa.gov.au/Documents/Bridge%20Heights%20For%20MRWA%20Website%20-%20CURRENT%20-%20July%202018.RCN-D18%5E23581592.PDF>

Headroom clearances for bridges over roads relates the likelihood of bridge strikes by vehicles and the restriction to reliable and unimpeded movement of vehicles.

7.9 Vertical Clearance	5.7 Vertical Clearance Score
Low Height managed by HVS	5
No Clearance Issues	1

**\*\*NOTE: Vertical Clearance is currently excluded from the Model.\*\***

### 7.10. Sustainability of Investment

Sustainability of investment is also included here as it is intended that the results of the financial risk assessment will flow on to and guide whether recurrent or capital investment MCA Tools should be used. This measure takes the ratio of Planned Maintenance and Net Book Value to test the logic of expending a large amount of money maintaining a low value asset.

7.10 Sustainability of Investment	Sustainability Score
Planned maintenance >100% of Net Book Value	5
Planned maintenance 75-100% of Net Book Value	4
Planned maintenance 50-75% of Net Book Value	3
Planned maintenance <50% of Net Book Value	2
No Planned maintenance	1

#### 7.10.1. Planned Maintenance – Past and Future

The BMS records all planned past maintenance for each bridge since the BMS inception, up to and occasional greater than 5 years ago. BMS also captured future maintenance over a 10 Year Plan. Past and future expenditure provides an indication of the likelihood of growing unsustainable maintenance expenditure.

### 7.10.2. Net Book Value

Net Book Value can be sourced from the Oracle Asset Register which is managed and audited against Australian Accounting Standards Board (AASB) requirements. The Net Book Value for each bridge is an indicator of the likelihood of an investment of recurrent expenditure achieving sustained economic benefit.

### 7.11. Asset Consumption Ratio

The Asset Consumption Ratio (ACR) is the Net Book Value divided by the Current Replacement Cost of the asset. A low ACR indicates that the asset is coming close to being fully consumed financially and has low remaining value and theoretically, low remaining life.

7.11 Asset Consumption Ratio	Asset Consumption Ratio Score
Asset Consumption Ratio <0.2	5
Asset Consumption Ratio 0.2 to 0.4	4
Asset Consumption Ratio 0.4 to 0.6	3
Asset Consumption Ratio 0.6 to 0.8	2
Asset Consumption Ratio 0.8 to 1	1
No Constructed Date	3

### 7.12. Deferred Maintenance

Consistent deferral of Maintenance can result in a greater likelihood of defects becoming more serious with an increase in condition state and escalating cost. The longer maintenance has been deferred the greater the likelihood of a risk eventuating.

7.12 Deferred Needs	7.12 Deferred Needs	Deferred Needs Score
Deferred	Previously identified Needs have been deferred	5
Not Deferred	Identified Needs have not been deferred	4

### 7.13. Work Item Density

The number of Specific Work Items and their location on the structure, expressed in terms of their Component Group, shows the quantum of maintenance work is necessary on the structure. Along with 7.4 Condition, this is an indicator of how likely the bridge requires maintenance.

7.13 Work Item Density	Number of Specific Work Items				
Component Group	>10	5-10	3-5	<3	0
CG1	5	4	3	2	1
CG2	4	3	2	2	1
CG3	3	2	2	1	1
Bridge/Other	2	1	1	1	1

#### 7.14. Potential Future Measures of Criticality and Risk

The measures below could potentially be added to the model in the future.

##### 7.14.1. Key Freight Routes

The movement of Freight by Road is an important service delivery for Main Roads. A consequence criteria for Key Freight Routes is included in the low definition binary (yes/no) criteria for risk scoring.

##### 7.14.2. Vertical Clearance over Rail

The Public Transport Authority (PTA) publishes clearance envelopes for structures over rail. The headroom measurement captured in IRIS can be used to assess the risk related to close clearances over rail. As the height of rail vehicles is easier to manage than the height of road vehicles, the risk scores will be lower than that for clearances over road.

##### 7.14.3. Low Headroom for Inspection Safety

Minimum headroom when 1.2m or less can relate the likelihood of incomplete bridge inspections due to health and safety issues of performing inspections. Currently a risk based process for identifying bridges that are too low to inspect is being developed, this will allow the majority of bridges with minimum headroom of 1.2m or less to be inspected as required. The scoring of this risk will therefore be less onerous than other criteria but will be included in assessing risk.

##### 7.14.4. Horizontal Clearance

At present data on horizontal clearances for assessing the risk of bridge supports within clear zones, or weak bridge supports susceptible to failure on being struck resulting in bridge collapse is not available. Risk to network service for horizontal clearances is therefore not included in the assessment until explicit bridge inventory data is available.

##### 7.14.5. Planned Capital Works

The BMS records planned capital works over a 10 Year Plan. Where a bridge has a low Net Book Value and No future Capital Works are planned there is a risk to diminishing capital value of structures and therefore the Agencies Asset Valuation. There is also a risk of building future financial shock from an accumulating backlog of bridge renewals.

##### 7.14.6. Barrier End Treatment and Length off Bridge.

The length of barrier and barrier end treatment type is captured in IRIS and refreshed using As constructed drawings and during Level 2 bridge inspections. The length of barrier and end treatment types are important in providing both safe, crashworthy end terminals and run-off containment for the hazard being crossed.

##### 7.14.7. Fire Risk

Fire risk assessment is currently under development and will be linked to the Office of Bushfire Risk Management (OBRM) Bushfire Risk Management System (BRiMS). At present Main Roads does not keep asset data on bushfire risk for bridges so an additional bridge inventory field will need to be included in IRIS for fire risk once the process of evaluating the risk using BRiMS is completed.

## 8. Criticality Scoring

The calculation of the final Criticality Score is by simple averaging as shown for a variety of scores against each criteria in the table below and provides a Criticality Score between 1 and 5.

Network			Bridge			Finance	Bridge Criticality (Ave.)
6.1 Commonwealth Class	6.2 Functional Class	6.3 Link Subcategory	6.4 Crossing Type	6.5 Primary Function	6.6 Deck Area	6.7 Current Replacement Cost	
3	1	1	1	1	1	1	1.29
3	1	1	1	1	1	5	1.86
3	1	1	5	5	5	5	3.57
5	5	5	5	5	5	5	5.00
3	1	1	5	5	5	1	3.00
5	5	5	1	1	1	1	2.71
5	5	5	5	5	5	1	4.43
4	4	5	1	1	3	5	3.29
4	4	5	1	1	1	5	3.00
4	4	5	1	2	2	5	3.29



## 9. Risk Ratings

Risk Ratings are derived from the Risk Likelihood Score multiplied by the Criticality Score (Consequence)

Safety						
7.1 Age	x	Bridge Criticality Score	=	X /25		
7.2 Bridge Type	x	Bridge Criticality Score	=	X /25		
7.3 Inspection Status	x	Bridge Criticality Score	=	X /25		
7.4 Condition		Bridge Criticality Score	=	X /25		
7.5 Barrier Containment	x	Bridge Criticality Score	=	X /25		
				AVE	= XX/25 Safety Risk Score	
Reliability						
7.6 Strength and Load Management	x	Bridge Criticality Score	=	X /25		
7.7 Load Rating Status	x	Bridge Criticality Score	=	X /25		
7.8 Width	x	Bridge Criticality Score	=	X /25		
<del>7.9 Vertical Clearance</del>	<del>x</del>	<del>Bridge Criticality Score</del>	<del>=</del>	<del>X /25</del>		
				MAX	= XX/25 Reliability Risk Score	
Sustainability						
7.10 Planned Maintenance (Past and Future)	x	Bridge Criticality Score	=	X /25		
7.11 Asset Consumption Ratio	x	Bridge Criticality Score	=	X /25		
				MAX	= XX/25 Sustainability Risk Score	
						Safety Risk Score Reliability Risk Score Sustainability Risk Score
					Total Risk Score = MAX(Safety,Reliability,Sustainability)	

## 10. Capital Investment Multi Criteria Analysis (Capital MCA)

The Capital Investment MCA uses the following Risk Scores to determine a Priority Score and Risk Rating for bridges and indicates where LoS or Investigatory Criteria (IC) are not met.

Deterioration								
	7.1 Age	x	Bridge Criticality Score	=	X /25			
	7.4 Condition	x	Bridge Criticality Score	=	X /25			
	7.13 Work Item Density	x	Bridge Criticality Score	=	X /25			
					AVE /3	=	XX Deterioration MCA Score	
Level of Service (LoS)								
	7.6 Strength and Load Management	x	Bridge Criticality Score	=	X /25			
	7.8 Bridge Width	x	Bridge Criticality Score	=	X /25			
					MAX	=	XX/25 LoS MCA Score	
Cost (Sustainability of Investment)								
	7.10 Sustainability of Investment	x	Bridge Criticality Score	=	X /25			
	7.11 Asset Consumption Ratio	x	Bridge Criticality Score	=	X /25			
					AVE	=	XX/25 Cost MCA Score	
							Deterioration MCA Score	
							LoS MCA Score	
							Cost MCA Score	
							Capital MCA Score = MAX(Deterioration,LoS,Cost)	



## 11. Maintenance Investment Multi Criteria Analysis (Maintenance MCA)

Maintenance MCA									
	7.4 Condition	x	Bridge Criticality Score	=	X /25				
	7.12 Deferred Maintenance	x	Bridge Criticality Score	=	X /25				
	7.13 Work Item Density	x	Bridge Criticality Score	=	X /25				
					<b>AVE</b>	<b>=</b>	<b>XX/25 Maintenance MCA Score</b>		

## 12. Bridge Inspection Prioritisation Multi Criteria Analysis (Inspection MCA)

The Bridge Inspection MCA determines a Risk Rating for all bridges.


Bridge Inspection Backlog MCA									
	7.1 Age	x	Bridge Criticality Score	=	X /25				
	7.3 Inspection Status	x	Bridge Criticality Score	=	X /25				
	7.4 Condition	x	Bridge Criticality Score	=	X /25				
	7.13 Work Item Density	x	Bridge Criticality Score	=	X /25				
	7.6 Strength and Load Management	x	Bridge Criticality Score	=	X /25				
						=	MAX Inspection Backlog Risk Score		

### 13. Bridge Improvement MCA

The Bridge Improvement MCA determines a risk rating based on whether the bridge meets Level of Service criteria and is relatively new and in good condition.

Level of Service (LoS)							
	7.6 Strength and Load Management	=	X /5				
	7.8 Bridge Width	=	X /5				
			MAX	=	XX/25	LoS MCA Score	
Deterioration							
	7.1 Age	=	X /5				
	7.4 Condition	=	X /5				
	7.13 Work Item Density	=	X /5				
			AVE	=	XX	Deterioration MCA Score	
Improvement MCA Score = (MAX LoS / AVE Deterioration) * Bridge Criticality Score							

## 14. Power BI Model Diagram



## 15. Regional Review of Risk Assessment Process

A process is required that allows the Regional Asset Manager Structures (AMS) to apply in depth regional knowledge and of the network and bridge Levels of Service (LoS).

This is an essential part of the process as the 'low definition' explicit data based process can only derive Risk Ratings from corporately supported data. A Regional Review process allows the knowledge and capability of experienced staff to improve the system generated Risk Assessment.

It is also important to include a review facility to ensure that the Regional AMS revised risk ratings are reasonable and based on sound justification. A central review of revised risk ratings is required by the Structures Asset Strategy Manager (SASM) in Network Management Branch.

Further, the Regional AMS are best placed to identify the appropriate risk treatment measures for identified risks using the hierarchy of control measures. Once risk ratings are reviewed and agreed, mitigation measures are applied and the Residual Risk calculated and agreed.


## 16. Risk Treatment, Residual Risk Evaluation and Risk Communication.

It is then essential that the actions to mitigate risk be they a build or non-build solution, are communicated, reviewed and endorsed at the appropriate level within the Agency.

Build solutions for risk mitigation result in the generation of Maintenance, Improvement and Renewal and Refurbishment Programs. These are collated in Network Management Branch and in liaison with Budget and Programming and Investment Planning, programs are submitted through AMSC, IPSC and MRIC.

Non-build solutions such as load posting, warning signage, temporary propping, bridge monitoring etc. are lower in the risk control hierarchy and require communication and regular review of effectiveness. Where these measures are in place and the Residual risk is still High or Very High, these will be reviewed and the AMSC will receive regular updates with the highest Residual Risk bridges being reported on to CorpEx.

The Flow chart below shows the process and activities associated with Regional Review and Risk Communication.





Step	(1) Establish the Context	BMS Structures Criticality, Risk and Prioritisation Process											
Overview	This step is the planning phase of the risk assessment. The 'Relevant Officer' should ensure the subject of the risk assessment is defined and placed into context and the format of the risk assessment and level of effort should be defined.	The context of the Risk Assessment is the identification and prioritization of bridge asset management activities during the operational phase. This includes prioritization of maintenance, improvement, renewal and refurbishment and planning of delivery of bridge inspection backlog.											
Expected Outcome	The objectives, scope and parameters of the risk assessment are documented.	Identify Critical Assets (Highest Consequence to network operations) Identify Bridge Risk against key categories; <ul style="list-style-type: none"><li>• Safety</li><li>• Reliability</li><li>• Sustainability</li></ul> Use selected risk scores and ratings to prioritise and plan; <ul style="list-style-type: none"><li>• Bridge Maintenance works</li><li>• Bridge Capital works</li><li>• Bridge Inspections</li></ul>											
Procedure	<div><div>1. There are different ways in which the risk assessment can be carried out – workshops, team meetings, interviews, surveys or a desktop exercise. Consider which one of these options would be most appropriate in the circumstances to adopt.</div><div>2. Identify the participants for the risk assessment. Ideally the participants in the risk assessment have competencies that will allow for effective risk identification and assessment.</div><div>3. Define objectives of the risk assessment – purpose and use of the results.</div><div>4. Define the focus of the risk assessment – This step seeks to answer the question – what are we assessing the risks of – an initiative, a process, a contract, a supplier etc.</div><div>5. Determine the resources required to perform the risk assessment - people, time and information.</div><div>6. Identify any internal relationships and their impact on the risk assessment – is the subject of this risk assessment related to another project, product, strategy or initiative at main Roads. If so, what is the impact of it on the risk assessment?</div><div>7. It is important to understand the organisation and the external environment and determine their impact on the risk assessment. The table below outlines some of the internal and external factors to consider.</div><table><tr><td rowspan="4">External factors</td><td>Business, social, regulatory, cultural, competitive, financial and political environments</td></tr><tr><td>The Organisation's strengths, weaknesses, opportunities and threats</td></tr><tr><td>External stakeholders and their perceptions</td></tr><tr><td>Key business drivers</td></tr><tr><td rowspan="5">Internal factors</td><td>The culture</td></tr><tr><td>Internal stakeholders</td></tr><tr><td>Organisational structure</td></tr><tr><td>Capabilities in terms of resources</td></tr><tr><td>Goals, objectives and strategies to achieve them</td></tr></table><div>8. Document the process to the extent required.</div></div>	External factors	Business, social, regulatory, cultural, competitive, financial and political environments	The Organisation's strengths, weaknesses, opportunities and threats	External stakeholders and their perceptions	Key business drivers	Internal factors	The culture	Internal stakeholders	Organisational structure	Capabilities in terms of resources	Goals, objectives and strategies to achieve them	<div><div>1. Initial risk assessment to be carried out on Asset data held in corporate systems</div><div>2. Key stakeholders engaged in the Bridge risk assessment process are;<ul style="list-style-type: none"><li>• Structures Engineering</li><li>• Budget and Programming/Investment Planning</li><li>• Regional Asset Managers</li><li>• Route Planning Team</li><li>• Crisis and Emergency Management</li><li>• DFES Emergency Management</li><li>• Road Network Definition</li><li>• Legal Services</li></ul></div><div>3. Results are used to prioritise asset management activities for bridges by regional Asset Manager Structures and to communicate forward program requirements to Budget &amp; Programming and Investment Planning</div><div>4. We are assessing the risk of bridge deterioration and LoS gaps on the safe, reliable and sustainable operation of our network</div><div>5. Main resources are;<ul style="list-style-type: none"><li>• Asset Management System Analyst, NMB</li><li>• Regional AMS</li><li>• BMS Development Project Manager</li></ul></div><div>6. Related to development of the Asset Management System and AM Policy which requires a Risk based approach to management of assets.</div><div>7. As per table opposite</div><div>8. This document demonstrates alignment with the risk process.</div></div>
External factors	Business, social, regulatory, cultural, competitive, financial and political environments												
	The Organisation's strengths, weaknesses, opportunities and threats												
	External stakeholders and their perceptions												
	Key business drivers												
Internal factors	The culture												
	Internal stakeholders												
	Organisational structure												
	Capabilities in terms of resources												
	Goals, objectives and strategies to achieve them												
TIP: <div><div>1. Following the guidance in this document will assist you in facilitating a risk assessment or a risk workshop. Alternatively, the CUA for Financial services provides risk services including risk workshop facilitation.</div><div>2. Use this step to set the context and scene for the risk assessment.</div></div>													



Step	(2) Risk Identification	BMS Structures Criticality, Risk and Prioritisation Process
<b>Overview</b>	<p>Risk identification involves describing the source and causes of a risk. Risk may originate from all areas of the business e.g. business units, projects, sites, support services and corporate.</p> <p>During this step, all risks that may impact on the achievement of the objectives should be identified. Identified risks should be:</p> <ul style="list-style-type: none"> <li>• Relevant to the subject matter;</li> <li>• Appropriate, given the context; and</li> <li>• Useful for decision-making purposes.</li> </ul> <p>For example: the risk of a natural disaster may be possible, but not relevant, appropriate or useful when assessing the risk of introducing a new product.</p>	<p>Risk Source is the ownership and responsibility for safe, reliable and sustainable asset management of bridge structures to facilitate road based transport systems.</p> <p>Factors affecting Bridge Risk (Consequence and Likelihood) are Identified and detailed in D18#932044. A sample are listed below;</p> <ul style="list-style-type: none"> <li>• Bridge Age</li> <li>• Bridge Condition</li> <li>• Bridge Value</li> <li>• History of expenditure</li> <li>• Strength</li> <li>• Width</li> </ul>
<b>Expected Outcome</b>	<ol style="list-style-type: none"> <li>1. Documentation of risks.</li> <li>2. Progress towards completion of a Risk Register – see Appendix 2 for a template.</li> </ol>	<ol style="list-style-type: none"> <li>1. D18#932044 – Development of a Network Level Bridge Criticality and Risk Assessment Framework</li> <li>2. Criticality (Consequence) Criteria</li> <li>3. Risk Likelihood Criteria</li> <li>4. Proof of concept Risk Register set up in Power BI - <a href="https://app.powerbi.com/groups/me/dashboards/27a815e1-27f5-415b-b686-88469159f3e4">https://app.powerbi.com/groups/me/dashboards/27a815e1-27f5-415b-b686-88469159f3e4</a></li> <li>5. Final Bridge Risk Register will be Managed and Stored within the corporate Bridge Management System (BMS)</li> </ol>
<b>Procedure</b>	<ol style="list-style-type: none"> <li>1. Identify the objectives of the project, initiative, process (subject of the risk assessment). There are different ways of identifying the risks – judgements based on experience and records, checklists, flow charts, brainstorming, scenario analysis, system analysis and so on.</li> <li>2. Consider holistically what events may impact on the ability to achieve these objectives. Consider the events across a range of categories including: <ul style="list-style-type: none"> <li>- Customer and Market</li> <li>- Finance and Procurement</li> <li>- Fraud and Corruption</li> <li>- Innovation, Quality and Improvement</li> <li>- People</li> <li>- Reputation</li> <li>- Safety</li> <li>- Success and Sustainability</li> <li>- Strategy and Planning</li> <li>- Service Delivery</li> <li>- Environmental</li> </ul> </li> <li>3. Review the key risk areas to determine potential sources of risk, relevant to the objectives.</li> <li>4. Document the outcomes in the Risk Register.</li> </ol>	<ol style="list-style-type: none"> <li>1. The objective is to apply the principles of risk management to identify and prioritise bridge asset management activities. System and Data analysis is used to undertake initial risk analysis with risk evaluation carried out by regional AMS who have more detailed understanding of the network and bridge needs than can be captured in bridge data systems.</li> <li>2. The following categories are considered based on the data available from asset management systems; <ul style="list-style-type: none"> <li>- Customer and Market</li> <li>- Finance (Asset Valuation Register)</li> <li>- Reputation</li> <li>- Safety</li> <li>- Success and Sustainability</li> <li>- Strategy and Planning</li> </ul> </li> <li>3. As per D18#932044</li> <li>4. As above</li> </ol>
<b>TIP:</b> <ol style="list-style-type: none"> <li>1. A risk can be a positive or negative impact on the objective - consider holistically positive or negative events that can influence the objectives.</li> <li>2. Where possible conduct some preliminary research on the potential risks. This will help better inform the</li> <li>3. Consult relevant stakeholders to gain a better understanding and perspective on potential risks</li> </ol>		
Step	(3) Risk Analysis	BMS Structures Criticality, Risk and Prioritisation Process
<b>Overview</b>	<p>Risk analysis involves determining the causes, consequences, likelihood and impact of each identified risk. This allows each risk to be allocated a risk rating, which influences treatment planning decisions.</p> <p>The results of the risk analysis inform resource allocation so that risks of the highest potential impact are prioritised.</p>	<p>As per D18#932044 scores of 1 to 5 are allocated to the risk consequence and likelihood criteria. The bridge data records in IRIS, BMS and the Asset Valuation register are used to determine the initial risk score.</p> <p>The results of the analysis ensure that the Regional AMS are Evaluating the highest priority bridge risks and planning accordingly.</p> <p>The Transport portfolio Risk Reference table is replicated in the BMS so that scores and ratings are allocated to Portfolio requirements. The Risk Reference Table can be amended by the BMS Administrator in response to any changes in the matrix and risk appetite.</p>



	It is essential that the Transport Portfolio Risk Reference table is provided in Appendix 1 are used to determine the risk ratings.	
Expected outcome	<ol style="list-style-type: none"> <li>1. Risk rating allocated for each risk.</li> <li>2. Further completion of the Risk Register.</li> </ol>	<ol style="list-style-type: none"> <li>1. Proof of concept Risk Register set up in Power BI - <a href="https://app.powerbi.com/groups/me/dashboards/27a815e1-27f5-415b-b686-88469159f3e4">https://app.powerbi.com/groups/me/dashboards/27a815e1-27f5-415b-b686-88469159f3e4</a></li> </ol>
Procedure	<ol style="list-style-type: none"> <li>1. Identify possible causes of the risk. Also consider the underlying factors that impact the risk and likely treatment options.</li> <li>2. Identify the possible consequence of the risk.</li> <li>3. Identify <u>existing</u> controls including processes, devices or practices that act to minimise or enhance the risks.</li> <li>4. Determine the potential consequences of the risk occurring.</li> <li>5. Determine the likelihood of the risk occurring.</li> <li>6. Combine the impact and likelihood ratings to establish the overall risk rating.</li> <li>7. You have the option of applying a Residual Risk Rating or an Inherent Risk Rating.</li> <li>8. Document the results in the Risk Register.</li> </ol>	<ol style="list-style-type: none"> <li>1. As per D18#932044</li> <li>2. " " "</li> <li>3. " " "</li> <li>4. " " "</li> <li>5. " " "</li> <li>6. " " "</li> <li>7. Residual Risk ratings are not calculated at this step</li> <li>8. As per Power BI PoC dashboard</li> </ol>
<b>TIP:</b> <ol style="list-style-type: none"> <li>1. Often this step is completed in conjunction with Step 2 – Risk Identification.</li> </ol>		
<b>Step</b>	<b>(4) Risk Evaluation</b>	<b>BMS Structures Criticality, Risk and Prioritisation Process</b>
Overview	The purpose of risk evaluation is to assist in making decisions, based on the outcomes of the risk analysis, about which risks need treatment and to inform prioritisation decisions regarding the implementation of treatment plans.	Initial risk analysis and evaluation is performed by the data model as described in D18#932044. During the risk evaluation phase the Regional Asset Manager refines the risk evaluation and records justification in the corporate Records Manager system for any changes to the initial risk evaluation. The regional AMS can accept the 'System Risk Evaluation' or modify based on demonstrated regional information aligned to the defined likelihood and consequence criteria.
Expected Outcome	<ol style="list-style-type: none"> <li>1. Plot levels of risk on the risks matrix and determine risks that need treatment and priority regarding implementation of treatment.</li> <li>2. Further completion of the relevant Risk Register</li> </ol>	<ol style="list-style-type: none"> <li>1. The risk evaluation process progresses from Initial data based evaluation, to refined Regional AMS Evaluation, Central review and approval of AMS evaluation to Agreed Risk Evaluation.</li> <li>2. The progression is captured and recorded within the BMS to form an audit trail of the risk process to this point.</li> </ol>
Procedure	<ol style="list-style-type: none"> <li>1. Plot the identified risks on the heat map in the Risk Register to determine its level of priority (very high, high, moderate or low).</li> <li>2. Determine which risks can be satisfactorily managed through existing controls or processes and where additional treatment or improvements to existing controls will be required to be made to manage the risk exposure.</li> </ol>	<ol style="list-style-type: none"> <li>1. Risk Scores are used to determine the risk ratings as per Portfolio Risk reference tables.</li> <li>2. AMS will consider existing controls or any acceptable reductions in asset Level of Service in performing his evaluation of Risks through modification of consequence and likelihood scores.</li> </ol>
<b>TIP:</b> <ol style="list-style-type: none"> <li>1. Plotting the risks on the heat map provides a good pictorial representation of the risks.</li> <li>2. Plotting the risks in this manner assists in effective decision making.</li> </ol>		
<b>Step</b>	<b>(5) Risk Treatment</b>	<b>BMS Structures Criticality, Risk and Prioritisation Process</b>
Overview	Risk treatment involves selecting one or more options to manage the risk. The optimal treatment is not necessarily the one that reduces the risk to its lowest possible level, but the one which allows Main Roads to achieve its objectives, whilst remaining within the agreed risk appetite/parameters.	<p>In selecting risk treatment for bridge assets, treatments/controls using ALARP principles can be selected from;</p> <ul style="list-style-type: none"> <li>Existing, non-build' AM procedures such as propping, load posting monitoring etc. These will be monitored through the existing BMS issues register.</li> <li>Build options such as maintenance, strengthening, widening renewal and associate project development activities such as environmental and AH approvals, scoping and design. These treatments will be captured in the BMS program Management Module and risk monitoring based on the treatments progressing from 'planned' to 'programmed' (funded) and delivered. These are generally eliminate options from the treatment</li> </ul>



		hierarchy. The PM module will also capture some non-build treatments such as inspections and load ratings.
<b>Expected Outcome</b>	<ol style="list-style-type: none"> <li>1. Primary treatment options are identified and documented.</li> <li>2. Update the Risk Register.</li> </ol>	<ol style="list-style-type: none"> <li>1. Treatment options will be linked to PM module options and stages or Issues Register with associated justification documentation.</li> <li>2. The BMS Risk register will be updated with Residual Risk Scores added to demonstrate risks are being planned for and managed. Effectiveness of treatments reviewed bi-annually.</li> </ol>
<b>Procedure</b>	<ol style="list-style-type: none"> <li>1. Determine if the identified risk is to be avoided, accepted, transferred or mitigated. Refer to Appendix 1 for the Risk Acceptance Criteria and guidance.</li> <li>2. The Risk Treatment Options are listed in Appendix 3. .</li> <li>3. A risk treatment plan must be created for risks that are rated as <b>High</b> or <b>Very High</b> - what is the proposed actions, who is the accountable person and timelines.</li> <li>4. The risk treatment plan can be a business plan action or a project plan action.</li> <li>5. If there are existing business/project actions that mitigate the identified risks, note them in the Risk Register.</li> <li>6. Monitor and review the effectiveness of the treatment plan on a regular basis and document the review.</li> </ol>	<ol style="list-style-type: none"> <li>1. Assessment made by AMS based on ALARP principles and Risk Acceptance Criteria</li> <li>2. Treatment options are broadly categorized into build and non-build options. Build options are defined by Bridgeworks Work Items</li> <li>3. The BMS Risk Register forms the Risk Treatment Plan with accountabilities established and communicated based on the Risk Acceptance Criteria.</li> <li>4. The BMS PM Module and Issues Register for the treatment plans and are linked to Investment Planning through the AMSC and MRIC committees.</li> <li>5. Existing business processes for asset management will be taken into consideration in the risk evaluation and risk treatment phases with justification documentation link for transparency and auditability.</li> <li>6. Monitoring and Review as per Step 6 below based on a reporting tool in BMS.</li> </ol>
<b>TIP:</b> <ol style="list-style-type: none"> <li>1. If there is an existing business or project actions that will treat the identified risk/s, there is no need to develop a discrete treatment action plan. It is essential that the existing business or project action is properly referenced in the Risk Register and monitored and reviewed on a regular basis.</li> </ol>		<ol style="list-style-type: none"> <li>1. Links to Asset Management Program (BMS PM Module) and BMS Issues Register capture treatment plans.</li> </ol>
<b>Step</b>	<b>(6) Monitoring, Reporting and Reviewing</b>	<b>BMS Structures Criticality, Risk and Prioritisation Process</b>
<b>Overview</b>	Ongoing monitoring, reporting and reviewing is an integral part of risk management.	
<b>Expected Outcome</b>	Develop governance system around monitoring, reporting and reviewing risks, controls and treatment plans.	<ol style="list-style-type: none"> <li>1. Governance system as per risk acceptance criteria and review frequency twice per year or as required.</li> <li>2. Assessment of Risk Treatments/Controls and review of risk as necessary.</li> <li>3. Risk Acceptance as per Portfolio Risk Tables.</li> <li>4. Review triggers; System Data Change, LoS Change, Demand/Use change.</li> </ol>
<b>Notes</b>	<p>Risks, controls and the effectiveness of treatment measures need to be monitored, reviewed and reported on to ensure changing circumstances do not alter risk treatment priorities.</p> <p>Where possible consider embed the monitoring, reporting, reviewing requirements in existing processes.</p> <p><u>Review and Monitor</u> Ensure there is regular reviewing and monitoring of the identified risks, controls and treatment plans. When reviewed, document the review and note if any changes were made. It is recommended that a review be conducted at least twice a year or more depending on the risk profile.</p> <p><u>Report</u> Clear risk reporting and escalation guidelines are an important component to ensure that management have proper oversight over business activities. Ensure the identified risks are reported in a timely manner to senior managers and the Corporate Executive. Where possible, provide a report on the aggregated risk data.</p> <p><u>Escalate</u></p>	<p>BMS Risk Monitoring and Review screen and input table set up for AMS to update bi-annually to coincide with programming cycle.</p> <p>Review and Monitoring carried out through dedicated page/table in BMS. Review and Monitoring also to include any Risk Process improvements via SAMF to NM Branch BMS Project Sponsor/ SE Branch BMS Project Manager.</p> <p>Reporting and Communication at regional level by printed report from BMS to Network Manager and Regional Manager on frequency decided by Regional reporting requirements.</p> <p>Escalation of Issues through Network Asset Management monthly conferences, Regional Manager Conferences, AMSC, MRIC.</p>



	If an Issue occurs, the Risk Register will need to be reviewed and appropriately updated. The flow chart below outlines the process to follow in such instances.	
<b>Step</b>	<b>(7) Communication and Consultation</b>	<b>BMS Structures Criticality, Risk and Prioritisation Process</b>
<b>Overview</b>	<p>Communication and consultation with relevant stakeholders at every process step is essential. It assists in ensuring that those accountable for implementing risk management process and stakeholders understand the basis on which decisions are made and the reasons why particular actions are required.</p> <p>It also provides the opportunity for stakeholders to share their ideas and assist in making effective decisions.</p>	
<b>Expected Outcome</b>	<ol style="list-style-type: none"> <li>1. Ongoing communication and consultation with the relevant internal and external stakeholders throughout the process.</li> </ol>	<ol style="list-style-type: none"> <li>1. Communication and consultation locally in region by AMS.</li> <li>2. Centralised reporting by NM Branch through AMSC, MRIC, Treasury and CorpEx using Power BI Dashboard for statewide risk management for Bridges.</li> </ol>
<b>Notes</b>	<p>Relevant people from each Branch or Directorate should be identified, consulted and where appropriate and involved in the risk process.</p> <p>Most people have different perceptions of risk based on their experiences, values, and assumptions. Where possible, a consultative approach should be used in the risk assessment process. Utilising those with different areas of expertise provides greater assurance that all relevant risks have been identified and will lead to greater commitment in implementing risk treatment action plans.</p>	

# Main Roads WA Bridge Criticality and Risk Assessment

Structure No.	Structure Type Code	BMA	Owner	LGA	Road Name	Road No.	Crossing Name	SLK	Critical	Current Bridge Criticality Score	Current Combined Risk Rating	Residual Combined Risk Rating	BAMP Complete	No Deferred Maintenance	Level 2 Inspection not Overdue
3125	TMBR	Wheatbelt	Local Authority	Narrogin	Whimbin Rock Rd	4180205	Arthur River	6.10	No	2.50	High	High	No	Yes	Yes
4551	TMBR	Wheatbelt	Local Authority	Narrogin	Tarwonga Rd	4180204	Wangelling Gully	22.78	No	2.67	Medium	Medium	No	Yes	Yes
3122	TMBR	Wheatbelt	Local Authority	Narrogin	Tarwonga Rd	4180204	Torbling Brook	2.82	No	2.50	Medium	Medium	No	Yes	Yes
3128A	TMBR	Wheatbelt	Local Authority	Narrogin	Manaring Rd	4180211	Williams River	3.58	No	2.50	High	High	No	Yes	Yes
3142	TMBR	Wheatbelt	Local Authority	Narrogin	Havelock St	4180025	Narrogin Brook	0.61	No	2.83	High	Low	No	Yes	Yes
9250	STBR	Wheatbelt	Local Authority	Narrogin	Northam Cranbrook	M031	Northam - Cranbrook Hwy And Rail	167.89	No	3.00	Medium	Medium	No	Yes	Yes

# Main Roads WA Bridge Risk Assessment - February 2020

Structure No.	BMA	Road Name	Road No.	SLK	Crossing Name	Road Classification	Owner	Structure Type Code	Safety Risk Score	Reliability Risk Score	Sustainability Risk Score	Combined Risk Score	Capital MCA Risk Score	Maintenance MCA Risk Score	Inspection MCA Risk Score	Improvement MCA Risk Score	Evaluated	Treated / Risk Accepted	Control
3125	Wheatbelt	Whimbin Rock Rd	4180205	6.10	Arthur River	Local Road	Local Authority	TMBR	9.00	12.50	6.25	12.50	12.50	9.17	2.50	3.75	Complete.	Untreated	
4551	Wheatbelt	Tanwonga Rd	4180204	22.78	Wangelling Gully	Local Road	Local Authority	TMBR	8.54	8.01	6.68	8.54	8.90	9.79	2.67	2.67	Complete.	Untreated	
3122	Wheatbelt	Tanwonga Rd	4180204	2.82	Torbling Brook	Local Road	Local Authority	TMBR	8.00	7.50	7.50	8.00	7.50	5.00	2.50	3.22	Complete.	Untreated	
3128A	Wheatbelt	Manaring Rd	4180211	3.58	Williams River	Local Road	Local Authority	TMBR	8.50	12.50	3.75	12.50	12.50	8.33	2.50	4.17	Complete.	Untreated	
3142	Wheatbelt	Havelock St	4180025	0.61	Narrogin Brook	Local Road	Local Authority	TMBR	10.75	14.15	8.49	14.15	14.15	5.66	8.49	6.07	Review is completed by AMS and requires SASM input.	Treated/Risk Accepted	Adequate
9250	Wheatbelt	Northam Cranbrook	M031	167.89	Northam - Cranbrook Hwy And Rail	State Road	Local Authority	STBR	8.25	9.00	9.00	9.00	9.00	7.00	9.00	4.50	Complete.	Untreated	

Page intentionally left blank

**Bridge 3125**  
**Whinbin Rock Road over**  
**Arthur River**  
**L2 Inspection**



File: **04/4053**  
To: **Engineer Bridge Loading**  
Subject: **Bridge Number: 3125**

---

1. Having recently completed an assessment of routine and specific maintenance work required on this bridge, I am of the opinion that the condition of certain structural components has deteriorated to such an extent that the load carrying capacity of the bridge may have been affected.
2. In accordance with the requirements of the procedure for Heavy Loads Assessment, Document number 3912/01-7, this bridge is referred for a detailed structural assessment of the bridge in its present condition.



Mark Billings  
Senior Structural Engineer AECOM  
18 March 2019

Span 3 Stringer 3





Enquiries: Gavin Johnston on 9323 4431  
Our Ref: 04/4053  
Your Ref:



ABN: 50 860 676 021

## ASSET MANAGER STRUCTURES WHEATBELT REGION

Structure No.: 3125  
Over: Arthur River  
On: Whimbin Rock Rd (4180205)  
SLK: 6.14  
LGA: Shire of Narrogin

1. Please find enclosed a copy of the Detailed Inspection Report for the above Local Authority structure.
2. Attached is a schedule of maintenance items that are required to be undertaken in order to maintain structural integrity and extend the life of the Structure.
3. The maintenance items have been entered into IRIS for programming purposes.
4. Preliminary examination has indicated that the load carrying capacity of this Structure may have been affected by the deterioration of structural components as listed in the attached report. We are in the process of determining its current load capacity and will advise you accordingly when our assessment is completed.

Reviewed By:

Mark Billings  
SENIOR STRUCTURAL ENGINEER AECOM

19/3/2019

Enc

Issued By:

Gavin Johnston  
BRIDGE CONDITION MANAGER

22/3/19

**WORK ITEMS - TIMBER BRIDGES**  
**BRIDGE No: 3125**

ITEM NO	ITEM DESCRIPTION	WORK REQD	PRIORITY CODE	COMMENTS
---------	------------------	-----------	---------------	----------

**(A) GENERAL MAINTENANCE**

G005	Bridge Durability Survey (L3)			
G009	Bridge - Load Rating	Y	0	Span 3 Stringer 3, abutment 1 side.
G010	Bridge - Monitor Defect			

**(B) PREVENTATIVE MAINTENANCE**

P101	Bridge Seal Timber			
P102	Bridge Maintain Fastener			
P103	Bridge - Fungicide Treatment			

**(C) ROUTINE MAINTENANCE**

	Bearing - Maintain			
	Bridge Remove Graffiti			
	Bridge - Repair Scour (Minor)			
	Bridge - Eradicate Termites	Y	1	
	Bridge Clear Debris and Vegetation			
	Deck Joint Maintain			
	Deck Surface Maintain	Y	1	Gap at Approached A1 RHS-req correction
	Drainage - Maintain			
	Expansion Joint - Maintain			
	Fence - Remove			
	Fence - Repair (Control of Access)			
	Guardrail Maintain/Repair			
	Kerb - Repair (Minor) - Non Structural			
	Lighting - Maintain			
	Sign - Maintain	Y	1	Width Marker replace & realign

**(D) SPECIFIC MAINTENANCE**

S315	Bridge - Replace Fastener <1.5m			
S350	Bridge Repair Scour (Major)			
S366	Bridge - Access - Improve			
S413	Deck Repair			
S437	Decking - Repair (Timber)			
S449	Drainage - Repair			
S455	Expansion Joint - Repair			
S461	Footpath - Repair			
S501	Abutment - Reconstruct			
S504	Abutment - Repair (Non timber)			
S507	Bedlog - Repair			
S510	Bedlog - Shim			
S522	Corbel Bolt			
S525	Corbel - Repair			
S528	Corbel - Shim	Y	2	Pier 2 corbel 6 A1
S537	Footpath Railing - Repair			
S540	Fullcap - Repair			
S543	Halfcap - Improve Bearing			
S546	Halfcap Pack			
S549	Halfcap - Repair			
S558	Pier - Repair			
S561	Pile - Band			
S564	Pile - Repair	Y	2	Abutment 2 pile 10
S570	Sheeting Repair	Y	2	A1 face, wing caps RHS & LHS. A2 face, wing walls & caps LHS
S582	Waler - Replace			
S607	Bearer - Repair			
S643	Joist Repair			
S655	Stringer - Bolting	Y	2	span 3 Str 7
S661	Stringer - Repair	Y	2	span 3 Str 3
S667	Stringer - Shim	Y	2	Span 2 Str 3 A2, Span 3 Str 1 A2, Str 6 A2

**PRIORITY CODE**

0 - Critical Safety Deficiency : EMERGENCY action required (Immediate or within 6 months)

1 - Very High Priority (Within 3 years)

2 - Medium Priority (Within 4 years)

3 - Low Priority (Within 5 years-assess again at next Detailed Inspection)

## DETAILED TIMBER BRIDGE INSPECTION SUMMARY

Bridge No:	3125	Region:	WHEATBELT REGION
River Name:	Arthur River	SLK:	6.14
Road:	Whimbin Rock Rd	Road No:	4180205
LGA:	Shire of Narrogin		

---

### 1.0 General

Bridge no. 3125 located on Whimbin Rock Rd in the Shire of Narrogin is a three spans bridge crossing the Arthur River. The structure requires maintenance and generally appears to be in fair condition.

### 2.0 Preventative Maintenance

Preventative maintenance to be undertaken on a 5 year periodic basis.

### 3.0 Routine Maintenance

Undertake termite inspection and treatment as required in accordance with specification 850.93.09.  
Correct road surface on bridge deck and approaches as outlined in report.  
Replace signs and lights as outlined in report.

#### Specific Maintenance

### 4.0 Substructure

#### 4.1 Undertake pile repairs as outlined in report in accordance with specification 850.31.

( Abutment 2 pile 10 )

Undertake timber abutment repairs as outlined in report.

( A1 face, wing caps RHS & LHS. A2 face, wing walls & caps LHS )

#### 4.2 Superstructure

Shim corbels as outlined in report

( Pier 2 corbel 6 A1 )

Bolt and or seal stringers as outlined in report in accordance with specification 850.29/850.30

( span 3 Str 7 )

Undertake stringer repairs as outlined in report.

( span 3 Str 3 )

Shim stringers as outlined in report

( span 2 Str 3 A2, span 3 Str 1 A2 end , Str 6 A2 )

### 5.0 BCI

39.9

### 6.0 Load Rating

Span 3 stringer 3, abutment 1 side requires load rating.

Mark Billings  
Senior Structural Engineer AECOM

March 6 2018  
MAIN ROADS Western Australia  
2011 T BCM 3125 - Summary(3)



**DETAILED VISUAL (LEVEL 2) TIMBER  
BRIDGE INSPECTION REPORT  
BRIDGE CONDITION INDEX (BCI)**



**Bridge Number**

**3125**

In conjunction with the Detailed Level 2 Bridge Inspection Report (as dated below), a Bridge Condition Index (BCI) has been calculated for this Bridge. The BCI assigns a numerical value to a bridge that is indicative of its condition and provides a relative condition in comparison with other timber bridges (BCI calculation is only applicable for timber bridges). The BCI rating system is a tool to provide a systematic approach for the determination of bridge condition by bridge inspection alone.

The process for determining the BCI is outlined in the Timber Bridge Condition Index User Guide. The BCI is primarily calculated utilising Condition States which are assigned based on the Level 2 Bridge Inspection Report (see attached).

A summary of the condition states and the calculated BCI for this bridge is provided below.

**Condition States from Detailed Inspection Report conducted on**

17-01-2018

		Condition State - Distribution (%)					
LOCATION	Weighting	CS1	CS2	CS3	CS4	Ave AGR	BCI
Condition State Weighting		1	3	9	11		
Stringers	11	58.4	40.0	0.0	1.6	25.5	<u>39.9</u>
Pier Piles	11	57.0	43.0	0.0	0.0		
Abutment Piles	11	60.5	28.3	11.2	0.0		
Halfcaps	11	0.0	100.0	0.0	0.0	20.4	
Corbels	6	0.0	100.0	0.0	0.0		
Timber Decking	6	0.0	90.0	0.0	10.0	14.0	
Wing Piles	3	65.0	23.0	12.0	0.0		
Abutment Sheeting	3	0.0	36.3	60.0	3.7		

Descriptor	BCI Range
Very Good	0 - 19
Good	20 - 39
Fair	40 - 55
Poor	56 - 100
Severe	101 -

**BCI Descriptor Range (Refer Table 5.1 Doc No. 6706/02/2232)**

**Comments:**

**Prepared by:** P Olsen & A Buenaventura

**Date:** 23/02/2018



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GENERAL INFORMATION - SHEET 1


Bridge No.: 3125

Region:	<u>Wheatbelt</u>	Latitude (S):	<u>-33.08132</u>
		Longitude (E):	<u>117.30610</u>
Road Name:	<u>Whimbin Rock Rd</u>	Road No.:	<u>4180205</u>
Local Government:	<u>Narrogin</u>	Owner:	<u>Local Authority</u>
Crossing Name:	<u>Arthur River</u>	SLK:	<u>6.11</u>
Number of Lanes:	<u>2</u>	Length (m):	<u>18.67</u>
Total Width (m):	<u>7.80</u>	Max. Head Room (m):	<u>2.10</u>
Inc. Footpath		Min. Head Room (m):	<u>1.60</u>
No. of Spans:	<u>3</u>	Width between Kerbs (m):	<u>7.20</u>
		Concrete Overlay (Y/N):	<u>Y (120mm)</u>

Piers are numbered along the bridge in ascending order from ABUTMENT 1 to ABUTMENT 2.  
Piles are numbered across the bridge in ascending order from LEFT to RIGHT.  
Stringers are numbered across the bridge in ascending order from LEFT to RIGHT.

Inside and outside kerb depths noted in corners of sketch.

Exposed Deck Ends (RCO only): LHS ☒ N RHS ☒ N



This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Timber Bridge Detailed Inspection Guidelines.

Inspected by: S. MAULE D. EWER

Checked by: POLSEN A ALKHILAF

Date: 17.1.18

Date: 1-3-18

Drilled by: DAVID EWER



## SITE CONDITIONS

Bridge No: 3125



DRIVE THROUGH	Visible Line of Sight from Abut. 1: 1 Km Visible Line of Sight from Abut. 2: 1 Km
TRAFFIC CONTROL (Describe if different to the generic TMP)	Abut. 1 end: N/A Abut. 2 end:
PARKING POSITION	> 3 m <input checked="" type="checkbox"/> Position: AB 2 LHS in Paddock 1.2 to 3 m <input type="checkbox"/> Position: 0 to 1.2 m <input type="checkbox"/> Position:
ACCESS TO ABUTMENTS (Describe access conditions at each wing)	Abutment 1: LHS: } OK FROM PARKING AREA RHS: } Abutment 2: LHS: } RHS: } Vegetation: Low Growth
ACCESS TO PIERS (Describe access conditions along each side of the structure)	LHS: AS ABOVE RHS: Vegetation: OK
POTENTIAL HAZARDS	Railing/Posts: WATER Bolts: Low Hanging SCUFFERS Services: Asbestos: Other:
FENCES	Timber <input type="checkbox"/> Location: Wire/Mesh: <input type="checkbox"/> Location: Electrified: <input type="checkbox"/> Location: Barbed Wire: <input type="checkbox"/> Location: Other (Specify): <input type="text"/> Location:
WATER	Depth (m): 1.2 m Flow Rate: Slow Algae: No (Access may be restricted by toxic algae) Tide: No Location: SPAN 1 to 3.
POWERLINES	Side of bridge: LHS Horizontal distance from edge of deck (m): 3 m Estimated vertical height above deck (m): 5 m

Signature

Date 17-1-18



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GUARDRAIL INFORMATION

Bridge No.: 3125

### Barrier Type

None  
RHS Rails No. of Rails (on bridge):  
Thriebeam  
W Beam  
Tric-Bloc Concrete Barrier  
Reinforced Concrete Barrier (Type F)  
Constant Slope Concrete Barrier  
Other Concrete Profiles

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS
X		X	X		X	X		X

### Post Type

None  
Concrete  
Timber  
Steel Type: PFC

X		X	X		X	X		X

[Types: C-Section (C), I Section (I), RHS (R), Square Hollow Section SHS (S), Tubular (T), Steel PFC (PFC), Steel Channel (Ch)]

### Off bridge:

Number of Posts off Bridge  
Length of Barrier off Bridge (m)

6		4				4		6
11.9		8				8		11.9

### Visibility Barrier

Timber No. of Rails (on bridge):  
Steel Pipe(s) No. of Pipes (on bridge):  
Guide Posts  
Balustrade

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS

### Top Rails

Steel Pipe  
Steel RHS/Channel  
Steel C Section  
Timber


### End Terminals

#### Approved End Terminal Types:

WAMELT  
SKT-350  
ET-2000  
X Tension  
TAU II Crash Cushion  
Other:

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS				LHS	Median	RHS

#### Other End Terminal Types:

None  
Turn-down  
Bullnose  
Fishtail  
Other

X		X				X		X

Structural problem found? (Y/N)

N If yes, comment below.





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## ROUTINE INFORMATION

Bridge No.: 3125

SCUPPERS LOCATION, TYPE & CONDITION (R208)		None <input type="checkbox"/> LHS <input checked="" type="checkbox"/> RHS <input checked="" type="checkbox"/>	Box <input type="checkbox"/> PVC pipe <input checked="" type="checkbox"/> Hole in deck <input type="checkbox"/>
			Through Deck <input checked="" type="checkbox"/> Through Kerb <input type="checkbox"/>
FLASHING TYPE & CONDITION (R208)		None <input type="checkbox"/> PVC pipe <input checked="" type="checkbox"/> PGI <input type="checkbox"/>	
BOLT TIGHTENING REQUIRED (P102)		Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
TERMITES (R204)		Active <input checked="" type="checkbox"/> Not Active <input type="checkbox"/>	
PREVENTATIVE FUNGICIDE (P103)		Treated <input checked="" type="checkbox"/> Not Treated <input type="checkbox"/>	
ATTACHED FENCES & OTHER WATERWAY OBSTRUCTIONS (R210)			
ROAD SURFACE & KERBING CONDITION (R207)	ON BRIDGE	Road Surface: R.C.O. ONLY - GOOD	
		Kerbing: CONCRETE - GOOD.	
	APPROACHES	Road Surface: BITUMEN SEAL - MINOR DIPS - FAIR GAP AT AI RHS - REPAIRS CORRECTION	
		Kerbing: SHORT CONCRETE - OK	
VEGETATION (R205)		Requires Clearing : LHS <input type="checkbox"/> Abut 1 <input type="checkbox"/> RHS <input type="checkbox"/> Abut 2 <input type="checkbox"/>	
STREAM BED CONDITION (General comments and details of location, depth & extent of scour, undermining and silt build up.) (R203)			
SERVICES (Type, Size & Location)		Type	Size (mm) Location
		None	
BRIDGE CONDITION		Low <input type="checkbox"/> Priority for Engineering Assessment Medium <input checked="" type="checkbox"/> High <input type="checkbox"/> Urgent <input type="checkbox"/>	

Comments:





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GENERAL INFORMATION - SHEET 2

Bridge No.: 3125

### Bridge Status

Built/In Use ☒

Not Used ☐

Date Built 01/06/1966

Skew (angle) \_\_\_\_\_

Skewed Width (m) \_\_\_\_\_

### Widening

Left Hand side ☐ Width (m) \_\_\_\_\_  
Date \_\_\_\_\_

Right Hand side ☐ Width (m) \_\_\_\_\_  
Date \_\_\_\_\_

### Surface Type

Unsurfaced ☒  
Rubberised Seal ☐

Bitumen Seal ☐  
Tiles ☐

Asphalt ☐  
Steel Plate ☐

### Pavement Type

Unpaved ☐

Gravel ☐

Material Unknown ☒

### Footpath Left

Left Kerb (m) 0.19

Path (m) \_\_\_\_\_

Right Kerb (m) \_\_\_\_\_

### Footpath Right

Left Kerb (m) \_\_\_\_\_

Path (m) \_\_\_\_\_

Right Kerb (m) 0.19

### Median

Left Kerb (m) \_\_\_\_\_

Median (m) \_\_\_\_\_

Right Kerb (m) \_\_\_\_\_

### Bridge Function 1

Road Bridge ☒

Rail Bridge ☐

Pedestrian Bridge ☐

### Bridge Function 2

Over Water ☒

Over Road ☐

Over Rail ☐

Over Road & Rail ☐

Over Road & Water ☐

Over Rail & Water ☐

Stock Underpass ☐

Pedestrian Underpass ☐

## SIGNAGE

### Load Limits

Abutment 1 End  Tonne

Abutment 2 End  Tonne

### Width Markers

Abutment 1 LHS ☒ RHS ☒

Abutment 2 LHS ☒ RHS ☒

Is position of Width Markers a true indication of the bridge width? (Y/N) ☒

\* - REPLACE & REALIGN

### Other Signs

No Overtaking or Passing

Abutment 1 LHS ☐

RHS ☐

Abutment 2 LHS ☐

RHS ☐

No Overtaking on Bridge

Abutment 1 LHS ☐

RHS ☐

Abutment 2 LHS ☐

RHS ☐

One Lane Bridge

Abutment 1 LHS ☐

RHS ☐

Abutment 2 LHS ☐

RHS ☐

Low Clearance .....m

Abutment 1 LHS ☐

RHS ☐

Abutment 2 LHS ☐

RHS ☐

Narrow Bridge Sign

Abutment 1 LHS ☐

RHS ☐

Abutment 2 LHS ☐

RHS ☐

Give Way

Abutment 1 LHS ☐

RHS ☐

Abutment 2 LHS ☐

RHS ☐

### Crossing Sign:

### Other

Abutment 1 LHS ☐

RHS ☐

Abutment 2 LHS ☐

RHS ☐

Abutment 1 LHS ☐

RHS ☐

Abutment 2 LHS ☐

RHS ☐

### Signage Condition Legend

Good

1

Poor

3

Not Required

☐

Fair

2

None (missing)

4


## ELEMENT SPACING SHEET 1

Bridge No.: 3125


### Abutment 1

All measurements (cumulative) are taken from the reference point as indicated by the star ☆


#### LHS Wing Wall Layout



#### Abutment Abutment Pile Centres




#### RHS Wing Wall Layout




### Abutment 2


#### LHS Wing Wall Layout



#### Abutment Abutment Pile Centres



#### RHS Wing Wall Layout





## ELEMENT SPACING SHEET 2

Bridge No.: 3125


All measurements (cumulative) are taken from the reference point as indicated by the star ☆

### Pier Pile Centres


Mark in RHS edge of deck and dimension last pile to RHS edge of deck.

PIER No. ....


TYPICAL



PIER No. ....



PIER No. ....




### Typical Stringer Spacing


Mark in RHS edge of deck and dimension last stringer to RHS edge of deck.

Note: Stringer spacings must be measured in every span with additional stringers. Use additional sheets as required.


SPAN No. .... TYPICAL



SPAN No. ....



SPAN No. ....






# TIMBER BRIDGE DETAILED INSPECTION REPORT



ABUTMENT: 1

Bridge No: 3125



Pile No.	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Dia. (mm) below H/C (5m+)	Mat. Type	Tied Back	Cond. State
		Solid	Rot	Pipe	Drill Location from top H/C	Above	Below	Location	Requires Band	Marking (ft/m)	Height Top H/C to Blaze (m)	Height Blaze to GL (m)	A1	A2				
1	330	105	60		0.5			1		-	0.7	-	-	-	-	JAR		2
2	310	100		55	1.0			1		-	1.3	-	-	-	-	JAR		2
3	350	105		70	1.3			1		-	1.8	-	-	-	-	JAR		2
4	360	130	50		1.9			✓		-	2.3	-	-	-	-	JAR		2
5	390	195								-	1.6	-	-	140	-	JAR		2
6	320	160								-	1.7	-	-	150	-	JAR		2
7	350	135		40	1.2			-		-	1.7	-	-	130	-	JAR		2
8	360	180						-		-	1.7	-	-	100	-	JAR		2
9	460	230								-	1.6	-	-	145	-	JAR		2
10	380	190								-	1.8	-	-	-	-	JAR		2
11	430	215						-		-	1.1	-	-	-	-	JAR		2
12	410	SEE NOTES			0.6	TO TOP	0.6	-		-	0.8	-	-	-	-	JAR		3
13	370	SEE NOTES			0.4	TO TOP	0.3			-	0.3	-	-	-	-	JAR		2
14																		
15																		

Saturated Piles:

LHS Halfcaps Size V 330 H 150 Length 8630 No. of 1 Gap between H/Caps -

Top of H/Caps to underside of Deck 380 Back of Halfcaps to Sheeting 230 H/Cap Material JAR

RHS Halfcaps Size V H Length No. of Gap between H/Caps

Top of H/Caps to underside of Deck Back of Halfcaps to Sheeting H/Cap Material

Are there more than 2 sets of halfcaps or sill beams (YES/NO) No (If yes record details on comments sheet)

Comments: FIRST DRILLING PLANK A- STR 2 IS IN POOR CONDITION.

ANY RESULTS VASTLY DIFFERING FROM OLD REPORT ARE DOUBLE CHECKED - T/OUT REPORT.

BAND NOT REQ

Pile No. 12 60/s R.H.S 120/s L.H.S 120/s F= 80/s	Pile No. 13 50/s R.H.S 150/s L.H.S 200/s F= 120/s	Pile No. 12 (2013 DIR) 130/s R.H.S 130/s L.H.S 120/s F= 130/s	Pile No. 13 (2013 DIR) 180/s R.H.S 180/s L.H.S 200/s F= 60/s
--------------------------------------------------------	---------------------------------------------------------	---------------------------------------------------------------------	--------------------------------------------------------------------





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## ABUTMENT 1 and WING WALL SHEETING

Bridge No: 3125

ABUTMENT 1 SHEETING (indicate ground line, piles and failed sheeting) 9 SMTS

RHS	1		50/5	LHS
	2			U/S At END, REPAIR
	3			
	4			
	5			
	6	40/5		
	7	40/5		
	8	U/S	REPAIR	
	9			
	10			
	11			
	12			

SHEETING - ABUTMENT LHS TOP 50/5 Rest Solid.

Rot from Pile

To Pile

Centreline 8" U/S 6x7 40/5 Rest Solid

Rot from Pile 6

To Pile 7

RHS Solid

Rot from Pile

To Pile

SHEETING Material Type

J

SHEETING Material Size (mm)

Vertical

220

Depth

70

Condition 1

Condition 2

Condition 3

Condition 4

% Condition State

85

10

5

ABUTMENT 1 WING WALLS (indicate ground line, piles and failed sheeting)

RHS	8 SMTS	1	LHS	9 SMTS
		2		
		3		
		4		
		5		
		6		
		7		
		8		
		9		
		10		
		11		
		12		

WINGCAP / SPIKING RAIL CONDITION

WINGCAP / SPIKING RAIL CONDITION

Lower Section U/S Rest Poor Cond. REPAIR  
Rep's Attention

All in Poor Cond. Rep's Attention  
REPAIR

SHEETING - WING WALLS LHS All 50 to 60 Solid.

Rot from Pile

To Pile

RHS All 50 to 60 Solid.

Rot from Pile

To Pile

SHEETING Material Type

J

SHEETING Material Size (mm)

Vertical

220

Depth

70

Condition 1

Condition 2

Condition 3

Condition 4

% Condition State

100



# TIMBER BRIDGE DETAILED INSPECTION REPORT



PIER No: 1

Bridge No: 3125

Pile No.	Circ. (mm)	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Circ. (mm) below IIC (5m+)	Mat. Type	Cond. State
			Solid	Rot	Pipe	Drill Location from top I/C	Below	Above	Location	Requires Band	Marking (ft/m)	Height Top I/C to Blaze (m)	Height Blaze to GL (m)	A1	A2			
1	1220	390	195								-	2.8	-	110	140	-	JAR	2
2	1260	400	200						✓		-	2.4	-	85	90	-	JAR	2
3	1160	310	185						-		-	2.3	-	100	130	-	JAR	2
4	1320	420	210						-		-	2.3	-	150	150	-	JAR	2
5																		
6																		
7																		
8																		
9																		
10																		

Total Number of Corbels: 7

Typical Corbel Height (mm): LHS 330 RHS 330

Corbel No:

Material Type:

Requires Bolting:

Condition State:

A1/A2 End

A1/A2 End

1	2	3	4	5	6	7	8	9	10	11	12	13	14
JAR	JAR	JAR	JAR	JAR	JAR	JAR							
-	-	-	-	-	-	-	-	-	-	-	-	-	-
2	2	2	2	2	2	2	2	2	2	2	2	2	2

Ironwork Condition: MEDIUM RUST

Tightening Required: No

Walers Size V - x H -

Bracing Size V - x H -

Saturated Piles:

LHS Halfcaps Size V 330 H 170 Length 1380 No. of 2 Gap between H/Caps 150

Top of I I/Caps to underside of Deck 700

I I/Cap Material JAR

RHS Halfcaps Size V - H - Length - No. of - Gap between I I/Caps -

Top of I I/Caps to underside of Deck -

I I/Cap Material -

Are there more than 2 sets of halfcaps or sill beams (YES/NO) No (If yes record details on comments sheet)

Comments: PILE 3, AB1 SIDE HAS A H.C. SUPPORT BRACKET.

BAND NOT RECD

Pile No.: _____ A2 _____ LHS _____ A1 _____ RIIS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RIIS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____
--------------------------------------------------------------------	-------------------------------------------------------------------	--------------------------------------------------------------------	-------------------------------------------------------------------





# TIMBER BRIDGE DETAILED INSPECTION REPORT



PIER No: 2

Bridge No: 3125

Pile No.	Circ. (mm)	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Circ. (mm) below H/C (5m+)	Mat. Type	Cond. State
			Solid	Rot	Pipe	Drill Location from top H/C	Below	Above	Location	Requires Band	Marking (ft/m)	Height Top H/C to Blaze (m)	Height Blaze to GL (m)	A1	A2			
1	1190	380	150	40		1.3			1		-	2.2	-	95	80	-	JAR	2
2	1190	380	190								-	2.0	-	105	110	-	JAR	2
3	1260	400	200								-	2.0	-	110	125	-	JAR	2
4	1350	430	215						✓		-	2.1	-	115	120	-	JAR	2
5																		
6																		
7																		
8																		
9																		
10																		

Total Number of Corbels: 7

Typical Corbel Height (mm): LHS 330 RHS 330

Corbel No:

Material Type:

Requires Bolting:

Condition State:

A1/A2 End

A1/A2 End

1	2	3	4	5	6	7	8	9	10	11	12	13	14
JAR	JAR	JAR	JAR	JAR	JAR	JAR							
-	-	-	-	-	-	-	-	-	-	-	-	-	-
2	2	2	2	2	2	2	2	2	2	2	2	2	2

Ironwork Condition: MEDIUM RUST

Tightening Required: No

Walers Size V - x H -

Bracing Size V - x H -

Saturated Piles:

LHS Halfcaps Size V 330 H 170 Length 7470 No. of 2 Gap between H/Caps 140

Top of H/Caps to underside of Deck 700

H/Cap Material JAR

RHS Halfcaps Size V H Length  No. of  Gap between H/Caps

Top of H/Caps to underside of Deck

H/Cap Material

Are there more than 2 sets of halfcaps or sill beams (YES/NO) No (If yes record details on comments sheet)

Comments: CORBEL 6 AB1 SIDE RAIL PACKING. PACK

BRACE NOT RUST

Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____
-------------------------------------------------------------------	-------------------------------------------------------------------	-------------------------------------------------------------------	-------------------------------------------------------------------






# TIMBER BRIDGE DETAILED INSPECTION REPORT



ABUTMENT: 2



Bridge No: 3125

Pile No.	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Dia. (mm) below H/C (5m+)	Mat. Type	Tied Back	Cond. State
		Solid	Rot	Pipe	Drill Location from top H/C	Above	Below	Location	Requires Band	Marking (Fvm)	Height Top I/C to Blaze (m)	Height Blaze to GL (m)	A1	A2				
1	980 1300	CONCRETE BLOCK								-	0.4	-	-	-	-	CON		1
2	380	SEE NOTES			0.7	TO TOP	0.3	-	-	-	1.3	-	-	-	-	JAR		3
3	380	140		50	2.1			-	-	-	2.1	-	-	-	-	JAR		2
4	410	SEE NOTES			0.9	TO TOP	0.5	-	-	-	1.6	-	130	-	-	JAR		3
5	380	100		90	1.4			-	-	-	1.6	-	95	-	-	JAR		2
6	390	SEE NOTES			1.4	1.0	0.4	-	-	-	1.9	-	145	-	-	JAR		3
7	400	120		80	0.5			-	-	-	1.9	-	120	-	-	JAR		2
8	370	145		40	0.5			-	-	-	1.8	-	150	-	-	JAR		2
9	360	SEE NOTES			1.5	TO TOP	0.8	-	-	-	2.3	-	-	-	-	JAR		3
10	380	SEE NOTES			0.8	TO TOP	1.0	-	-	-	1.4	-	-	-	-	JAR		2
11	700 1000	CONCRETE BLOCK								-	0.5	-	-	-	-	CON		1
12																		
13																		
14																		
15																		

Saturated Piles: —

LHS Halfcaps Size V 330 170 Length 8650 No. of 1 Gap between H/Caps —

Top of H/Caps to underside of Deck 380 Back of H/Caps to Sheeting 220 H/Cap Material JAR


RHS Halfcaps Size V 11 Length — No. of — Gap between H/Caps —

Top of H/Caps to underside of Deck — Back of H/Caps to Sheeting — H/Cap Material —

Are there more than 2 sets of halfcaps or sill beams (YES/NO) No (If yes record details on comments sheet)

Comments:

PILE 10 IS POOR AT TOP  
SEE AUDIT PHOTO



<p>REPAIR</p> <p>Pile No. <u>10</u> <u>0/s</u></p> <p>L.H.S. <u>140/s</u> R.H.S. <u>160/s</u></p> <p>F = <u>120/s</u></p>	<p>Pile No. <u>9</u> <u>0/s</u></p> <p>L.H.S. <u>140/s</u> R.H.S. <u>90/s</u></p> <p>F = <u>110/s</u></p>	<p>Pile No. <u>6</u> <u>0/s</u></p> <p>L.H.S. <u>120/s</u> R.H.S. <u>150/s</u></p> <p>F = <u>80/s</u></p>	<p>Pile No. <u>4</u> <u>60/s</u></p> <p>L.H.S. <u>90/s</u> R.H.S. <u>110/s</u></p> <p>F = <u>100/s</u></p>
---------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------



## ABUTMENT 2 and WING WALL SHEETING

Bridge No: 3125

**ABUTMENT 2 SHEETING** (indicate ground line, piles and failed sheeting)

10 SHTS

LHS		RHS	
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			

SHEETING - ABUTMENT LHS All 50 to 60 Solid

Centreline 6" A/S Rest Go Solid

RHS 6" A/S Rest Go Solid

Rot from Pile

Rot from Pile

Rot from Pile

To Pile

To Pile

To Pile

SHEETS 3, 4 & 5 IN POOR CONDITION RHS SHEET 6 IS U/S BEHIND PILE 7 - SEE Awaiting Photos

SHEETING Material Type J

SHEETING Material Size (mm) 220 Vertical 70 Depth

Condition 1

% Condition State

Condition 2

60

Condition 3

40

Condition 4

**ABUTMENT 2 WING WALLS (indicate ground line, piles and failed sheeting)**

ABUTMENT 2 WING WALLS (indicate ground line, piles and railed sheeting)

The diagram shows two cross-sections of wing walls, LHS and RHS, with a vertical scale of 12 piles. The LHS wall is labeled '8 SWS' at the top and 'LHS' on the right. It has a '6" U/S' note on the left. The RHS wall is labeled '7 SWS' at the top and 'RHS' on the right. It has a '4" U/S' note on the right and 'TERMITE DAMAGE AT END.' written vertically. Both walls have a 'WINGCAP / SPIKING RAIL CONDITION' label at the bottom. The LHS wall has a 'REPAIR' note in red and 'XXXXXX' in yellow on pile 6. The RHS wall has 'AOL'S' written on piles 5, 6, and 7. At the bottom, there are two lines of text: 'U/S REQ'S REPLACING. REPAIR' and 'BADLY WEATH & SPLIT.'

6" U/S

LHS

8 SWS

1

2

3

4

5

6

7

8

9

10

11

12

REPAIR

XXXXXX

WINGCAP / SPIKING RAIL CONDITION

U/S REQ'S REPLACING.

REPAIR

RHS

7 SWS

4" U/S

TERMITE DAMAGE AT END.

Xk

AOL'S

AOL'S

AOL'S

WINGCAP / SPIKING RAIL CONDITION

BADLY WEATH & SPLIT.

SHEETING - WING WALLS LHS	6" U/S	Riser 50 to 60 SOLID.	Rot from Pile	2	To Pile	3
RHS	5.6" U/S	Riser 50 to 60 SOLID.	Rot from Pile		To Pile	
SHEETING Material Type	J					
SHEETING Material Size (mm)	Vertical	220	Depth	70		
% Condition State	Condition 1	Condition 2	Condition 3	Condition 4		
			90	10		





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## DETAIL SHEET

Span No: 1

Bridge No: 3125

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	JAR	JAR	JAR	JAR	JAR							

		H Diameter (mm)	420	490	460	490	520	510	420							
		V Measurement (mm)	380	380	380	380	380	380	380							
Abutment 1 End	Drill Vertical	Solid (B)	140	140	100	380	380	380	110							
		Rot		70												
		Pipe	170	160	140				240							
		Rot														
		Solid (T)	70	—	140				30							
	Drill Horiz	Left	200	190					150							
		Right	170	160					150							
	Split	V Bolt Rqd	—	—		—	—	—								
		H Bolt Rqd														
	Propped															
Condition State		2	2	2	1	1	1	2								

		H Diameter (mm)	460	530	460	500	540	530	400								
		V Measurement (mm)	450	510	410	530	550	530	440		NOTE:						
Mid Span	Drill Vertical	Solid (B)	450	480	410	480	280	480	260		DRILL IS ONLY 180mm LONG.						
		Rot									RESULTS GIVEN TO 180mm						
		Pipe					100		120		ONLY - TIGHT REBAR						
		Rot															
		Solid (T)					100		60								
	Drill Horiz	Left															
		Right															
	Split	V Bolt Rqd															
		H Bolt Rqd															
	Propped																
Condition State			1	1	1	1	2	1	2								

		H Diameter (mm)	510	600	510	540	550	600	460								
		V Measurement (mm)	370	370	370	370	370	370	370								
Abutment 2 End	Drill Vertical	Solid (B)	370	370	370	370	110	370	130								
		Rot															
		Pipe					240		140								
		Rot															
		Solid (T)					20		100								
	Drill Horiz.	Left					180										
		Right					190										
	Split	V Bolt Rqd	✓	1			1		1								
		H Bolt Rqd			1												
	Propped																
Condition State			1	1	1	1	2	1	2								

Cond. of Spiking Plank Not Applicable ☒ Size V  Condition S  R  %

Cond. of Decking (Solid/Rot) S  90 R  10 % Cond. of Deck Ends S  R  %

Decking Size (mm) V  120 x H  230 Decking Timber Type JAR

Span Length from Centreline Supports (m)  5.75 Clear Span Length  4.92 Saturated stringers:

Deck Condition State Condition 1  Condition 2  90 Condition 3  Condition 4  10 Spiral Grain Stringers:

Comments: Bowdeck used LHS to STR 1 & STR 7 TO RHS. T/OUT BRIDGE STRS 2 & 6 HAVE S.G. BOLT NOT REQ. OLD TERMITE NEST AT AB FACE, STR 1 TO 3, APPEARS NOT ACTIVE STR 7, AB 1 RHS DRILLED IN A 30mm CHECKOUT.





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## DETAIL SHEET

Span No: 2

Bridge No: 3125

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	JAR	JAR	JAR	JAR	JAR							

Abutment 1 End	H Diameter (mm)	540	490	480	560	550	570	500						
	V Measurement (mm)	370	370	370	370	370	370	370						
	Drill Vertical	Solid (B)	370	370	120	370	100	370	120					
		Rot			60		50							
		Pipe						110						
		Rot												
		Solid (T)			190		220		140					
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd	-	-	-		-	-						
		H Bolt Rqd												
	Propped													
	Condition State		1	1	2	1	2	1	2					

Mid Span	H Diameter (mm)	440	480	460	480	550	520	450						
	V Measurement (mm)	450	450	420	570	520	520	500						
	Drill Vertical	Solid (B)	230	450	100	480	220	170	480					
		Rot												
		Pipe	70		140		70	140						
		Rot												
		Solid (T)	150		180		190	170						
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd			-									
		H Bolt Rqd												
	Propped													
	Condition State		2	1	2	1	2	2	1					

Abutment 2 End	H Diameter (mm)	420	420	440	450	520	480	450						
	V Measurement (mm)	370	370	370	370	370	370	370						
	Drill Vertical	Solid (B)	180	150	180	370	220	100	140					
		Rot	100											
		Pipe		100	80		50	120	140					
		Rot												
		Solid (T)	90	120	110		100	150	90					
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd			✓	✓	✓	✓	✓					
		H Bolt Rqd												
	Propped													
	Condition State		2	2	2	1	2	2	2					

Cond. of Spiking Plank Not Applicable ☒ Size V  Condition S  R  %

Cond. of Decking (Solid/Rot) S  R  % Cond. of Deck Ends S  R  %

Decking Size (mm) V  x H  Decking Timber Type

Span Length from Centreline Supports (m)  Clear Span Length  Saturated stringers: \_\_\_\_\_

Deck Condition State Condition 1 Condition 2 Condition 3 Condition 4

Percentage:   Spiral Grain Stringers: \_\_\_\_\_

Comments: STR 1 HAS SG.

STR 3, AB 2 REQ'S PACKING. PACK

BOLTS NOT REQ





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## DETAIL SHEET

Span No: 3

Bridge No: 3125

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	JAR	JAR	JAR	JAR	JAR							

Abutment 1 End	H Diameter (mm)	400	510	500	470	470	540	460						
	V Measurement (mm)	370	370	370	370	370	370	370						
	Drill Vertical	Solid (B)	370	370	100	200	370	370						
		Rot												
		Pipe			100	60								
		Rot												
		Solid (T)			170	110								
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd												
Mid Span		H Bolt Rqd												
	Propped													
	Condition State		1	1	2	2	1	1						

Mid Span	H Diameter (mm)	380	490	500	480	460	580	470						
	V Measurement (mm)	460	540	520	500	510	570	510						
	Drill Vertical	Solid (B)	460	480	170	480	480	480						
		Rot												
		Pipe			120									
		Rot												
		Solid (T)			190									
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd												
Abutment 2 End		H Bolt Rqd												
	Propped													
	Condition State		1	1	2	1	1	1						

Abutment 2 End	H Diameter (mm)	530	590	580	560	600	610	520						
	V Measurement (mm)	380	380	380	380	380	380	380						
	Drill Vertical	Solid (B)	380	130	0	380	380	380						
		Rot												
		Pipe		130	340									
		Rot												
		Solid (T)		120	40									
	Drill Horiz.	Left			80									
		Right			80									
	Split	V Bolt Rqd												
Abutment 2 End		H Bolt Rqd												
	Propped													
	Condition State		1	2	4	1	1	1						

Cond. of Spiking Plank Not Applicable ☒ Size V  Condition S  R  %

Cond. of Decking (Solid/Rot) S  90 R  10 % Cond. of Deck Ends S  R  %

Decking Size (mm) V  120 x H  230 Decking Timber Type JAR

Span Length from Centreline Supports (m)  5.67 Clear Span Length  4.82 Saturated stringers:

Deck Condition State Condition 1  Condition 2  90 Condition 3  Condition 4  10 Spiral Grain Stringers:


Comments: STR 7 HAS S.G. ACTIVE TERMITES IN STR 3.

STR 1, AB 2 END REQD PACKING. STR 6, AB 2 REQD PACKING. } PACK

STR 3, AB 2 END REQD URGENT ATTENTION - ALREADY PROPPED REQD REPAIR

BOLT AS INDICATED





Page intentionally left blank



**Bridge 4551**  
**Tarwonga Road over**  
**Wangelling Gully**  
**L2 Inspection**





Enquiries: Gavin Johnston on 9323 4431  
Our Ref: 04/7524  
Your Ref:



ABN: 50 860 676 021

## ASSET MANAGER STRUCTURES WHEATBELT REGION

Structure No.: 4551  
Over: Wangelling Gully  
On: Tarwonga Rd (4190004)  
SLK: 22.78  
LGA: Shire of Narrogin

1. Please find enclosed a copy of the Detailed Inspection Report for the above Local Authority structure.
2. Attached is a schedule of maintenance items that are required to be undertaken in order to maintain structural integrity and extend the life of the Structure.
3. The maintenance items have been entered into IRIS for programming purposes.

Reviewed by:

Mark Billings  
SENIOR STRUCTURAL ENGINEER AECOM

Issued by:

Gavin Johnston  
BRIDGE CONDITION MANAGER

Don Aitken Centre, Waterloo Crescent, East Perth or PO Box 6202 EAST PERTH Western Australia 6892  
Telephone: (08) 9323 4111 Facsimile: (08) 9323 4136 TTY: (08) 9428 2230  
Email: [dac@mainroads.wa.gov.au](mailto:dac@mainroads.wa.gov.au) Website: [www.mainroads.wa.gov.au](http://www.mainroads.wa.gov.au)



## DETAILED TIMBER BRIDGE INSPECTION SUMMARY

Bridge No:	4551	Region:	WHEATBELT REGION
River Name:	Wangelling Gully	SLK:	22.78
Road:	Tarwonga Rd	Road No:	4190004
LGA:	Shire of Narrogin		

### 1.0 General

Bridge no.4551 located on Tarwonga Rd in the Shire of Narrogin is a four span bridge crossing Wangelling Gully. Generally this bridge is in good condition and requires routine and specific maintenance.

### 2.0 Preventative Maintenance

Preventative maintenance to be undertaken on a 5 year periodic basis. Areas of concern have been identified below, Carry out fastener maintenance in accordance with specification 850.35.

### 3.0 Routine Maintenance

Vegetation and Debris clearing shall be undertaken as outlined in report in accordance with specification 850.93.08.  
Correct road surface on bridge deck and approaches as outlined in report.  
Replace signs and lights as outlined in report.

### 4.0 Specific Maintenance

#### 4.1 Substructure

Pack halfcaps as outlined in report.  
(Pier 3: Pile 1)  
Halfcap repair and replacement as outlined in report in accordance with specification 850.32  
(Tighten Pier 1 halfcap and repair racking over of halfcap in Pier 1 and 3)  
Band and or seal timber pile splits as detailed in the report in accordance with Document No. 6706-02-2226, Preventive Maintenance Standards.  
(Abut 1: Piles 4, 5, 10; Pier 1: Piles 2, 4; Pier 2: all piles, 2 bands on Pile 1; Pier 3: Pile 3; Abut 2: Piles 3, 8)  
Undertake timber abutment repairs as outlined in report.  
(Large gaps and wingcap in poor condition on Abut 1 RHS wingwall; Wingcaps on Abut 2 require reattachment)  
Undertake pile repairs as outlined in report in accordance with specification 850.31.  
(Abut 2 Pile 9 leaning forward)

#### 4.2 Superstructure


Bolt and or seal corbels as outlined in report in accordance with specification 850.30 and Document No. 6706-02 2226, Preventive Maintenance Standards.  
(Halfmoon washer of Pier 1 Corbel 6 A2 end not making contact)  
Shim corbels as outlined in report  
(Pier 1: Corbel 3 A1, Corbel 2 A2; Pier 3: Corbel 3 A2)  
Shim stringers as outlined in report  
(Span 1: Stringer 1 A2, Stringer 6 A2; Span 4: Stringer 7 A1, Stringer 4 A2)

### 5.0 BCI

25.9

### 6.0 Load Rating

Not required.

  
Bruna Rocha  
Engineer Bridges

March 8 2019

**WORK ITEMS - TIMBER BRIDGES**  
**BRIDGE No: 4551**

ITEM NO	ITEM DESCRIPTION	WORK REQD	PRIORITY CODE	COMMENTS
---------	------------------	-----------	---------------	----------

**(A) GENERAL MAINTENANCE**

G005	Bridge - Durability Survey (L3)			
G009	Bridge - Load Rating			
G010	Bridge - Monitor Defect	Y	1	Abut 2 halfcap split between Pile 7 and 8; Settlement of Pier 1 Pile 2; Sagging of Pier 3 A2 Halfcap

**(B) PREVENTATIVE MAINTENANCE**

P101	Bridge - Seal Timber			
P102	Bridge - Maintain Fastener	Y	1	Pier 1
P103	Bridge - Fungicide Treatment			

**(C) ROUTINE MAINTENANCE**

	Bearing - Maintain			
	Bridge - Remove Graffiti			
	Bridge - Repair Scour (Minor)	Y	1	Pier 3 Pile 4: bottom of potted pile exposed; Abut 2
	Bridge - Eradicate Termites			
	Bridge - Clear Debris and Vegetation	Y	1	Trees and scrubs around bridge and debris built up on Pier 2 and 3
	Deck Joint - Maintain			
	Deck Surface - Maintain	Y	1	Minor cracking and depression on both abutments and hole at Abut 1 RHS
	Drainage - Maintain			
	Expansion Joint - Maintain			
	Fence - Remove			
	Fence - Repair (Control of Access)			
	Guardrail Maintain/Repair			
	Kerb - Repair (Minor) - Non Structural			
	Lighting - Maintain			
	Sign - Maintain	Y	1	Width markers at Abut 1 RHS and Abut 2 LHS are in poor condition

**(D) SPECIFIC MAINTENANCE**

S315	Bridge - Replace Fastener <1.5m			
S350	Bridge - Repair Scour (Major)			
S366	Bridge - Access - Improve			
S413	Deck - Repair			
S437	Decking - Repair (Timber)			
S449	Drainage - Repair			
S455	Expansion Joint - Repair			
S461	Footpath - Repair			
S501	Abutment - Reconstruct			
S504	Abutment - Repair (Non timber)			
S507	Bedlog - Repair			
S510	Bedlog - Shim			
S522	Corbel - Bolt	Y	2	Halfmoon washer of Pier 1 Corbel 6 A2 not making contact
S525	Corbel - Repair			
S528	Corbel - Shim	Y	2	Pier 1: Corbel 3 A1, Corbel 2 A2; Pier 3: Corbel 3 A2
S537	Footpath Railing - Repair			
S540	Fullcap - Repair			
S543	Halfcap - Improve Bearing			
S546	Halfcap - Pack	Y	2	Pier 3: Pile 1
S549	Halfcap - Repair	Y	2	Tightening: Pier 1 / Racking: Pier 1 and 3
S558	Pier - Repair			
S561	Pile - Band	Y	2	Abut 1: Piles 4, 5, 10; Pier 1: Piles 2, 4; Pier 2: all piles, 2 bands on Pile 1; Pier 3: Pile 3; Abut 2: Piles 3, 8
S564	Pile - Repair	Y	3	Abut 2 Pile 9
S570	Sheeting - Repair	Y	2	Large gaps and wingcap in poor condition on Abut 1 RHS wingwall/ Wingcaps on Abut 2 require reattachment
S576	Tie Back - Repair			
S607	Bearer - Repair			
S643	Joist - Repair			
S655	Stringer - Bolting			
S661	Stringer - Repair			
S667	Stringer - Shim	Y	2	Span 1: Stringer 1 A2, Stringer 6 A2; Span 4: Stringer 7 A1, Stringer 4 A2

**PRIORITY CODE**

0 - Critical Safety Deficiency : EMERGENCY action required (Immediate or within 6 months)

1 - Very High Priority (Within 3 years)

2 - Medium Priority (Within 4 years)

3 - Low Priority (Within 5 years-assess again at next Detailed Inspection)

**Bridge Number** **4551**

In conjunction with the Detailed Level 2 Bridge Inspection Report (as dated below), a Bridge Condition Index (BCI) has been calculated for this Bridge. The BCI assigns a numerical value to a bridge that is indicative of its condition and provides a relative condition in comparison with other timber bridges (BCI calculation is only applicable for timber bridges). The BCI rating system is a tool to provide a systematic approach for the determination of bridge condition by bridge inspection alone.

The process for determining the BCI is outlined in the Timber Bridge Condition Index User Guide. The BCI is primarily calculated utilising Condition States which are assigned based on the Level 2 Bridge Inspection Report (see attached).

A summary of the condition states and the calculated BCI for this bridge is provided below.

Condition States from Detailed Inspection Report conducted on 16-01-2019

		Condition State - Distribution (%)					
LOCATION	Weighting	CS1	CS2	CS3	CS4	Ave AGR	BCI
Condition State Weighting		1	3	9	11		
Stringers	11	89.4	9.4	1.2	0.0	22.5	<u>25.9</u>
Pier Piles	11	50.1	49.9	0.0	0.0		
Abutment Piles	11	55.3	44.7	0.0	0.0		
Halfcaps	11	0.0	100.0	0.0	0.0	15.0	
Corbels	6	0.0	100.0	0.0	0.0		
Timber Decking	6	90.0	0.0	0.0	10.0	8.4	
Wing Piles	3	58.0	34.4	7.6	0.0		
Abutment Sheeting	3	0.0	96.3	0.0	3.8		

Descriptor	BCI Range
Very Good	0 - 19
Good	20 - 39
Fair	40 - 55
Poor	56 - 100
Severe	101 +

BCI Descriptor Range (Refer Table 5.1 Doc No. 6706/02/2232)

Comments:

Prepared by: Bruna Rocha

Date: 24/01/2019



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GENERAL INFORMATION - SHEET 1

Bridge No.: 4551

Region:	<u>Wheatbelt</u>	Latitude (S):	<u>-33.14436</u>
		Longitude (E):	<u>117.05573</u>
Road Name:	<u>Tarwonga Rd</u>	Road No.:	<u>4180204</u>
Local Government:	<u>Narrogin</u>	Owner:	<u>Local Authority</u>
Crossing Name:	<u>Wangelling Gully</u>	SLK:	<u>22.78</u>
Number of Lanes:	<u>2</u>	Length (m):	<u>24.6 m</u>
Total Width (m):	<u>7.77</u>	Max. Head Room (m):	<u>4.60</u>
Inc. Footpath		Min. Head Room (m):	<u>2.50</u>
No. of Spans:	<u>4</u>	Width between Kerbs (m):	<u>7.17</u>
		Concrete Overlay (Y/N):	<u>Y (130mm)</u>


Piers are numbered along the bridge in ascending order from ABUTMENT 1 to ABUTMENT 2.

Piles are numbered across the bridge in ascending order from LEFT to RIGHT.

Stringers are numbered across the bridge in ascending order from LEFT to RIGHT.

Inside and outside kerb depths noted in corners of sketch.

Exposed Deck Ends (RCO only): LHS ☒ RHS ☒



This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Timber Bridge Detailed Inspection Guidelines.

Inspected by: J.P.A.R., L.M.O.N

Checked by: B. Rocha / M. Billings

Date: 15/1/19-16

Date: 6/02/2019

Drilled by: J. Pink, D. North





# SITE CONDITIONS

## Bridge No: 4551



<b>DRIVE THROUGH</b>	Visible Line of Sight from Abut. 1: 100m Visible Line of Sight from Abut. 1: 100m
<b>TRAFFIC CONTROL</b> (Describe if different to the generic TMP)	Abut. 1 end: } Abut. 2 end: } As per T.M.
<b>PARKING POSITION</b>	> 3 m <input type="checkbox"/> Position: 1.2 to 3 m <input checked="" type="checkbox"/> Position: On bridge behind truck T.M. 0 to 1.2 m <input type="checkbox"/> Position:
<b>ACCESS TO ABUTMENTS</b> (Describe access conditions at each wing)	Abutment 1: LHS: } RHS: } Steep banks OK Abutment 2: LHS: } RHS: } Steep banks OK Vegetation: Trees, scrub req clearing
<b>ACCESS TO PIERS</b> (Describe access conditions along each side of the structure)	LHS: } RHS: } Piers 2,3 in mud + water Vegetation: OK
<b>POTENTIAL HAZARDS</b>	Railing/Posts: Bolts: Services: Asbestos: Other: Steep banks
<b>FENCES</b>	Timber <input type="checkbox"/> Location: Wire/Mesh: <input type="checkbox"/> Location: Electrified: <input type="checkbox"/> Location: Barbed Wire: <input type="checkbox"/> Location: Other (Specify): <input type="text"/> Location:
<b>WATER</b>	Depth (m): 0.3m Flow Rate: Slow Algae: Yes (Access may be restricted by toxic algae) Tide: Location: Pier 2 + 3
<b>POWERLINES</b>	Side of bridge: Horizontal distance from edge of deck (m): None Estimated vertical height above deck (m):

Signature

Timber Bridge Detailed Inspection Guidelines

Doc 6706-02-2231 - Issue 21/02/2014

Bridges Asset Management Plan 2020-2030

Date

16/1/19



## GUARDRAIL INFORMATION

Bridge No.: 4551

### Barrier Type

None

RHS Rails      No. of Rails (on bridge):

Thriebeam

W Beam

Tric-Bloc Concrete Barrier

Reinforced Concrete Barrier (Type F)

Constant Slope Concrete Barrier

Other Concrete Profiles

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS
X		X	X		X	X		X

### Post Type

None

Concrete

Timber

Steel Type: Parallel Flange Channel (PFC)

[Types: C-Section (C), I Section (I), RHS (R), Square Hollow Section SHS (S), Tubular (T), Steel PFC (PFC), Steel Channel (Ch)]

X		X	X		X	X		X

Off bridge:

Number of Posts off Bridge

Length of Barrier off Bridge (m)

7		4				4		7
12.7		6.8				6.8		12.7

### Visibility Barrier

Timber      No. of Rails (on bridge):

Steel Pipe(s)      No. of Pipes (on bridge):

Guide Posts

Balustrade

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS

### Top Rails

Steel Pipe

Steel RHS/Channel

Steel C Section

Timber

X		X	X		X	X		X

### End Terminals

Approved End Terminal Types:

WAMELT

SKT-350

ET-2000

X Tension

TAU II Crash Cushion

Other:

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS				LHS	Median	RHS

Other End Terminal Types:

None

Turn-down

Bullnose

Fishtail

Other

X		X				X		X

Structural problem found? (Y/N)

N	If yes, comment below.
---	------------------------



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## ROUTINE INFORMATION

Bridge No.: 4551

SCUPPERS LOCATION, TYPE & CONDITION (R208)		None <input type="checkbox"/> LHS <input checked="" type="checkbox"/> RHS <input checked="" type="checkbox"/>	Box <input type="checkbox"/> PVC pipe <input checked="" type="checkbox"/> Hole in deck <input type="checkbox"/>
			Through Deck <input checked="" type="checkbox"/> Through Kerb <input type="checkbox"/>
		Spoon drains A1 + A2 LHS + RHS	
FLASHING TYPE & CONDITION (R208)		None <input type="checkbox"/>	PVC pipe <input checked="" type="checkbox"/> PGI <input type="checkbox"/>
BOLT TIGHTENING REQUIRED (P102)		Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
TERMITES (R204)		Active <input type="checkbox"/>	Not Active <input checked="" type="checkbox"/>
PREVENTATIVE FUNGICIDE (P103)		Treated <input checked="" type="checkbox"/>	Not Treated <input type="checkbox"/>
ATTACHED FENCES & OTHER WATERWAY OBSTRUCTIONS (R210)		None	
ROAD SURFACE & KERBING CONDITION (R207)	ON BRIDGE	Road Surface: Concrete, OK	
		Kerbing: Concrete, OK	
	APPROACHES	Road Surface: Bitumen seal minor cracking and depressions A1 + A2, Small hole A1 RHS see photo 34	
		Kerbing: Concrete - OK	
VEGETATION (R205)		Requires Clearing : LHS <input checked="" type="checkbox"/> Abut 1 <input checked="" type="checkbox"/> RHS <input checked="" type="checkbox"/> Abut 2 <input checked="" type="checkbox"/> Trees, scrub REMOVE	
STREAM BED CONDITION (General comments and details of location, depth & extent of scour, undermining and silt build up.) (R203)		Debris buildup pier 2+3 RHS	
SERVICES (Type, Size & Location)		Type	Size (mm)
		Location	
		None	
BRIDGE CONDITION		Priority for Engineering Assessment	
		Low <input checked="" type="checkbox"/>	Medium <input type="checkbox"/> High <input type="checkbox"/> Urgent <input type="checkbox"/>

Comments:





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GENERAL INFORMATION - SHEET 2

Bridge No.: 4551

### Bridge Status

Built/In Use ☒

Not Used ☐

Date Built 01/06/1973

Skew (angle) \_\_\_\_\_

Skewed Width (m) \_\_\_\_\_

### Widening

Left Hand side ☒ Width (m) 0.40

Date \_\_\_\_\_

Right Hand side ☒ Width (m) 0.40

Date \_\_\_\_\_

### Surface Type

Unsurfaced ☒

Bitumen Seal ☐

Asphalt ☐

Rubberised Seal ☐

Tiles ☐

Steel Plate ☐

### Pavement Type

Unpaved ☐

Gravel ☐

Material Unknown ☒

### Footpath Left

Left Kerb (m) 0.30

Path (m) \_\_\_\_\_

Right Kerb (m) \_\_\_\_\_

### Footpath Right

Left Kerb (m) \_\_\_\_\_

Path (m) \_\_\_\_\_

Right Kerb (m) 0.30

### Median

Left Kerb (m) \_\_\_\_\_

Median (m) \_\_\_\_\_

Right Kerb (m) \_\_\_\_\_

### Bridge Function 1

Road Bridge ☒

Rail Bridge ☐

Pedestrian Bridge ☐

### Bridge Function 2

Over Water ☒

Over Road ☐

Over Rail ☐

Over Road & Rail ☐

Over Road & Water ☐

Over Rail & Water ☐

Stock Underpass ☐

Pedestrian Underpass ☐

## SIGNAGE

### Load Limits

Abutment 1 End  Tonne

Abutment 2 End  Tonne

### Width Markers

Abutment 1 LHS 2 RHS 3

Abutment 2 LHS 3 RHS 2

Is position of Width Markers a true indication of the bridge width? (Y/N) ☒ Y

### Other Signs

No Overtaking or Passing

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

No Overtaking on Bridge

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

One Lane Bridge

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

Low Clearance .....m

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

Narrow Bridge Sign

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

Give Way

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

### Crossing Sign:

### Other

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

### Signage Condition Legend

Good

1

Poor

3

Not Required

☐

Fair

2

None (missing)

4




## ELEMENT SPACING SHEET 1

Bridge No.: 4551

### Abutment 1


All measurements (cumulative) are taken from the reference point as indicated by the star ☆

#### LHS Wing Wall Layout




#### Abutment Abutment Pile Centres

Mark in RHS edge of deck and dimension to outside pile.



#### RHS Wing Wall Layout




### Abutment 2

#### LHS Wing Wall Layout


All measurements (cumulative) are taken from the reference point as indicated by the star ☆

Mark in and dimension to corner of wing wall sheeting




#### Abutment Abutment Pile Centres

Mark in RHS edge of deck and dimension to outside pile.



#### RHS Wing Wall Layout



## ELEMENT SPACING SHEET 2


Bridge No.: 4551

All measurements (cumulative) are taken from the reference point as indicated by the star ☆


### Pier Pile Centres

Mark in RHS edge of deck and dimension last pile to RHS edge of deck.


PIER No. ....  
*Typical*



PIER No. ....



PIER No. ....




### Typical Stringer Spacing


Mark in RHS edge of deck and dimension last stringer to RHS edge of deck.

Note: Stringer spacings must be measured in every span with additional stringers. Use additional sheets as required.


SPAN No. ...  
*Typical*



SPAN No. ....



SPAN No. ....








# TIMBER BRIDGE DETAILED INSPECTION REPORT



ABUTMENT: 1

Bridge No: 4551



Pile No.	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Dia. (mm) below H/C (5m+)	Mat. Type	Tied Back	Cond. State
		Solid	Rot	Pipe	Drill Location from top H/C	Above	Below	Location	Requires Band	Marking (ft/m)	Height Top H/C to Blaze (m)	Height Blaze to GL (m)	A1	A2				
1	400	See notes			4	10 Top	5			-	2	-	-	-	-	JAR		3
2	400	200						-		-	1.2	-	-	-	-	JAR		2
3	470	235						-		-	2.2	-	-	-	-	JAR		2
4	360	180						-	✓	-	3.0	-	-	-	-	JAR		2
5	380	190						-	✓	-	3.6	-	-	-	-	JAR		2
6	410	205								-	3.1	-	-	120	-	JAR		2
7	360	180						-		-	3.0	-	-	170	-	JAR		2
8	420	210						-		-	3.0	-	-	170	-	JAR		2
9	350	125		50	1.5					-	3.0	-	-	140	-	JAR		2
10	400	200						-	✓	-	3.1	-	-	130	-	JAR		2
11	390	195								-	3.6	-	-	-	-	JAR		2
12	370	185						-		-	2.6	-	-	-	-	JAR		2
13	400	200								-	1.8	-	-	-	-	JAR		2
14	450	See notes			3	To Top	5			-	3	-	-	-	-	JAR		3
15																		

Saturated Piles:

**LHS Halfcaps** Size V 340 H 170 Length 8500 No. of 1 Gap between H/Caps -

Top of H/Caps to underside of Deck 370 Back of Halfcaps to Sheeting 250 H/Cap Material JAR

**RHS Halfcaps** Size V H Length  No. of  Gap between H/Caps

Top of H/Caps to underside of Deck  Back of Halfcaps to Sheeting  H/Cap Material

Are there more than 2 sets of halfcaps or sill beams (YES/NO) No (If yes record details on comments sheet)

Comments: Pile 5 has termite damage, and sheet 7 LHS w/wall none found

Pile No. <u>1</u> R.H.S. <u>108/s</u> L.H.S. <u>120/s</u> F= <u>120/s</u>	Pile No. <u>14</u> R.H.S. <u>160/s</u> L.H.S. <u>100/s</u> F= <u>120/s</u>	Pile No. <u></u> R.H.S. <u></u> L.H.S. <u></u> F= <u></u>	Pile No. <u></u> R.H.S. <u></u> L.H.S. <u></u> F= <u></u>
---------------------------------------------------------------------------------	----------------------------------------------------------------------------------	-----------------------------------------------------------------	-----------------------------------------------------------------









# TIMBER BRIDGE DETAILED INSPECTION REPORT



PIER No: 1

Bridge No: 4551

Pile No.	Circ. (mm)	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Circ. (mm) below H/C (5m+)	Mat. Type	Cond. State
			Solid	Rot	Pipe	Drill Location from top H/C	Below	Above	Location	Requires Band	Marking (ft/m)	Height Top H/C to Blaze (m)	Height Blaze to GL (m)	A1	A2			
1	1130	360	180						iii		-	3.3	-	100	170	-	JAR	2
2	1260	400	180		20	2.8			✓	✓	-	3.2	-	170	100	-	JAR	2
3	1100	350	175						✓		-	3.0	-	170	170	-	JAR	2
4	1320	420	210						✓	✓	-	2.8	-	140	150	-	JAR	2
5																		
6																		
7																		
8																		
9																		
10																		

Total Number of Corbels: 7

Typical Corbel Height (mm): LHS 320 RHS 320

Corbel No:

Material Type:

Requires Bolting:

Condition State:

A1/A2 End

A1/A2 End

1	2	3	4	5	6	7	8	9	10	11	12	13	14
JAR	JAR	JAR	JAR	JAR	JAR	JAR							
-	-	-	-	-	-	-	-	-	-	-	-	-	-
2	2	2	2	2	2	2	2	2	2	2	2	2	2

Ironwork Condition: Minor Rust

Tightening Required:

YES

Walers

Size

V

—

x

H

—

Bracing

Size

V

—

x

H

—

Saturated Piles:

LHS Halfcaps

Size

V

340

H

170

Length

7300

No. of

2

Gap between H/Caps

ISO

Top of H/Caps to underside of Deck

720

H/Cap Material

JAR

RHS Halfcaps

Size

V

—

H

—

Length

—

No. of

—

Gap between H/Caps

—

Top of H/Caps to underside of Deck

—

H/Cap Material

—





Are there more than 2 sets of halfcaps or sill beams (YES/NO)

No

(If yes record details on comments sheet)

Comments:

CORBEL 3 A1 REQ PACKING - SEE PHOTO 13  
H/C REQ TIGHTENING. A2 H/C HAS 25mm GAP BETWEEN PILE 1 + 3. A2 H/C HAS ROLLED OUT FROM PILE, 35mm GAP BETWEEN PILE + H/C AND 10mm ON BOTTOM OF H/C.  
CORBEL 2 A2 repacking Pile 2 A1 H/C req packing (Photo 19). Corbel 6 A2 halfmooring washer not making contact (Photo 18)  
not required

Pile No.: <u>—</u> A2 <u>—</u> LHS <u>—</u>  RHS <u>—</u> A1 <u>—</u>	Pile No.: <u>—</u> A2 <u>—</u> LHS <u>—</u>  RHS <u>—</u> A1 <u>—</u>	Pile No.: <u>—</u> A2 <u>—</u> LHS <u>—</u>  RHS <u>—</u> A1 <u>—</u>	Pile No.: <u>—</u> A2 <u>—</u> LHS <u>—</u>  RHS <u>—</u> A1 <u>—</u>
-------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------





# TIMBER BRIDGE DETAILED INSPECTION REPORT



PIER No: 2

Bridge No: 4551

Pile No.	Circ. (mm)	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Circ. (mm) below H/C (5m+)	Mat. Type	Cond. State
			Solid	Rot	Pipe	Drill Location from top H/C	Below	Above	Location	Requires Band	Marking (ft/m)	Height Top H/C to Blaze (m)	Height Blaze to GL (m)	A1	A2			
1	1130	360	130		50	2.3			✓	✓	-	4.2	-	140	140	-	JAR	2
2	1225	390	195						✓	✓	-	4.2	-	130	150	-	JAR	2
3	1160	370	185						✓	✓	-	4.2	-	170	100	-	JAR	2
4	1160	370	155		30	2.8			✓	✓	-	4.2	-	120	130	-	JAR	2
5																		
6																		
7																		
8																		
9																		
10																		

Total Number of Corbels: 7

Typical Corbel Height (mm): LHS 320 RHS 320

Corbel No:

Material Type:

Requires Bolting:

Condition State:

A1/A2 End

A1/A2 End

1	2	3	4	5	6	7	8	9	10	11	12	13	14
JAR	JAR	JAR	JAR	JAR	JAR	JAR							
-	-	-	-	-	-	-	-	-	-	-	-	-	-
2	2	2	2	2	2	2	2	2	2	2	2	2	2

Ironwork Condition: Minor Rust

Tightening Required:

No

Walers Size V — x H —

Bracing Size V — x H —

Saturated Piles:

LHS Halfcaps Size V 340 H 170 Length 7300 No. of 2 Gap between H/Caps 150

Top of H/Caps to underside of Deck 720 H/Cap Material JAR

RHS Halfcaps Size V — H — Length — No. of — Gap between H/Caps —

Top of H/Caps to underside of Deck — H/Cap Material —

Are there more than 2 sets of halfcaps or sill beams (YES/NO) No (If yes record details on comments sheet)

Comments:

Unable to drill pile 4 at ground level large amount of debris  
Pier 2 Corbel 7 A1 req. packing (Photo 25).

Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____
-------------------------------------------------------------------	-------------------------------------------------------------------	-------------------------------------------------------------------	-------------------------------------------------------------------





# TIMBER BRIDGE DETAILED INSPECTION REPORT



PIER No: 3

Bridge No: 4551

Pile No.	Circ. (mm)	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Circ. (mm) below H/C (5m+)	Mat. Type	Cond. State
			Solid	Rot	Pipe	Drill Location from top H/C	Below	Above	Location	Requires Band	Marking (ft/m)	Height Top H/C to Blaze (m)	Height Blaze to GL (m)	A1	A2			
1	1130	360	180								-	3-2	-	110	150	-	JAR	2
2	1290	410	205								-	3-3	-	100	130	-	JAR	2
3	1290	410	205						✓	✓	-	3-2	-	160	110	-	JAR	2
4	210	UC	Potted			11mm					-	2-9	-	170	170	-	STE	1
5																		
6																		
7																		
8																		
9																		
10																		

Total Number of Corbels: 7

Typical Corbel Height (mm): LHS 320 RHS 320

Corbel No:

Material Type:

Requires Bolting:

Condition State:

A1/A2 End

A1/A2 End

1	2	3	4	5	6	7	8	9	10	11	12	13	14
JAR	JAR	JAR	JAR	JAR	JAR	JAR	JAR						
All bolted													
2	2	2	2	2	2	2	2	2					

Iron work Condition: Minor Rust

Tightening Required: No

Walers Size V - x H -

Bracing Size V - x H -

Saturated Piles:

LHS Halfcaps Size V 340 H 170 Length 7300 No. of 2 Gap between H/Caps 150

Top of H/Caps to underside of Deck 720 H/Cap Material JAR

RHS Halfcaps Size V - H - Length - No. of - Gap between H/Caps -

Top of H/Caps to underside of Deck - H/Cap Material -

Are there more than 2 sets of halfcaps or sill beams YES/NO No (If yes record details on comments sheet)

Comments: Corbel 7 A2 req packing (photo 30) -> small gap - not required  
15mm SAG IN A1 H/C BETWEEN PILE 1 + 3.

40mm SAG IN A1 H/C FROM PILE 3 TO R.H.S

BOTH H/C RACKING OVER, A2 H/C SAG BETWEEN PILE 1 + 2 (Ph 28)


pile 4 bottom of pot is exposed due to scour see photo 33

Corbel 3 A2 req packing (Photo 21) Pier 3 H/C packing req Pile 1 (Ph 24)

Pile No.: <u>      </u> A2 <u>      </u> LHS <u>      </u> RHS <u>      </u> A1 <u>      </u>	Pile No.: <u>      </u> A2 <u>      </u> LHS <u>      </u> RHS <u>      </u> A1 <u>      </u>	Pile No.: <u>      </u> A2 <u>      </u> LHS <u>      </u> RHS <u>      </u> A1 <u>      </u>	Pile No.: <u>      </u> A2 <u>      </u> LHS <u>      </u> RHS <u>      </u> A1 <u>      </u>
--------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------



ABUTMENT: 2



Bridge No: 4551

Pile No.	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Dia. (mm) below H/C (5m+)	Mat. Type	Tied Back	Cond. State
		Solid	Rot	Pipe	Drill Location from top H/C	Above	Below	Location	Requires Band	Marking (Ft/m)	Height Top H/C to Blaze (m)	Height Blaze to GL (m)	A1	A2				
1	400	140		60	0.7			✓		-	3	-	-	-	-	JAR		2
2	350	SEE NOTES			1.8	TOP	5	✓		-	1.6	-	-	-	-	JAR		3
3	350	175						✓	✓	-	2.8	-	-	-	-	JAR		2
4	360	180						✓		-	3.1	-	-	-	-	JAR		2
5	210	UC Potted			11mm					-	2.5	-	170	-	-	STE		1
6	400	200						✓		-	2.6	-	140	-	-	JAR		2
7	360	180						✓		-	3.0	-	100	-	-	JAR		2
8	420	210						✓	✓	-	2.8	-	120	-	-	JAR		2
9	370	185						✓		-	2.7	-	100	-	-	JAR		2
10	360	180						✓		-	2.7	-	-	-	-	JAR		2
11	400	SEE NOTES			1.6	TOP	5	✓		-	1.4	-	-	-	-	JAR		3
12	370	SEE NOTES			2			✓		-	2	-	-	-	-	JAR		2
13																		
14																		
15																		

Saturated Piles:

**LHS Halfcaps** Size V 340 170 Length 6250 No. of 1 Gap between H/Caps ---  
 Top of H/Caps to underside of Deck 370 Back of Halfcaps to Sheeting 290 H/Cap Material JAR  
**RHS Halfcaps** Size V H Length --- No. of --- Gap between H/Caps ---  
 Top of H/Caps to underside of Deck --- Back of Halfcaps to Sheeting --- H/Cap Material ---  
 Are there more than 2 sets of halfcaps or sill beams (YES/NO) No (If yes record details on comments sheet)

Comments:

SCORE AT ABUT FACE. SEE PHOTO 8  
 Halfcap → split between Pile 7 and 8 (Photo 32) → not severe MONITOR  
 Pile 9: seems to be leaning forward → also creating gap between Pile and H/C. (audit photos) → TIE BACK TO SHEETING


Pile No. <u>2</u> L.H.S. <u>100/s</u> R.H.S. <u>180/s</u> F= <u>110/s</u>	Pile No. <u>11</u> L.H.S. <u>200/s</u> R.H.S. <u>160/s</u> F= <u>180/s</u>	Pile No. <u>12</u> L.H.S. <u>150/s</u> R.H.S. <u>150/s</u> F= <u>120/s</u>	Pile No. <u>---</u> L.H.S. <u>---</u> R.H.S. <u>---</u> F= <u>---</u>
---------------------------------------------------------------------------------	----------------------------------------------------------------------------------	----------------------------------------------------------------------------------	-----------------------------------------------------------------------------



## ABUTMENT 2 and WING WALL SHEETING

Bridge No: 4551

### ABUTMENT 2 SHEETING (indicate ground line, piles and failed sheeting)



SHEETING - ABUTMENT LHS

Solid

Rot from Pile

7

To Pile

8

Centreline

Solid

11+12 u/r

Rot from Pile

To Pile

RHS

Solid

Rot from Pile

To Pile

SHEETING Material Type

J

SHEETING Material Size (mm)

Vertical

220

Depth

80

Condition 1

Condition 2

Condition 3


Condition 4

% Condition State

95

5

### ABUTMENT 2 WING WALLS (indicate ground line, piles and failed sheeting)



WINGCAP / SPIKING RAIL CONDITION

WEATHERED + SPLIT - OK

BOTTOM SECTION HAS COME OFF  
REQ RE ATTACHMENT.

WINGCAP / SPIKING RAIL CONDITION

WEATHERED + SPLIT - OK

HAS COME OFF - REQ RE ATTACH

SHEETING - WING WALLS LHS

Solid

Rot from Pile

To Pile

RHS

Solid

Rot from Pile

To Pile

SHEETING Material Type

J

SHEETING Material Size (mm)

Vertical

220

Depth

80

Condition 1

Condition 2

Condition 3

Condition 4

% Condition State

100



## DETAIL SHEET

Span No: 1

Bridge No: 4551

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	JAR	JAR	JAR	JAR	JAR							
H Diameter (mm)	410	560	530	550	540	400	420							
V Measurement (mm)	370	370	370	370	370	370	370							
Abutment 1 End	Drill Vertical	Solid (B)	130	370	370	370	370	160	370					
		Rot												
		Pipe	80					70						
		Rot												
		Solid (T)	160					140						
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd	-	-	-	✓	-	-						
		H Bolt Rqd												
	Propped													
	Condition State		2	1	1	1	1	2	1					

H Diameter (mm)	420	540	530	460	600	400	460							
V Measurement (mm)	470	480	500	460	500	420	500							
Mid Span	Drill Vertical	Solid (B)	470	480	480	460	480	120	190					
		Rot												
		Pipe						220	90					
		Rot												
		Solid (T)						80	200					
	Drill Horiz.	Left						190						
		Right						110						
	Split	V Bolt Rqd	✓											
		H Bolt Rqd							✓					
	Propped													
	Condition State		1	1	1	1	1	2	2					

H Diameter (mm)	470	500	550	400	610	390	480							
V Measurement (mm)	400	400	400	400	400	400	400							
Abutment 2 End	Drill Vertical	Solid (B)	400	400	400	400	400	400	400					
		Rot												
		Pipe												
		Rot												
		Solid (T)												
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd	✓		-				-					
		H Bolt Rqd							✓					
	Propped													
	Condition State		1	1	1	1	1	1	1					

Cond. of Spiking Plank Not Applicable ☒ Size V  Condition S  R  %

Cond. of Decking (Solid/Rot) S  R  % Cond. of Deck Ends S  R  %

Decking Size (mm) V  x H  Decking Timber Type

Span Length from Centreline Supports (m)  Clear Span Length  Saturated stringers: \_\_\_\_\_

Deck Condition State Condition 1  Condition 2  Condition 3  Condition 4  Spiral Grain Stringers:

Comments: STR 1 REQ PACKING SEE PHOTO - Abut 2 - Photo 15

Stringer 6 Abut 2 requires packing - Photo 14

NO BOLTS REQUIRED





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## DETAIL SHEET

Span No: 2

Bridge No: 4551

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	JAR	JAR	JAR	JAR	JAR							

Abutment 1 End	H Diameter (mm)	600	500	550	440	550	430	570						
	V Measurement (mm)	400	400	400	400	400	400	400						
	Drill Vertical	Solid (B)	400	400	400	400	400	400						
		Rot												
		Pipe												
		Rot												
		Solid (T)												
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd	-	-	-	-	-	✓						
		H Bolt Rqd												
	Propped													
	Condition State		1	1	1	1	1	1						

Mid Span	H Diameter (mm)	480	550	530	490	500	460	540						
	V Measurement (mm)	440	460	480	500	450	450	480						
	Drill Vertical	Solid (B)	290	460	290	480	450	450	480					
		Rot	180											
		Pipe			100									
		Rot												
		Solid (T)	0		90									
	Drill Horiz.	Left	180											
		Right	200											
	Split	V Bolt Rqd	✓											
		H Bolt Rqd												
	Propped													
	Condition State		3	1	2	1	1	1	1					

Abutment 2 End	H Diameter (mm)	410	600	500	530	460	500	470						
	V Measurement (mm)	400	400	400	400	400	400	400						
	Drill Vertical	Solid (B)	400	400	400	400	400	400						
		Rot												
		Pipe												
		Rot												
		Solid (T)												
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd	✓		✓									
		H Bolt Rqd												
	Propped													
	Condition State		1	1	1	1	1	1	1					

Cond. of Spiking Plank Not Applicable ☒ Size V - Condition S - R - %

Cond. of Decking (Solid/Rot) S 90 R 10 % Cond. of Deck Ends S 90 R 10 %

Decking Size (mm) V 127 x H 220 Decking Timber Type JAR

Span Length from Centreline Supports (m) 6.13 Clear Span Length 4.70 Saturated stringers: \_\_\_\_\_

Deck Condition State Condition 1 Condition 2 Condition 3 Condition 4  
Percentage: 90   10 Spiral Grain Stringers: \_\_\_\_\_

Comments: NO BOLTS REQUIRED



## DETAIL SHEET

Span No: 3

Bridge No: 4551

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	JAR	JAR	JAR	JAR	JAR							

Abutment 1 End	H Diameter (mm)	460	420	540	430	470	560	480						
	V Measurement (mm)	400	400	400	400	400	400	400						
	Drill Vertical	Solid (B)	400	400	400	400	400	400						
		Rot												
		Pipe												
		Rot												
		Solid (T)												
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd	✓		-	-	-	-						
		H Bolt Rqd					✓							
	Propped													
	Condition State		1	1	1	1	1	1						

Mid Span	H Diameter (mm)	470	500	570	420	520	580	520						
	V Measurement (mm)	500	400	480	460	510	470	490						
	Drill Vertical	Solid (B)	480	400	480	460	480	470	480					
		Rot												
		Pipe												
		Rot												
		Solid (T)												
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd					✓							
		H Bolt Rqd												
	Propped													
	Condition State		1	1	1	1	1	1						

Abutment 2 End	H Diameter (mm)	540	560	630	470	510	550	560						
	V Measurement (mm)	400	400	400	400	400	400	400						
	Drill Vertical	Solid (B)	400	400	400	400	400	400						
		Rot												
		Pipe												
		Rot												
		Solid (T)												
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd	-	-	-	-	-	-						
		H Bolt Rqd												
	Propped													
	Condition State		1	1	1	1	1	1						

Cond. of Spiking Plank Not Applicable ☒ Size V - Condition S - R - %

Cond. of Decking (Solid/Rot) S 90 R 10 % Cond. of Deck Ends S 90 R 10 %

Decking Size (mm) V 127 x H 220 Decking Timber Type JAR

Span Length from Centreline Supports (m) 6.00 Clear Span Length 4.58 Saturated stringers: \_\_\_\_\_

Deck Condition State Condition 1 Condition 2 Condition 3 Condition 4

Percentage: 90   10 Spiral Grain Stringers: \_\_\_\_\_

Comments: Stringer 2 Abut 2 req packing (Photo 22) } NOT REQUIRED

Stringer 7 A2 req packing (Photo 26)

BOLTS NOT REQUIRED





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## DETAIL SHEET

Span No: 4

Bridge No: 4551

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	JAR	JAR	JAR	JAR	JAR							

H Diameter (mm)	550	530	600	450	520	480	560							
V Measurement (mm)	400	400	400	400	400	400	400							

Abutment 1 End	Drill Vertical	Solid (B)	400	400	400	400	400	400	400					
		Rot												
		Pipe												
		Rot												
		Solid (T)												
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd	-	-			-	✓	-					
		H Bolt Rqd												
	Propped													
	Condition State		1	1	1	1	1	1	1					

H Diameter (mm)	500	480	520	530	530	510	500							
V Measurement (mm)	500	490	510	450	440	530	470							

Mid Span	Drill Vertical	Solid (B)	240	480	480	450	440	480	470					
		Rot												
		Pipe	80											
		Rot												
		Solid (T)	160											
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd												
		H Bolt Rqd						✓						
	Propped													
	Condition State		2	1	1	1	1	1	1					

H Diameter (mm)	500	460	500	630	510	540	480							
V Measurement (mm)	370	370	370	370	370	370	370							

Abutment 2 End	Drill Vertical	Solid (B)	370	240	370	370	140	370	370					
		Rot												
		Pipe		20			30							
		Rot												
		Solid (T)		110			200							
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd	-				-	✓	-					
		H Bolt Rqd						✓						
	Propped													
	Condition State		1	2	1	1	2	1	1					

Cond. of Spiking Plank Not Applicable ☒ Size V  Condition S  R  %

Cond. of Decking (Solid/Rot) S  R  % Cond. of Deck Ends S  R  %

Decking Size (mm) V  x H  Decking Timber Type

Span Length from Centreline Supports (m)  Clear Span Length  Saturated stringers:

Deck Condition State Condition 1  Condition 2  Condition 3  Condition 4  Spiral Grain Stringers:

Comments: TRUSHOE PROP UNDER STR 1 AT END. - SEE PHOTO


Stringer 7 About 1 req packing (Photo 29)

Stringer 4 About 2 req packing (Photo 34)


BOLTS NOT REQUIRED




# TIMBER BRIDGE DETAILED INSPECTION REPORT



ROUND THE DIMENSIONS ON THE HALFCAP BEARING ON THE PILE AT BOTH ABUTMENT SIDES OF THE PILE i.e. ABUTMENT N° 1 & ABUTMENT N° 2



## HALFCAP SEATING ARRANGEMENTS



## LEGEND

### MATERIAL TYPE

- J - JARRAH
- W - WANDOO
- S - STEEL
- U - UNKNOWN TIMBER

### SPLITS

- ✓ TICK ONLY IF REQUIRED

### PRIORITY BOLT/BAND

- U - A.S.A.P.
  - H - HIGH PRIORITY
  - M - ROUTINE MAINTENANCE
  - L - LOW PRIORITY
- FOR AUDIT PURPOSES ONLY


### GENERAL

- P - PIPE
- R - ROT
- F - FRIABLE
- S - SOLID
- N/A - NOT APPLICABLE
- V - VERTICAL
- H - HORIZONTAL
- LHS - LEFT HAND SIDE
- RHS - RIGHT HAND SIDE
- Dia - PIPE DIAMETER
- Circ - CIRCUMFERENCE
- A1 - ABUTMENT No. 1
- A2 - ABUTMENT No. 2
- Str - STRINGER
- H/C - HALFCAP
- H/CAP - HALFCAP
- Blz - BLAZE
- CL - CENTRE LINE
- O/A - OVERALL
- GL - GROUND LEVEL
- Ht - HEIGHT
- Ft - FEET
- W - WIDTH BETWEEN WALING
- Cond - CONDITION
- U/S - UNSOUND (STRUCTURALLY)
- SG - SPIRAL GRAIN

NOTE: All dimensions are of solid timber excluding sap wood and any surface rot on piles and stringers

/SE Documents/Management System Manual/Dwgs/timber\_repair.dwg





Map 56

Page intentionally left blank



**Bridge 3122**  
**Tarwonga Road over**  
**Torbling Brook**  
**L2 Inspection**







Enquiries: Gavin Johnston on 9323 4431  
Our Ref: 04/4055  
Your Ref:



ABN: 50 860 676 021

## ASSET MANAGER STRUCTURES WHEATBELT REGION

Structure No.: 3122  
Over: Torbling Brook  
On: Tarwonga Rd (4190004)  
SLK: 2.82  
LGA: Shire of Narrogin

1. Please find enclosed a copy of the Detailed Inspection Report for the above Local Authority structure.
2. Attached is a schedule of maintenance items that are required to be undertaken in order to maintain structural integrity and extend the life of the Structure.
3. The maintenance items have been entered into IRIS for programming purposes.

Reviewed By:

Mark Billings  
SENIOR STRUCTURAL ENGINEER AECOM

19/3/2017

Issued By:

Gavin Johnston  
BRIDGE CONDITION MANAGER

22/3/17

Enc

**WORK ITEMS - TIMBER BRIDGES**  
**BRIDGE No: 3122**

ITEM NO	ITEM DESCRIPTION	WORK REQD	PRIORITY CODE	COMMENTS
---------	------------------	-----------	---------------	----------

**(A) GENERAL MAINTENANCE**

G005	Bridge - Durability Survey (L3)			
G009	Bridge - Load Rating			
G010	Bridge - Monitor Defect			

**(B) PREVENTATIVE MAINTENANCE**

P101	Bridge - Seal Timber			
P102	Bridge - Maintain Fastener			
P103	Bridge - Fungicide Treatment			

**(C) ROUTINE MAINTENANCE**

	Bearing - Maintain			
	Bridge - Remove Graffiti			
	Bridge - Repair Scour (Minor)			
	Bridge - Eradicate Termites			
	Bridge - Clear Debris and Vegetation			
	Deck Joint - Maintain			
	Deck Surface - Maintain			
	Drainage - Maintain	Y	1	spoon drains a1 & a2 LHS
	Expansion Joint - Maintain			
	Fence - Remove			
	Fence - Repair (Control of Access)			
	Guardrail Maintain/Repair			
	Kerb - Repair (Minor) - Non Structural	Y	1	a2 LHS
	Lighting - Maintain			
	Sign - Maintain			

**(D) SPECIFIC MAINTENANCE**

S315	Bridge - Replace Fastener <1.5m			
S350	Bridge - Repair Scour (Major)			
S366	Bridge - Access - Improve			
S413	Deck - Repair			
S437	Decking - Repair (Timber)			
S449	Drainage - Repair			
S455	Expansion Joint - Repair			
S461	Footpath - Repair			
S501	Abutment - Reconstruct			
S504	Abutment - Repair (Non timber)			
S507	Bedlog - Repair			
S573	Sillbeam - Repair	Y	2	Pier 1, knot hole
S522	Corbel - Bolt			
S525	Corbel - Repair			
S528	Corbel - Shim			
S537	Footpath Railing - Repair			
S540	Fullcap - Repair			
S543	Halfcap - Improve Bearing			
S546	Halfcap - Pack			
S549	Halfcap - Repair			
S558	Pier - Repair			
S561	Pile - Band			
S564	Pile - Repair			
S570	Sheeting - Repair			
S582	Waler - Replace			
S607	Bearer - Repair			
S643	Joist - Repair			
S655	Stringer - Bolting			
S661	Stringer - Repair			
S667	Stringer - Shim			

**PRIORITY CODE**

- 0 -Critical Safety Deficiency : EMERGENCY action required (Immediate or within 6 months)
- 1 - Very High Priority (Within 3 years)
- 2 - Medium Priority (Within 4 years)
- 3 - Low Priority (Within 5 years-assess again at next Detailed Inspection)

## DETAILED TIMBER BRIDGE INSPECTION SUMMARY

Bridge No:	3122	Region:	WHEATBELT REGION
River Name:	Torbling Brook	SLK:	2.82
Road:	Tarwonga Rd	Road No:	4190004
LGA:	Shire of Narrogin		

---

### 1.0 General

Bridge no. 3122 located on Tarwonga Rd in the Shire of Narrogin is a two span bridge crossing Torbling Brook. The structure requires maintenance but generally appears to be in good condition.

### 2.0 Preventative Maintenance

Preventative maintenance to be undertaken on a 5 year periodic basis.

### 3.0 Routine Maintenance

Undertake deck drainage maintenance as outlined in report in accordance with specification 850.93.07.  
(spoon drains a1 & a2 LHS)  
Undertake minor kerb repairs as outlined in report.  
(a2 LHS)

### 4.0 Specific Maintenance

#### 4.1 Substructure

Undertake sillbeam repair as outlined in report. (Pier 1)

#### 4.2 Superstructure

Not required.

### 5.0 BCI

38.6

### 6.0 Load Rating

Not required.

Paul Olsen  
Engineering Associate Bridges

March 18 2019



## Bridge Condition Index (BCI)

Date 21/08/2017

**Bridge Number**

**3122**

LOCATION	Weighting	CS1	CS2	CS3	CS4	ICR	AGR	Ave AGR	BCI
Condition State Weighting		1	3	9	11				
Stringers	11	30.0	58.4	11.6	0.0	3.1	34.1	32.2	<u>38.6</u>
Pier Piles	11	0.0	100.0	0.0	0.0	3.0	33.0		
Abutment Piles	11	0.0	100.0	0.0	0.0	3.0	33.0		
Halfcaps	11	20.0	80.0	0.0	0.0	2.6	28.6		
Corbels	6	0.0	100.0	0.0	0.0	3.0	18.0	20.4	
Timber Decking	6	0.00	90.00	0.00	10.00	3.8	22.8		
Wing Piles	3	0.0	100.0	0.0	0.0	3.0	9.0	6.0	
Abutment Sheeting	3	100.00	0.00	0.00	0.00	1.0	3.0		

Condition States are from a Detailed Inspection Report conducted on 17/08/2017

**Table 5.1: BCI Descriptor Range**

Descriptor	BCI Range	<div style="display: flex; align-items: center; justify-content: center; gap: 20px;"> <div style="text-align: center;">  better </div> <div style="text-align: center;">  worse </div> </div>	
Very Good	0 - 19		
Good	20 - 39		
Fair	40 - 55		
Poor	56 - 100		
Severe	101 +		

BDO,  
Please update in IRIS to indicate BCI values.

CPS

Bridge Condition Manager  
Date: 22/3/19

Calculation of BCI is based on the Timber Bridge Condition Index (BCI) User Guide

Comments:

Structure has concrete abutments and pier



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GENERAL INFORMATION - SHEET 1

Bridge No.: 3122

Region:	<u>Wheatbelt</u>	Latitude (S):	<u>-32.98702</u>
		Longitude (E):	<u>117.11055</u>
Road Name:	<u>Tarwonga Rd</u>	Road No.:	<u>4180204</u>
Local Government:	<u>Narrogin</u>	Owner:	<u>Local Authority</u>
Crossing Name:	<u>Torbling Brook</u>	SLK:	<u>2.82</u>
Number of Lanes:	<u>2</u>	Length (m):	<u>10.30</u>
Total Width (m):	<u>7.92</u>	Max. Head Room (m):	<u>1.70</u>
Inc. Footpath		Min. Head Room (m):	<u>1.20</u>
No. of Spans:	<u>2</u>	Width between Kerbs (m):	<u>7.38</u>
		Concrete Overlay (Y/N):	<u>Y (130mm)</u>


Piers are numbered along the bridge in ascending order from ABUTMENT 1 to ABUTMENT 2.

Piles are numbered across the bridge in ascending order from LEFT to RIGHT.

Stringers are numbered across the bridge in ascending order from LEFT to RIGHT.

Inside and outside kerb depths noted in corners of sketch.

Exposed Deck Ends (RCO only): LHS ☒ N RHS ☒ N



This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Timber Bridge Detailed Inspection Guidelines.

Inspected by: S. MAULE D. ENKER

Checked by: PAUL J CHAN

Date: 17-8-17

Date: 4-10-17

Drilled by: DAVID ENKER





## SITE CONDITIONS

Bridge No: 3122



DRIVE THROUGH	Visible Line of Sight from Abut. 1: 800 m
	Visible Line of Sight from Abut. 1: 200 m
TRAFFIC CONTROL (Describe if different to the generic TMP)	Abut. 1 end: Normal Abut. 2 end:
PARKING POSITION	> 3 m <input checked="" type="checkbox"/> Position: 4
	1.2 to 3 m <input checked="" type="checkbox"/> Position: AB 2 LHS BEHIND GUARD RAIL
	0 to 1.2 m <input type="checkbox"/> Position:
ACCESS TO ABUTMENTS (Describe access conditions at each wing)	Abutment 1: LHS: } OK FROM PARKING AREA RHS: }
	Abutment 2: LHS: RHS:
	Vegetation:
ACCESS TO PIERS (Describe access conditions along each side of the structure)	LHS: RS ABOVE RHS: Vegetation:
POTENTIAL HAZARDS	Railing/Posts: WATER
	Bolts:
	Services:
	Asbestos:
	Other:
FENCES None	Timber <input type="checkbox"/> Location:
	Wire/Mesh: <input type="checkbox"/> Location:
	Electrified: <input type="checkbox"/> Location:
	Barbed Wire: <input type="checkbox"/> Location:
	Other (Specify): <input type="text"/> Location:
WATER	Depth (m): 0.3
	Flow Rate: Shallow
	Algae: No (Access may be restricted by toxic algae)
	Tide: No
	Location: SPAN 1 & 2
POWERLINES None	Side of bridge:
	Horizontal distance from edge of deck (m):
	Estimated vertical height above deck (m):

Signature

Date 17-8-17

MAIN ROADS Western Australia

Timber Bridge Detailed Inspection Guidelines

Form 30

Shire of Narrogin

Bridges Asset Management Plan 2020-2030

Page | 119





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GUARDRAIL INFORMATION

Bridge No.: 3122

### Barrier Type

None  
 RHS Rails No. of Rails (on bridge):  
 Thriebeam  
 W Beam  
 Tric-Bloc Concrete Barrier  
 Reinforced Concrete Barrier (Type F)  
 Constant Slope Concrete Barrier  
 Other Concrete Profiles

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS
X		X	X		X	X		X

### Post Type

Steel Type: PFC  
 None  
 Concrete  
 Timber

X		X	X		X	X		X

[Types: C-Section (C), I Section (I), RHS (R), Square Hollow Section SHS (S), Tubular (T), Steel PFC (PFC), Steel Channel (Ch)]

### Off bridge:

Number of Posts off Bridge  
 Length of Barrier off Bridge (m)

7		3				3		6
13.6		7.4				7.4		13.6

### Visibility Barrier

Timber No. of Rails (on bridge):  
 Steel Pipe(s) No. of Pipes (on bridge):  
 Guide Posts  
 Balustrade

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS

### Top Rails

Steel Pipe  
 Steel RHS/Channel  
 Steel C Section  
 Timber


### End Terminals

#### Approved End Terminal Types:

WAMELT  
 SKT-350  
 ET-2000  
 X Tension  
 TAU II Crash Cushion  
 Other:

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS				LHS	Median	RHS

#### Other End Terminal Types:

None  
 Turn-down  
 Bullnose  
 Fishtail  
 Other

X		X				X		X

Structural problem found? (Y/N)

N If yes, comment below.



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## ROUTINE INFORMATION

Bridge No.: 3122

SCUPPERS LOCATION, TYPE & CONDITION (R208)		None <input checked="" type="checkbox"/> LHS <input type="checkbox"/> RHS <input type="checkbox"/>	Box <input type="checkbox"/> PVC pipe <input type="checkbox"/> Hole in deck <input type="checkbox"/>
		Not Req'd	Through Deck <input type="checkbox"/> Through Kerb <input type="checkbox"/>
		Spoon Drains At All 4 Corners - Req Clearing CLEAR AL LHS & AL RHS	
FLASHING TYPE & CONDITION (R208)		None <input checked="" type="checkbox"/>	PVC pipe <input type="checkbox"/> PGI <input type="checkbox"/>
BOLT TIGHTENING REQUIRED (P102)		Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
TERMITES (R204)		Active <input type="checkbox"/>	Not Active <input checked="" type="checkbox"/>
		None Found.	
PREVENTATIVE FUNGICIDE (P103)		Treated <input checked="" type="checkbox"/>	Not Treated <input type="checkbox"/> BLUE PLUGS
ATTACHED FENCES & OTHER WATERWAY OBSTRUCTIONS (R210)		FARM FENCES 10m EITHER SIDE OF BRIDGE HAVE DEBRIS BUILD UP - Req Clearing	
ROAD SURFACE & KERBING CONDITION (R207)	ON BRIDGE	Road Surface: Bitumen on R.C.O. - OK	
		Kerbing: Concrete - OK	
	APPROACHES	Road Surface: Bitumen - OK	
		Kerbing: Short Concrete - Minor Cracks, AB 2 LHS MISS ALIGNED REPAIR	
VEGETATION (R205)		Requires Clearing : LHS <input type="checkbox"/> Abut 1 <input type="checkbox"/> RHS <input type="checkbox"/> Abut 2 <input type="checkbox"/>	Some High Grass & Tree Re-Growth
STREAM BED CONDITION (General comments and details of location, depth & extent of scour, undermining and silt build up.) (R203)		OK	
SERVICES (Type, Size & Location)		Type	Size (mm) Location
		None	
BRIDGE CONDITION		Priority for Engineering Assessment	
		Low <input checked="" type="checkbox"/>	Medium <input type="checkbox"/> High <input type="checkbox"/> Urgent <input type="checkbox"/>

Comments:



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GENERAL INFORMATION - SHEET 2

Bridge No.: 3122

### Bridge Status

Built/In Use ☒

Not Used ☐

Date Built 1/1/1936

Skew (angle) \_\_\_\_\_

Skewed Width (m) \_\_\_\_\_

### Widening

Left Hand side ☒ Width (m) \_\_\_\_\_

Right Hand side ☒ Width (m) \_\_\_\_\_

Date 12/08/1988

Date 12/08/1988

### Surface Type

Unsurfaced ☐ Bitumen Seal ☒ Asphalt ☐  
Rubberised Seal ☐ Tiles ☐ Steel Plate ☐

### Pavement Type

Unpaved ☐ Gravel ☐ Material Unknown ☐

### Footpath Left

Left Kerb (m) 0.20 Path (m) \_\_\_\_\_ Right Kerb (m) \_\_\_\_\_

### Footpath Right

Left Kerb (m) \_\_\_\_\_ Path (m) \_\_\_\_\_ Right Kerb (m) 0.20

### Median

Left Kerb (m) \_\_\_\_\_ Median (m) \_\_\_\_\_ Right Kerb (m) \_\_\_\_\_

### Bridge Function 1

Road Bridge ☒ Rail Bridge ☐ Pedestrian Bridge ☐

### Bridge Function 2

Over Water ☒ Over Road ☐ Over Rail ☐  
Over Road & Rail ☐ Over Road & Water ☐ Over Rail & Water ☐  
Stock Underpass ☐ Pedestrian Underpass ☐

## SIGNAGE

### Load Limits

Abutment 1 End  Tonne Abutment 2 End  Tonne

### Width Markers

Abutment 1 LHS  RHS  Abutment 2 LHS  RHS

Is position of Width Markers a true indication of the bridge width? (Y/N)

### Other Signs

No Overtaking or Passing	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>
No Overtaking on Bridge	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>
One Lane Bridge	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>
Low Clearance .....m	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>
Narrow Bridge Sign	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>
Give Way	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>

### Crossing Sign:

### Other

Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>
Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>

### Signage Condition Legend

Good  1 Poor  3 Not Required ☐  
Fair  2 None (missing)  4



## ELEMENT SPACING SHEET 2


Bridge No.: 3122

All measurements (cumulative) are taken from the reference point as indicated by the star ☆


### Pier Pile Centres

Mark in RHS edge of deck and dimension last pile to RHS edge of deck.


PIER No. ....



PIER No. ....



PIER No. ....




### Typical Stringer Spacing


Mark in RHS edge of deck and dimension last stringer to RHS edge of deck.

Note: Stringer spacings must be measured in every span with additional stringers. Use additional sheets as required.


SPAN No. 1. *TYPICAL*



SPAN No. ....



SPAN No. ....






# TIMBER BRIDGE DETAILED INSPECTION REPORT



## SILL BEAM ABUTMENT 1

Bridge No: 3122



Sill Beam	Dimens. (mm)	Mat. Type	Drilling (mm)	SILL BEAM CONDITION BELOW STRINGER NUMBER												Condition State
				1	2	3	4	5	6	7	8	9	10	11	12	
1	H	WAN	Solid (Front)	CONCRETE	100	150	210	130	150	170	CONCRETE					1/2
	350		Rot/ Pipe			90	50	50	80	70	80					
	V		Solid (Rear)			160	150	90	140	130	100					
2	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
3	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
4	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
5	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
6	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													

Sheeting: LHS: \_\_\_\_\_ Saturated Sill beams: \_\_\_\_\_

CENTRE LINE: } PLY BOARD WITH CONC BEHIND.

RHS: \_\_\_\_\_

Comments: LARGE SPLIT AT R.H. END OF SILL BEAM - MINOR CRACKS IN CONCRETE - OK.


ANY RESULTS VASTLY DIFFERING FROM OLD REPORT ARE DOUBLE CHECKED. TROUT

DRILLINGS OK M.B.

## SILL BEAM PIER

Pier No: 1

Bridge No: 3122



Sill Beam	Dimens. (mm)	Mat. Type	Drilling (mm)	SILL BEAM CONDITION BELOW STRINGER NUMBER												Condition State
				1	2	3	4	5	6	7	8	9	10	11	12	
1	H	342000	Solid (Front)	Concrete	110	140	110	120	180	210	Concrete					
	350		Rot/ Pipe			120	80	130	70	70	90					1/2
	300		Solid (Rear)			120	130	110	160	100	50					
2	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
3	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
4	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													

Total Number of Corbels 10

Typical Corbel Height (mm): LHS 350 RHS 350

Corbel No:

Material Type:

Requires Bolting:

A1/A2 End

Condition State:

A1/A2 End

1	2	3	4	5	6	7	8	9	10	11	12
J	J	W	W	W	W	W	W	J	J		
22	22	22	22	22	22	22	22	22	22	22	22

Ironwork Condition:

Saturated Sill Beams:

Comments:

CORBELS 1, 2, 9 & 10 ARE SQUARE SAWN  
SILL BEAM HAS A KNOT HOLE BETWEEN STR 5 & 6 AB 1 SIDE LARGE HOLE  
MINOR CRACKS IN CONCRETE A- & = OK  
HOLE LOCATION IS BETWEEN CORBELS



## CORBEL SHEET

Bridge No.: 3122

This report sheet is only used when a corbel has a visible defect.

CORBEL LOCATION: PIER NO.: 1

CORBEL NO.: 8

Material Type: WANDO

Abutment 1 End	H Diameter (mm)		450
	V Measurement (mm)		340
	Drill Vertical	Solid (B)	110
		Rot	
		Pipe	160
		Rot	
		Solid (T)	70
	Drill Horiz.	Left	130
		Right	150
	Vertical Split	Large	
		Minor	
	Horiz. Split	Large	
		Minor	
	Star Splitting	Large	
		Minor	
RQS Bolting	V.Split		
	H.Split		
Propped			

Abutment 2 End	H Diameter (mm)		450
	V Measurement (mm)		340
	Drill Vertical	Solid (B)	110
		Rot	
		Pipe	120
		Rot	
		Solid (T)	110
	Drill Horiz.	Left	150
		Right	150
	Vertical Split	Large	
		Minor	
	Horiz. Split	Large	
		Minor	
	Star Splitting	Large	
		Minor	
RQS Bolting	V.Split		
	H.Split		
Propped			

Saturated corbel: \_\_\_\_\_


Pipe length from A1 Side 1560

Pipe length from A2 Side 1560


COMMENTS: SEE PHOTOS.

No CHANGE dh #12 #13  
17-8-17

DIAGRAM OF CONDITION - Indicate location of bolts



ABUTMENT 1 END  
(Refer photos for details)



ABUTMENT 2 END  
(Refer photos for details)




# TIMBER BRIDGE DETAILED INSPECTION REPORT



## SILL BEAM ABUTMENT 2

Bridge No: 3122



Sill Beam	Dimens. (mm)	Mat. Type	Drilling (mm)	SILL BEAM CONDITION BELOW STRINGER NUMBER												Condition State
				1	2	3	4	5	6	7	8	9	10	11	12	
1	H	WAN	Solid (Front)	Concrete	100	140	190	130	70	80	Concrete					1/2
	380		Rot/ Pipe			180	180	90	140	150	150					
	V		Solid (Rear)			100	60	100	110	160	150					
2	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
3	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
4	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
5	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
6	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													

Sheeting: LHS: \_\_\_\_\_ Saturated Sill beams: \_\_\_\_\_

CENTRE LINE: } Ply BOARDS WITH CONC BEHIND

RHS: \_\_\_\_\_

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## DETAIL SHEET

Span No: 1

Bridge No: 3122

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	WAN	WAN	WAN	WAN	WAN	WAN	JAR	JAR				

Abutment 1 End	H Diameter (mm)	350	480	340	470	350	370	410	330	430	410				
	V Measurement (mm)	350	350	350	350	350	350	350	350	350	350				
	Drill Vertical	Solid (B)	170	350	100	350	110	120	150	180	350	180			
		Rot					TO		TO						
		Pipe	90		200		TOP	60	TOP	120		70			
		Rot													
	Drill Horiz.	Solid (T)	90		50		170		50		100				
		Left			80		160		150						
	Split	Right			90		130		80						
		V Bolt Rqd													
	Propped	H Bolt Rqd													
		Condition State	2	1	3	1	2	2	3	2	1	2			

Mid Span	H Diameter (mm)	360	530	380	390	420	350	430	320	400	420				
	V Measurement (mm)	440	500	370	430	410	360	410	440	430	400				
	Drill Vertical	Solid (B)	440	480	130	430	410	360	150	150	220	400			
		Rot													
		Pipe			170				240	100	40				
		Rot													
	Drill Horiz.	Solid (T)			70				20	190	170				
		Left			90				220						
	Split	Right			100				150						
		V Bolt Rqd													
	Propped	H Bolt Rqd													
		Condition State	1	1	3	1	1	1	2	2	2	1			

Abutment 2 End	H Diameter (mm)	550	580	420	370	470	340	430	340	340	400				
	V Measurement (mm)	350	350	350	350	350	350	350	350	350	320				
	Drill Vertical	Solid (B)	350	130	100	210	130	180	90	130	100	140			
		Rot													
		Pipe		120	160	50	110	60	230	110	70	90			
		Rot													
	Drill Horiz.	Solid (T)		100	90	90	110	110	30	110	180	90			
		Left			110				150						
	Split	Right			110				160						
		V Bolt Rqd													
	Propped	H Bolt Rqd													
		Condition State	1	2	2	2	2	2	2	2	2	2			

Cond. of Spiking Plank Not Applicable ☒ Size V  Condition S  R  %

Cond. of Decking (Solid/Rot) S  90 R  10 % Cond. of Deck Ends S  R  %

Decking Size (mm) V  120 x H  230 Decking Timber Type JAR

Span Length from Centreline Supports (m)  4.40 Clear Span Length  3.50 Saturated stringers:

Deck Condition State Condition 1  Condition 2  90 Condition 3  Condition 4  10 Spiral Grain Stringers:

Comments: STR 7 IS WANBOO NOT JARRAH

STR 5 MIDSPAN DRILLED 3 TIMES SOLID. STR 1, AB 2 ALSO

STR 1 AB 2 END HAS 110 ROT IN 2012 DIR ☒ OK MB

STR 5 MID SPAN HAS 100 PIPE IN 2012 DIR ☒ OK MB





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## DETAIL SHEET

Span No: 2

Bridge No: 3122

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	WAN	WAN	WAN	WAN	WAN	WAN	JAR	JAR				

H Diameter (mm)	430	500	360	420	480	410	460	280	530	320				
V Measurement (mm)	350	350	350	350	350	350	350	350	350	350				
Abutment 1 End	Drill Vertical	Solid (B)	350	140	60	140	120	100	100	160	130	350		
		Rot												
		Pipe		50	250	130	70	110	110	80	40			
		Rot												
		Solid (T)		160	40	80	160	140	140	110	180			
	Drill Horiz	Left			90									
		Right			140									
	Split	V Bolt Rqd												
		H Bolt Rqd												
	Propped													
	Condition State		1	2	3	2	2	2	2	2	1			

H Diameter (mm)	430	490	390	480	400	410	390	300	510	320				
V Measurement (mm)	480	490	420	450	390	420	380	380	460	330				
Mid Span	Drill Vertical	Solid (B)	480	480	140	120	210	420	180	140	280	330		
		Rot												
		Pipe			220	250	60		60	200	90			
		Rot												
		Solid (T)			60	80	120		140	40	90			
	Drill Horiz	Left			90	190				90				
		Right			110	240				80				
	Split	V Bolt Rqd												
		H Bolt Rqd												
	Propped													
	Condition State		1	1	2	2	2	1	2	3	2	1		

H Diameter (mm)	410	510	390	520	390	450	390	360	460	420				
V Measurement (mm)	350	350	350	350	350	350	350	350	360	350				
Abutment 2 End	Drill Vertical	Solid (B)	350	130	90	80	120	70	130	50	150	350		
		Rot												
		Pipe		130	180	110	60	210	170	240	130			
		Rot												
		Solid (T)		90	80	160	170	70	50	60	80			
	Drill Horiz	Left			90	260		140	150	130				
		Right			180	120		160	110	70				
	Split	V Bolt Rqd												
		H Bolt Rqd												
	Propped													
	Condition State		1	2	2	2	2	2	3	2	1			

Cond. of Spiking Plank Not Applicable ☒ Size V  Condition S  R  %

Cond. of Decking (Solid/Rot) S  R  % Cond. of Deck Ends S  R  %

Decking Size (mm) V  x H  Decking Timber Type


Span Length from Centreline Supports (m)  Clear Span Length  Saturated stringers: \_\_\_\_\_

Deck Condition State Condition 1  Condition 2  Condition 3  Condition 4  Spiral Grain Stringers: \_\_\_\_\_

Percentage: \_\_\_\_\_

Comments: STR 10 AT END HAS 100 ROT IN 2012 DIR OK MB.






LEGEND:  
For map legend see page 4

Map 53

0 2 4 km





## LEGEND

### MATERIAL TYPE

J - JARRAH  
W - WANDOO  
S - STEEL  
U - UNKNOWN TIMBER

### SPLITS

✓ TICK ONLY IF REQUIRED

### PRIORITY BOLT/BAND


U - A.S.A.P.  
H - HIGH PRIORITY  
M - ROUTINE MAINTENANCE  
L - LOW PRIORITY

FOR AUDIT  
PURPOSES  
ONLY


### GENERAL

P - PIPE  
R - ROT  
F - FRIABLE  
S - SOLID  
N/A - NOT APPLICABLE  
V - VERTICAL  
H - HORIZONTAL  
LHS - LEFT HAND SIDE  
RHS - RIGHT HAND SIDE  
Dia - PIPE DIAMETER  
Circ - CIRCUMFERENCE  
A1 - ABUTMENT No. 1  
A2 - ABUTMENT No. 2  
Str - STRINGER  
H/C - HALFCAP  
H/CAP - HALFCAP  
Blz - BLAZE  
℄ - CENTRE LINE  
O/A - OVERALL  
GL - GROUND LEVEL  
Ht - HEIGHT  
Ft - FEET  
W - WIDTH BETWEEN WALING  
Cond - CONDITION  
U/S - UNSOUND (STRUCTURALLY)  
SG - SPIRAL GRAIN

ROUND THE DIMENSIONS ON THE HALFCAP BEARING ON THE PILE AT BOTH ABUTMENT SIDES OF THE PILE. i.e. ABUTMENT N° 1 & ABUTMENT N° 2



## HALFCAP SEATING ARRANGEMENTS



NOTE: All dimensions are of solid timber excluding sap wood and any surface rot on piles and stringers

/SE Documents/Management System Manual/Dwgs/timber\_repair.dwg



Page intentionally left blank

**Bridge 3128A**  
**Manaring Road over**  
**Williams River**  
**L2 Inspection**



File: **04/4051**  
To: **Engineer Bridge Loading**  
Subject: **Bridge Number: 3128A**

---

- 1 Having recently completed an assessment of routine and specific maintenance work required on this bridge, I am of the opinion that the condition of certain structural components has deteriorated to such an extent that the load carrying capacity of the bridge may have been affected.
- 2 In accordance with the requirements of the procedure for Heavy Loads Assessment, Document number 3912/01-7, this bridge is referred for a detailed structural assessment of the bridge in its present condition.



Mark Billings  
SENIOR STRUCTURAL ENGINEER AECOM  
24 April 2019

Abutment 2 Beddy  
Pier 1 Halfcap splice





Enquiries Gavin Johnston on 9323 4431  
Our Ref: 04/4051  
Your Ref:



ABN: 50 860 676 021

## ASSET MANAGER STRUCTURES WHEATBELT REGION

Structure No.: 3128A  
Over: Williams River  
On: Manaring Rd (4190011)  
SLK: 3.58  
LGA: Shire of Narrogin

1. Please find enclosed a copy of the Detailed Inspection Report for the above Local Authority structure.
2. Attached is a schedule of maintenance items that are required to be undertaken in order to maintain structural integrity and extend the life of the Structure.
3. The maintenance items have been entered into IRIS for programming purposes.
4. Preliminary examination has indicated that the load carrying capacity of this Structure may have been affected by the deterioration of structural components as listed in the attached report. We are in the process of determining its current load capacity and will advise you accordingly when our assessment is completed.

Reviewed By:

*Mark Billings*  
Mark Billings  
SENIOR STRUCTURAL ENGINEER AECOM

27/3/2019

Enc

Issued By:

*Gavin Johnston*  
Gavin Johnston  
BRIDGE CONDITION MANAGER

24/4/19

**WORK ITEMS - TIMBER BRIDGES**  
**BRIDGE No: 3128A**

ITEM NO	ITEM DESCRIPTION	WORK REQD	PRIORITY CODE	COMMENTS
---------	------------------	-----------	---------------	----------

**(A) GENERAL MAINTENANCE**

G005	Bridge - Durability Survey (L3)			
G009	Bridge - Load Rating	y	1	Abutment 2 Pile 2 and bedlog, Pier 1 Halfcap splice cracks.
G010	Bridge - Monitor Defect			

**(B) PREVENTATIVE MAINTENANCE**

P101	Bridge - Seal Timber	Y	1	
P102	Bridge - Maintain Fastener			
P103	Bridge - Fungicide Treatment	Y	1	

**(C) ROUTINE MAINTENANCE**

	Bearing - Maintain			
	Bridge - Remove Graffiti			
	Bridge - Repair Scour (Minor)			
	Bridge - Eradicate Termites	Y	1	
	Bridge - Clear Debris and Vegetation			
	Deck Joint - Maintain			
	Deck Surface - Maintain	Y	1	clear gravel build up at kerbs
	Drainage - Maintain			
	Expansion Joint - Maintain			
	Fence - Remove	Y	1	span 1 & 2 LHS
	Fence - Repair (Control of Access)			
	Guardrail Maintain/Repair			
	Kerb - Repair (Minor) - Non Structural			
	Lighting - Maintain			
	Sign - Maintain			

**(D) SPECIFIC MAINTENANCE**

S315	Bridge - Replace Fastener <1.5m			
S350	Bridge - Repair Scour (Major)			
S366	Bridge - Access - Improve			
S413	Deck - Repair			
S437	Decking - Repair (Timber)			
S449	Drainage - Repair			
S455	Expansion Joint - Repair			
S461	Footpath - Repair			
S501	Abutment - Reconstruct			
S504	Abutment - Repair (Non timber)			
S507	Bedlog - Repair	Y	1	abutment 2 face & LHS wingwall
S510	Bedlog - Shim			
S522	Corbel - Bolt			
S525	Corbel - Repair			
S528	Corbel - Shim			
S537	Footpath Railing - Repair			
S540	Fullcap - Repair			
S543	Halfcap - Improve Bearing			
S546	Halfcap - Pack			
S549	Halfcap - Repair	Y	1	Pier 1 Abutment 2 halfcap splice cracking
S558	Pier - Repair			
S561	Pile - Band			
S564	Pile - Repair			
S570	Sheeting - Repair			
S582	Waler - Replace			
S607	Bearer - Repair			
S643	Joist - Repair			
S655	Stringer - Bolting			
S661	Stringer - Repair			
S667	Stringer - Shim	Y	2	span 1 str 1 a1, strs 1,2 & 6 a2

**PRIORITY CODE**

0 -Critical Safety Deficiency : EMERGENCY action required (Immediate or within 6 months)

1 - Very High Priority (Within 3 years)

2 - Medium Priority (Within 4 years)

3 - Low Priority (Within 5 years-assess again at next Detailed Inspection)

**DETAILED TIMBER BRIDGE INSPECTION SUMMARY**

Bridge No:	3128A	Region:	WHEATBELT REGION
River Name:	Williams River	SLK:	3.58
Road:	Manaring Rd	Road No:	4190011
LGA:	Shire of Narrogin		

**1.0 General**

Bridge no. 3128A located on Manaring Rd in the Shire of Narrogin is a two span bridge crossing the Williams River. The structure requires maintenance in particular the bedlogs at abutment 2 are in poor condition. The pier 1 a2 halfcap is cracking in the vicinity of the splice but there is no change from the previous DIR.

**2.0 Preventative Maintenance**

Preventative maintenance to be undertaken on a 5 year periodic basis. Areas of concern have been identified below.  
Sealing of timber elements in accordance with Document No. 6706-02-2226, Preventive Maintenance Standards.  
Fungicide treatment of all timber elements in accordance with Document No. 6706-02-2226, Preventive Maintenance Standards.

**3.0 Routine Maintenance**

Undertake termite inspection and treatment as required in accordance with specification 850.93.09.  
Remove fences attached to bridge as outlined in report.  
Correct road surface on bridge deck and approaches as outlined in report.

**4.0 Specific Maintenance**

**4.1 Substructure**

Not required.

**4.2 Superstructure**

Undertake bedlog repairs as outlined in report.  
(abutment 2 face & LHS wingwall)  
Shim stringers as outlined in report  
(span 1 str 1 a1, strs 1,2 & 6 a2)

**5.0 BCI**

28.2

**6.0 Load Rating**

Load rate Abutment 2 Pile 2 for overall stability (in existing condition) and Pier 1 Abutment 2 halfcap splice.



Mark Billings  
SENIOR STRUCTURAL ENGINEER AECOM

March 21 2019



**DETAILED VISUAL (LEVEL 2) TIMBER  
BRIDGE INSPECTION REPORT  
BRIDGE CONDITION INDEX (BCI)**



**Bridge Number** **3128A**

In conjunction with the Detailed Level 2 Bridge Inspection Report (as dated below), a Bridge Condition Index (BCI) has been calculated for this Bridge. The BCI assigns a numerical value to a bridge that is indicative of its condition and provides a relative condition in comparison with other timber bridges (BCI calculation is only applicable for timber bridges). The BCI rating system is a tool to provide a systematic approach for the determination of bridge condition by bridge inspection alone.

The process for determining the BCI is outlined in the Timber Bridge Condition Index User Guide. The BCI is primarily calculated utilising Condition States which are assigned based on the Level 2 Bridge Inspection Report (see attached).

A summary of the condition states and the calculated BCI for this bridge is provided below.

**Condition States from Detailed Inspection Report conducted on** 28-07-2018

		Condition State - Distribution (%)					
LOCATION	Weighting	CS1	CS2	CS3	CS4	Ave	BCI
Condition State Weighting		1	3	9	11	AGR	
Stringers	11	90.5	9.5	0.0	0.0	21.3	<u>28.2</u>
Pier Piles	11	76.9	23.1	0.0	0.0		
Abutment Piles	11	83.1	15.0	1.9	0.0		
Halfcaps	11	0.0	89.6	10.4	0.0	20.4	
Corbels	6	0.0	100.0	0.0	0.0		
Timber Decking	6	0.0	90.0	0.0	10.0	6.5	
Wing Piles	3	82.9	17.1	0.0	0.0		
Abutment Sheeting	3	0.0	100.0	0.0	0.0		

Descriptor	BCI Range
Very Good	0 - 19
Good	20 - 39
Fair	40 - 55
Poor	56 - 100
Severe	101 +

**BCI Descriptor Range (Refer Table 5.1 Doc No. 6706/02/2232)**

**Comments:**

**Prepared by:** P Olsen

**Date:** 09/08/2018



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GENERAL INFORMATION - SHEET 1

Bridge No.: 3128A

Region:	<u>Wheatbelt</u>	Latitude (S):	<u>-33.01824</u>
		Longitude (E):	<u>117.05446</u>
Road Name:	<u>Manaring Rd</u>	Road No.:	<u>4180211</u>
Local Government:	<u>Narrogin</u>	Owner:	<u>Local Authority</u>
Crossing Name:	<u>Williams River</u>	SLK:	<u>3.58</u>
Number of Lanes:	<u>2</u>	Length (m):	<u>12.60</u>
Total Width (m):	<u>7.15</u>	Max. Head Room (m):	<u><del>3.50</del> 3.5</u>
Incl. Footpath:		Min. Head Room (m):	<u>1.40</u>
No. of Spans:	<u>2</u>	Width between Kerbs (m):	<u>6.85</u>
		Concrete Overlay (Y/N):	<u>N</u>


Piers are numbered along the bridge in ascending order from ABUTMENT 1 to ABUTMENT 2.

Piles are numbered across the bridge in ascending order from LEFT to RIGHT.

Stringers are numbered across the bridge in ascending order from LEFT to RIGHT.

Inside and outside kerb depths noted in corners of sketch.

Exposed Deck Ends (RCO only): LHS ☐ RHS ☐



This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Timber Bridge Detailed Inspection Guidelines.

Inspected by: S. MAHE D. ENKEL

Checked by: PARSON D. WANGA

Date: 17-1-18 28/7/18

Date: 3-10-18

Drilled by: DAVID ENKEL



SITE CONDITIONS  
Bridge No: 3128A



DRIVE THROUGH	Visible Line of Sight from Abut. 1: 100 m Visible Line of Sight from Abut. 1: 100 m
TRAFFIC CONTROL (Describe if different to the generic TMP)	Abut. 1 end: N/A Abut. 2 end:
PARKING POSITION	> 3 m <input checked="" type="checkbox"/> Position: AB 1 RHS 1.2 to 3 m <input type="checkbox"/> Position: 0 to 1.2 m <input type="checkbox"/> Position:
ACCESS TO ABUTMENTS (Describe access conditions at each wing)	Abutment 1: LHS: } L.A.S POOR - FARM FENCE AT BOTH WING WALLS RHS: } Abutment 2: LHS: } RHS FAIR - GRAVEL BANKS. RHS: } Vegetation: HIGH GRASS
ACCESS TO PIERS (Describe access conditions along each side of the structure)	LHS: AS ABOVE RHS: Vegetation:
POTENTIAL HAZARDS	Railing/Posts: FENCE ON LHS Bolts: GRAVEL BANKS Services: WATER HIGH GRASS Asbestos: Other:
FENCES	Timber <input type="checkbox"/> Location: Wire/Mesh: <input checked="" type="checkbox"/> Location: AT L.A.S. WING WALLS AB 1 & 2 - REMOVE Electrified: <input type="checkbox"/> Location: Barbed Wire: <input type="checkbox"/> Location: Other (Specify): Location:
WATER	Depth (m): 1.8 m Flow Rate: MED Algae: No (Access may be restricted by toxic algae) Tide: No Location: SPAN 1 & 2
POWERLINES	Side of bridge: Horizontal distance from edge of deck (m): Estimated vertical height above deck (m):

Signature

Date 17-1-18

MAIN ROADS Western Australia

Timber Bridge Detailed Inspection Guidelines  
Doc 6706-02-2231 - Issue 21/02/2014

Form 30

Shire of Narrogin

Bridges Asset Management Plan 2020-2030

Page | 140





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GUARDRAIL INFORMATION

Bridge No.: 3128A

### Barrier Type

None  
RHS Rails No. of Rails (on bridge):  
Thriebeam  
W Beam  
Tric-Bloc Concrete Barrier  
Reinforced Concrete Barrier (Type F)  
Constant Slope Concrete Barrier  
Other Concrete Profiles

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS
X		X	X		X	X		X

### Post Type

Steel Type: \_\_\_\_\_  
None  
Concrete  
Timber

X		X	X		X	X		X

[Types: C-Section (C), I Section (I), RHS (R), Square Hollow Section SHS (S), Tubular (T), Steel PFC (PFC), Steel Channel (Ch)]

Off bridge:

Number of Posts off Bridge

Length of Barrier off Bridge (m)

4		2				2		4
7.8		3.9				3.8		7.55

### Visibility Barrier

Timber No. of Rails (on bridge):  
Steel Pipe(s) No. of Pipes (on bridge):  
Guide Posts  
Balustrade

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS

### Top Rails

Steel Pipe  
Steel RHS/Channel  
Steel C Section  
Timber


### End Terminals

Approved End Terminal Types:

WAMELT  
SKT-350  
ET-2000  
X Tension  
TAU II Crash Cushion  
Other:

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS				LHS	Median	RHS

Other End Terminal Types:

None  
Turn-down  
Bullnose  
Fishtail  
Other

X								X
		X				X		

Structural problem found? (Y/N)

N

If yes, comment below.



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## ROUTINE INFORMATION

Bridge No.: 3128A

SCUPPERS LOCATION, TYPE & CONDITION (R208)		None <input type="checkbox"/> LHS <input checked="" type="checkbox"/> RHS <input checked="" type="checkbox"/>		Box <input checked="" type="checkbox"/> PVC pipe <input type="checkbox"/> Hole in deck <input type="checkbox"/>
				Through Deck <input type="checkbox"/> Through Kerb <input checked="" type="checkbox"/>
		Road's Clearing - GRAVEL BLOW UP AT ALL KERBS. CLEAR		
FLASHING TYPE & CONDITION (R208)		None <input type="checkbox"/>	PVC pipe <input type="checkbox"/>	PGI <input checked="" type="checkbox"/>
		OK		
BOLT TIGHTENING REQUIRED (P102)		Yes <input type="checkbox"/>		No <input checked="" type="checkbox"/>
TERMITES (R204)		Active <input checked="" type="checkbox"/>		Not Active <input type="checkbox"/> TREAT
		ABUT 2 L.H.S WING BELOW STR. IN BED LOG.		
PREVENTATIVE FUNGICIDE (P103)		Treated <input checked="" type="checkbox"/>		Not Treated <input type="checkbox"/> FACED END PLAYS
		END GRAIN ONLY & OUTSIDE STR'S		
ATTACHED FENCES & OTHER WATERWAY OBSTRUCTIONS (R210)		OLD FENCE WIRE ALONG LHS OF BRIDGE & PIER AT PIER DEBRIS BLOW UP - REMOVE. REMOVE		
ROAD SURFACE & KERBING CONDITION (R207)	ON BRIDGE	Road Surface: GRAVEL - OK		
		Kerbing: TIMBER, WEATH & SPLIT - FAIR, SPLIT AT END LHS.		
	APPROACHES	Road Surface: GRAVEL - OK		
		Kerbing: NONE		
VEGETATION (R205)		Requires Clearing : LHS <input type="checkbox"/> Abut 1 <input type="checkbox"/> RHS <input type="checkbox"/> Abut 2 <input type="checkbox"/> HIGH GRASS		
STREAM BED CONDITION (General comments and details of location, depth & extent of scour, undermining and silt build up.) (R203)		POSSIBLE SCOURING THRU SPAN 1,		
SERVICES (Type, Size & Location)		Type	Size (mm)	Location
		NONE		
BRIDGE CONDITION		Priority for Engineering Assessment Low <input type="checkbox"/> Medium <input checked="" type="checkbox"/> High <input type="checkbox"/> Urgent <input type="checkbox"/>		

Comments: ABUT 2 LHS WING BED LOG U/S



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GENERAL INFORMATION - SHEET 2

Bridge No.: 3128A

Bridge Status

Built/In Use ☒

Not Used ☐

Date Built 03/05/1979

Skew (angle) \_\_\_\_\_

Skewed Width (m) \_\_\_\_\_

Widening

Left Hand side ☐ Width (m) \_\_\_\_\_  
Date \_\_\_\_\_

Right Hand side ☐ Width (m) \_\_\_\_\_  
Date \_\_\_\_\_

Surface Type

Unsurfaced ☒  
Rubberised Seal ☐

Bitumen Seal ☐  
Tiles ☐

Asphalt ☐  
Steel Plate ☐

Pavement Type

Unpaved ☐

Gravel ☒

Material Unknown ☐

Footpath Left

Left Kerb (m) 0.15

Path (m) \_\_\_\_\_

Right Kerb (m) \_\_\_\_\_

Footpath Right

Left Kerb (m) \_\_\_\_\_

Path (m) \_\_\_\_\_

Right Kerb (m) 0.15

Median

Left Kerb (m) \_\_\_\_\_

Median (m) \_\_\_\_\_

Right Kerb (m) \_\_\_\_\_

Bridge Function 1

Road Bridge ☒

Rail Bridge ☐

Pedestrian Bridge ☐

Bridge Function 2

Over Water ☒

Over Road ☐

Over Rail ☐

Over Road & Rail ☐

Over Road & Water ☐

Over Rail & Water ☐

Stock Underpass ☐

Pedestrian Underpass ☐

## SIGNAGE

Load Limits

Abutment 1 End  Tonne

Abutment 2 End  Tonne

Width Markers

Abutment 1 LHS ☒ RHS ☒

Abutment 2 LHS ☒ RHS ☒

Is position of Width Markers a true indication of the bridge width? (Y/N) ☒

Other Signs

No Overtaking or Passing

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

No Overtaking on Bridge

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

One Lane Bridge

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

Low Clearance .....m

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

Narrow Bridge Sign

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

Give Way

Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐

Crossing Sign:

Abutment 1 LHS ☐ RHS ☐  
Abutment 1 LHS ☐ RHS ☐

Abutment 2 LHS ☐ RHS ☐  
Abutment 2 LHS ☐ RHS ☐

Other \_\_\_\_\_

Signage Condition Legend

Good ☐ 1 Poor ☐ 3  
Fair ☐ 2 None (missing) ☐ 4

Not Required ☐




## ELEMENT SPACING SHEET 1

Bridge No.: 3128A

### Abutment 1


All measurements (cumulative) are taken from the reference point as indicated by the star ☆

#### LHS Wing Wall Layout




#### Abutment Abutment Pile Centres

Mark in RHS edge of deck and dimension to outside pile.



#### RHS Wing Wall Layout




### Abutment 2

#### LHS Wing Wall Layout


All measurements (cumulative) are taken from the reference point as indicated by the star ☆

Mark in and dimension to corner of wing wall sheeting




#### Abutment Abutment Pile Centres

Mark in RHS edge of deck and dimension to outside pile.



#### RHS Wing Wall Layout



## ELEMENT SPACING SHEET 2


Bridge No.: 3128A

All measurements (cumulative) are taken from the reference point as indicated by the star ☆


### Pier Pile Centres

Mark in RHS edge of deck and dimension last pile to RHS edge of deck.


PIER No. ....



PIER No. ....



PIER No. ....




### Typical Stringer Spacing


Mark in RHS edge of deck and dimension last stringer to RHS edge of deck.

Note: Stringer spacings must be measured in every span with additional stringers. Use additional sheets as required.


SPAN No. .... *TYPICAL*



SPAN No. ....



SPAN No. ....








# TIMBER BRIDGE DETAILED INSPECTION REPORT



ABUTMENT: 1



Bridge No: 3128A

Pile No.	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Dia. (mm) below H/C (5m+)	Mat. Type	Tied Back	Cond. State
		Solid	Rot	Pipe	Drill Location from top H/C	Above	Below	Location	Requires Band	Marking (ft/m)	Height Top H/C to Blaze (m)	Height Blaze to GL (m)	A1	A2				
1	400	140		60	0.4					-	0.2	-	-	-	-	JAR		2
2 F	380	150	40		1.2					14	0.6	0.6	-	-	-	JAR		2
3	370	185								12	1.7	0.3	-	-	-	JAR		2
4	380	190								14	0.8	0.6	-	90	-	JAR		2
5 F	410	205								12	1	0.5	-	170	-	JAR		2
6 F	360	180								12	0.8	0.6	-	170	-	JAR		2
7 F	320	160								12	0.7	0.7	-	150	-	JAR		2
8	380	190								11	0.7	0.7	-	55	-	JAR		2
9	390	195								11	1.4	0.6	-	-	-	JAR		2
10	370	105		80	1.1					12	0.7	0.5	-	-	-	JAR		2
11	400	170	30		0.2					-	0.5	-	-	-	-	JAR		2
12																		
13																		
14																		
15																		

Saturated Piles:

**LHS Halfcaps** Size   Length  No. of  Gap between H/Caps





Top of H/Caps to underside of Deck  Back of Halfcaps to Sheeting  H/Cap Material

**RHS Halfcaps** Size   Length  No. of  Gap between H/Caps

Top of H/Caps to underside of Deck  Back of Halfcaps to Sheeting  H/Cap Material

Are there more than 2 sets of halfcaps or sill beams (YES/NO)  (If yes record details on comments sheet)

Comments: PILE 8 H/C BEARING LOAD RATED AT PREVIOUS D/I.R. (236% T44)  
BAND NOT REQ  
ALL H/C SPICE, NO SIGNS OF DISTRESS

Pile No. <input type="text"/>	Pile No. <input type="text"/>	Pile No. <input type="text"/>	Pile No. <input type="text"/>
R.H.S.  L.H.S.	R.H.S.  L.H.S.	R.H.S.  L.H.S.	R.H.S.  L.H.S.
F=	F=	F=	F=





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## ABUTMENT 1 and WING WALL SHEETING

Bridge No: 3128A

ABUTMENT 1 SHEETING (indicate ground line, piles and failed sheeting)

9 Suts

RHS			LHS
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			

SHEETING - ABUTMENT LHS

Solid

Rot from Pile

To Pile

Centreline

Solid

Rot from Pile

To Pile

RHS

Solid

Rot from Pile

To Pile

SHEETING Material Type

J

SHEETING Material Size (mm)

Vertical

220

Depth

70

Condition 1

Condition 2

Condition 3

Condition 4

% Condition State

100

ABUTMENT 1 WING WALLS (indicate ground line, piles and failed sheeting)

9 Suts

8 Suts

RHS			LHS
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			

WINGCAP / SPIKING RAIL CONDITION

WINGCAP / SPIKING RAIL CONDITION

Minor WEATH & SPLITS - OK

Minor WEATH & SPLITS - OK

SHEETING - WING WALLS LHS

Solid

Rot from Pile

To Pile

RHS

Solid

Rot from Pile

To Pile

SHEETING Material Type

J

SHEETING Material Size (mm)

Vertical

220

Depth

70

Condition 1

Condition 2

Condition 3

Condition 4

% Condition State

100



# TIMBER BRIDGE DETAILED INSPECTION REPORT



PIER No: 1

Bridge No: 3128A

Pile No.	Circ. (mm)	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits	Blaze Markings			Halfcaps Bearing (mm)		Pile Circ. (mm) below H/C (5m+)	Mat. Type	Cond. State
			Solid	Rot	Pipe	Drill Location from top H/C	Below	Above		Marking (ft/m)	Height Top H/C to Blaze (m)	Height Blaze to GL (m)	A1	A2			
1	1180	370	155	30		0.8				-	0.9	-	110	100	-	JAR	2
2	1240	390	195							-	0.9	-	160	130	-	JAR	2
3	1100	350	175							-	0.9	-	120	120	-	JAR	2
4	1250	400	200							-	0.9	-	140	130	-	JAR	2
5																	
6																	
7																	
8																	
9																	
10																	

Total Number of Corbels: 7

Typical Corbel Height (mm): LHS 340 RHS 340

Corbel No:

Material Type:

Requires Bolting:

A1/A2 End

Condition State:

A1/A2 End

1	2	3	4	5	6	7	8	9	10	11	12	13	14
JAR	JAR	JAR	JAR	JAR	JAR	JAR							
2	2	2	2	2	2	2	2						

Ironwork Condition:

MEDIUM RUST

Tightening Required:

No

Walers

Size

V

-

x

H

-

Bracing

Size

V

-

x

H

-

Saturated Piles:

LHS Halfcaps

Size

V 330

H 170

Length

7300

No. of

2

Gap between H/Caps

150

Top of H/Caps to underside of Deck

710

H/Cap Material

JAR

RHS Halfcaps

Size

V

H

Length

No. of

Gap between H/Caps

Top of H/Caps to underside of Deck

H/Cap Material

Are there more than 2 sets of halfcaps or sill beams (YES/NO)

No

(If yes record details on comments sheet)

Comments:

STUB PILES ARE SEATED ON TIMBER BEDLOG, SEATED ON CONCRETE FOOTING.  
AB 2 H.C JOIN HAS SPLITS & MINOR SAG. - NO CHANGE FROM PREVIOUS DIR.  
CONCRETE FOOTING HAS MINOR CRACKS BETWEEN PILE 2 & 3.

A2 HC SPlice HAS CRACKING

SEE AUDIT PHOTO 1 A1 OK

Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____	Pile No.: _____ A2 _____ LHS _____ A1 _____ RHS _____
-------------------------------------------------------------------	-------------------------------------------------------------------	-------------------------------------------------------------------	-------------------------------------------------------------------




# TIMBER BRIDGE DETAILED INSPECTION REPORT



## BEDLOG PIERS

Pier No: 1

Bridge No: 3128A



Bedlog No.	Vert. (mm)	Mat. Type	Drilling (mm)	BELOW STRINGER NUMBER												Bolt Req.	Cond State
				1	2	3	4	5	6	7	8	9	10	11	12		
1	300	JAR	Solid (Front)	140	300	300	120										L
			Rot/Pipe	80			120										
			Solid (Rear)	80			60										
2			Solid (Front)														
			Rot/Pipe														
			Solid (Rear)														

Bedlog No.	LHS (mm)					CENTRE LINE (mm)				RHS (mm)			
	Face	Solid	Rot	Pipe	Bolt reqd.	Solid	Rot	Pipe	Bolt reqd.	Solid	Rot	Pipe	Bolt reqd.
3	Front												
	Rear												
4	Front												
	Rear												
5	Front												
	Rear												
6	Front												
	Rear												
7	Front												
	Rear												

Total Number of Corbels: 7

Typical Corbel Height (mm): LHS          RHS         

Corbel No:  
Material Type:  
Requires Bolting: A1/A2 End  
Condition State: A1/A2 End

1	2	3	4	5	6	7	8	9	10	11	12
JAR	JAR	JAR	JAR	JAR	JAR	JAR					

Ironwork Condition:          Saturated bedlogs:         

Comments: STUB PILES ARE SEATED ON TIMBER BEDLOG, SEATED ON CONCRETE FOOTING, PILES ARE CHECKED INTO BEDLOG, 300x300 SQUARE





# TIMBER BRIDGE DETAILED INSPECTION REPORT



ABUTMENT: 2



Bridge No: 3128A

Pile No.	Dia. (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Dia. (mm) below H/C (5m+)	Mat. Type	Tied Back	Cond. State
		Solid	Rot	Pipe	Drill Location from top H/C	Above	Below	Location	Requires Band	Marking (Ft/m)	Height Top H/C to Blaze (m)	Height Blaze to GL (m)	A1	A2				
1	320	SEE NOTES			5					-	0.8	-	-	-	-	JAR	✓	2
2	350	SEE NOTES			2.0	0.6	0.2			-	2.2	-	-	-	-	JAR	✓	2
3	290 360	180								-	1.5	-	115	-	-	JAR		2
4	290 330	105	60		1.3					-	1.5	-	120	-	-	JAR		2
5	300 350	125		50	1.3					-	1.5	-	155	-	-	JAR		2
6	300 380	SEE NOTES			2.00	1.3	0.5	0.2		-	1.5	-	160	-	-	JAR		3
7	280 360	130	50		1.4					-	1.5	-	140	-	-	JAR		2
8	280 360	130	50		2.0					-	2.2	-	-	-	-	JAR	✓	2
9	290 300	SEE NOTES			120	0.7				-	0.9	-	-	-	-	JAR	✓	2
10																		
11																		
12																		
13																		
14																		
15																		

Saturated Piles:

LHS Halfcaps Size V 320 170 Length 8450 No. of 1 Gap between H/Caps -

Top of H/Caps to underside of Deck 380 Back of Halfcaps to Sheeting 230 H/Cap Material JAR

RHS Halfcaps Size V H Length  No. of  Gap between H/Caps

Top of H/Caps to underside of Deck  Back of Halfcaps to Sheeting  H/Cap Material

Are there more than 2 sets of halfcaps or sill beams (YES/NO) No (If yes record details on comments sheet)

Comments: ALL PILES ARE STUB PILES SEATED ON TIMBER BEDLOG, SEATED ON CONCRETE FOOTING. PILES 3 TO 9 ARE SAWN AT BASE FOR MOUNTING BRACKETS TO BEDLOG. NO SPLICE NO SIGNS OF DISTRESS

PILE 5 HAS MINOR FIRE DAMAGE.



5 = REF TO PREVIOUS D.I.R. - BURIED IN LONG GRASS

Pile No. <u>1</u> <u>40/s</u> L.H.S <u>160/s</u> R.H.S <u>100/s</u> F= <u>100/s</u>	Pile No. <u>2</u> <u>40/s</u> L.H.S <u>150/s</u> R.H.S <u>130/s</u> F= <u>80/s</u>	Pile No. <u>6</u> <u>20/s</u> L.H.S <u>130/s</u> R.H.S <u>130/s</u> F= <u>80/s</u>	Pile No. <u>9</u> <u>70</u> L.H.S <u>100/s</u> R.H.S <u>170/s</u> F= <u>100/s</u>
-------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------

## BEDLOG ABUTMENTS

Abutment No. 2

Bridge No: 3128A



Bedlog	Vert. (mm)	Mat. Type	Drilling (mm)	BELOW PILE NUMBER												Condition State
				1	2	3	4	5	6	7	8	9	10	11	12	
1	300	JAR	Solid (Front)	U/S	G/S	80	120	110	100	100	300	300				2/3/4
			Rot/Pipe			TO BACK	TO BACK	TO BACK	TO BACK	TO BACK						
			Solid (Rear)			-	-	-	-	-						

Bedlog No.	LHS					CENTRE LINE				RHS			
	Face	Solid	Rot	Pipe	Bolt reqd.	Solid	Rot	Pipe	Bolt reqd.	Solid	Rot	Pipe	Bolt reqd.
3	Front												
	Rear												
4	Front												
	Rear												
5	Front												
	Rear												
6	Front												
	Rear												
7	Front												
	Rear												
8	Front												
	Rear												

Bedlog - Wing Walls: LHS: \_\_\_\_\_ Saturated Bedlogs: \_\_\_\_\_  
 RHS: \_\_\_\_\_  
 Sheeting: LHS: \_\_\_\_\_  
 CENTRE LINE: \_\_\_\_\_  
 RHS: \_\_\_\_\_

Comments: BED LOG FROM LHS TO ABUT FACE IS  
U/S - SEE PHOTOS. ACTIVE TERMITES BELOW PILE 2.  
REPAIR.



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## ABUTMENT 2 and WING WALL SHEETING

Bridge No: 3128A

ABUTMENT 2 SHEETING (indicate ground line, piles and failed sheeting)

9 Skts

LHS	1		RHS
	2		
	3		
	4		
	5		
	6		
	7		
	8		
	9		
	10		
	11		
	12		

SHEETING - ABUTMENT LHS

SOLID

Rot from Pile

To Pile

Centreline

SOLID

Rot from Pile

To Pile

RHS

SOLID

Rot from Pile

To Pile

SHEETING Material Type

J

SHEETING Material Size (mm)

Vertical

220

Depth

70

Condition 1

Condition 2

Condition 3

Condition 4

% Condition State

100

ABUTMENT 2 WING WALLS (indicate ground line, piles and failed sheeting)

9 Skts

10 Skts

LHS	1	RHS
	2	
	3	
	4	
	5	
	6	
	7	
	8	
	9	
	10	
	11	
	12	

WINGCAP / SPIKING RAIL CONDITION

WINGCAP / SPIKING RAIL CONDITION

MINOR WEATH & SPLITS - OK

MINOR WEATH & SPLITS - OK

SHEETING - WING WALLS LHS

SOLID

Rot from Pile

To Pile

RHS

SOLID

Rot from Pile

To Pile

SHEETING Material Type

J

SHEETING Material Size (mm)

Vertical

220

Depth

70

Condition 1

Condition 2

Condition 3

Condition 4

% Condition State

100





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## DETAIL SHEET

Span No: 1

Bridge No: 3128A

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	JAR	JAR	JAR	JAR	JAR							

H Diameter (mm)	540	450	660	440	580	460	540							
V Measurement (mm)	380	380	380	380	380	380	380							

Abutment 1 End	Drill Vertical	Solid (B)	380	380	380	380	380	380						
		Rot												
		Pipe												
		Rot												
		Solid (T)												
	Drill Horiz	Left												
		Right												
	Split	V Bolt Rqd		✓	✓									
		H Bolt Rqd												
	Propped													
	Condition State													

H Diameter (mm)	480	430	610	450	550	490	460							
V Measurement (mm)	440	450	510	470	450	460	470							

Mid Span	Drill Vertical	Solid (B)	440	450	480	470	450	460	470	NOTE: DRILL IS ONLY 480 - LONG. RESULTS GIVEN TO 480 - ONLY. T/OUT REPORT				
		Rot												
		Pipe												
		Rot												
		Solid (T)												
	Drill Horiz	Left												
		Right												
	Split	V Bolt Rqd												
		H Bolt Rqd												
	Propped													
	Condition State													

H Diameter (mm)	430	540	530	500	510	550	410							
V Measurement (mm)	380	380	380	380	380	380	380							

Abutment 2 End	Drill Vertical	Solid (B)	380	380	380	380	380	380	120					
		Rot							80					
		Pipe												
		Rot												
		Solid (T)							180					
	Drill Horiz	Left												
		Right												
	Split	V Bolt Rqd	✓	✓	✓		✓	✓						
		H Bolt Rqd												
	Propped													
	Condition State													

Cond. of Spiking Plank Not Applicable ☒ Size V - Condition S - R - %

Cond. of Decking (Solid/Rot) S 90 R 10 % Cond. of Deck Ends S 90 R 10 %

Decking Size (mm) V 120 x H 220 Decking Timber Type JAR

Span Length from Centreline Supports (m) 5.80 Clear Span Length 5.00 Saturated stringers:

Deck Condition State Condition 1 Condition 2 Condition 3 Condition 4  
Percentage: 90 10 Spiral Grain Stringers: 6

Comments: Sr's 2, 3 Have S.G. STR 1 A2 packing + 2+6 PACK  
Sr 1, A01 Reqs Packing. PACK  
BOLTS NOT REQ.





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## DETAIL SHEET

Span No: 2

Bridge No: 3128A

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	JAR	JAR	JAR	JAR	JAR							

H Diameter (mm)	450	570	490	530	480	560	540							
V Measurement (mm)	380	380	380	380	380	380	380							

Abutment 1 End	Drill Vertical	Solid (B)	380	380	380	380	380	380	380					
		Rot												
		Pipe												
		Rot												
		Solid (T)												
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd		✓				✓	✓					
		H Bolt Rqd												
	Propped													
	Condition State		1	1	1	1	1	1	1					

H Diameter (mm)	520	430	560	470	510	470	480							
V Measurement (mm)	520	470	500	400	450	560	480							

Mid Span	Drill Vertical	Solid (B)	480	180	480	400	450	480	240					
		Rot							60					
		Pipe		70										
		Rot												
		Solid (T)		220					180					
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd												
		H Bolt Rqd												
	Propped													
	Condition State		1	2	1	1	1	1	2					

H Diameter (mm)	560	470	560	450	560	500	450							
V Measurement (mm)	380	380	380	380	380	380	380							

Abutment 2 End	Drill Vertical	Solid (B)	380	380	380	100	380	380	380					
		Rot												
		Pipe				130								
		Rot												
		Solid (T)				150								
	Drill Horiz.	Left												
		Right												
	Split	V Bolt Rqd	✓	✓	✓		✓		✓					
		H Bolt Rqd												
	Propped													
	Condition State		1	1	1	2	1	1	1					

Cond. of Spiking Plank Not Applicable ☒ Size V - Condition S - R - %

Cond. of Decking (Solid/Rot) S 90 R 10 % Cond. of Deck Ends S 90 R 10 %


Decking Size (mm) V 120 x H 220 Decking Timber Type JAR

Span Length from Centreline Supports (m) 5.85 Clear Span Length 4.98 Saturated stringers: \_\_\_\_\_


Deck Condition State Condition 1 Condition 2 Condition 3 Condition 4  
Percentage: 90 10 Spiral Grain Stringers: \_\_\_\_\_

Comments: BOLTS NOT REQD











ROUND THE DIMENSIONS ON THE HALFCAP BEARING ON THE PILE AT BOTH ABUTMENT SIDES OF THE PILE, i.e. ABUTMENT N° 1 & ABUTMENT N° 2



**HALFCAP SEATING ARRANGEMENTS**



## LEGEND

### MATERIAL TYPE

J - JARRAH  
W - WANDOO  
S - STEEL  
U - UNKNOWN TIMBER

### SPLITS

✓ TICK ONLY IF REQUIRED

### PRIORITY BOLT/BAND

U - A.S.A.P.  
H - HIGH PRIORITY  
M - ROUTINE MAINTENANCE  
L - LOW PRIORITY

} FOR AUDIT PURPOSES ONLY

### GENERAL

P - PIPE  
R - ROT  
F - FRIABLE  
S - SOLID  
N/A - NOT APPLICABLE  
V - VERTICAL  
H - HORIZONTAL  
LHS - LEFT HAND SIDE  
RHS - RIGHT HAND SIDE  
Dia - PIPE DIAMETER  
Circ - CIRCUMFERENCE  
A1 - ABUTMENT No. 1  
A2 - ABUTMENT No. 2  
Str - STRINGER  
H/C - HALFCAP  
H/CAP - HALFCAP  
Blz - BLAZE  
CL - CENTRE LINE  
O/A - OVERALL  
GL - GROUND LEVEL  
Ht - HEIGHT  
Ft - FEET  
W - WIDTH BETWEEN WALING  
Cond - CONDITION  
U/S - UNSOUND (STRUCTURALLY)  
SG - SPIRAL GRAIN

NOTE: All dimensions are of solid timber excluding sap wood and any surface rot on piles and stringers

/SE Documents/Management System Manual/Dwgs/timber\_repair.dwg

**Bridge 3142**  
**Havelock Street over**  
**Narrogin Brook**  
**L2 Inspection**





Enquiries: Gavin Johnston on 9323 4431  
Our Ref: 04/4087  
Your Ref:



ABN: 50 860 676 021

## ASSET MANAGER STRUCTURES WHEATBELT REGION

Structure No.: 3142  
Over: Narrogin Brook  
On: Havelock St (4180025)  
SLK: 0.61  
LGA: Town of Narrogin

1. Please find enclosed a copy of the detailed inspection report for the above Local Authority structure.
2. Attached is a schedule of maintenance items that are required to be undertaken in order to maintain structural integrity and extend the life of the Structure.
3. The maintenance items have been entered into IRIS for programming purposes.
4. This report details all components inspected. Some components have not been inspected due to inaccessibility.

Gavin Johnston  
BRIDGE CONDITION MANAGER

*Ken Wong (BCM/A)*  
*for G-J.*  
*8/6/15*  
Enc



**WORK ITEMS - TIMBER BRIDGES**  
**BRIDGE No: 3142**

ITEM NO	ITEM DESCRIPTION	WORK REQD	PRIORITY CODE	COMMENTS
---------	------------------	-----------	---------------	----------

**(A) GENERAL MAINTENANCE**

G005	Bridge - Durability Survey (L3)			
G009	Bridge - Load Rating			
G010	Bridge - Monitor Defect			

**(B) PREVENTATIVE MAINTENANCE**

P101	Bridge - Seal Timber			
P102	Bridge - Maintain Fastener			
P103	Bridge - Fungicide Treatment	Y	1	sillbeams

**(C) ROUTINE MAINTENANCE**

R201	Bearing - Maintain			
R202	Bridge - Remove Graffiti			
R203	Bridge - Repair Scour (Minor)			
R204	Bridge - Eradicate Termites			
R205	Bridge - Clear Debris and Vegetation			
R206	Deck Joint - Maintain			
R207	Deck Surface - Maintain			
R208	Drainage - Maintain			
R209	Expansion Joint - Maintain			
R210	Fence - Remove			
R211	Fence - Repair (Control of Access)			
R212	Guardrail Maintain/Repair			
R213	Kerb - Repair (Minor) - Non Structural			
R214	Lighting - Maintain			
R215	Sign - Maintain			

**(D) SPECIFIC MAINTENANCE**

S315	Bridge - Replace Fastener <1.5m			
S350	Bridge - Repair Scour (Major)			
S366	Bridge - Access - Improve	Y	2	spans 1 & 2
S413	Deck - Repair			
S449	Drainage - Repair			
S455	Expansion Joint - Repair			
S461	Footpath - Repair			
S473	Kerb - Repair			
S501	Abutment - Reconstruct			
S504	Abutment - Repair (Non timber)			
S507	Bedlog - Repair			
S510	Bedlog - Shim			
S522	Corbel - Bolt			
S525	Corbel - Repair			
S528	Corbel - Shim			
S537	Footpath Railing - Repair			
S540	Fullcap - Repair			
S543	Halfcap - Improve Bearing			
S546	Halfcap - Pack			
S549	Halfcap - Repair			
S558	Pier - Repair			
S561	Pile - Band			
S564	Pile - Repair			
S570	Sheeting - Repair			
S588	Wingwall - Repair			
S607	Bearer - Repair			
S643	Joist - Repair			
S655	Stringer - Bolting			
S661	Stringer - Repair			
S667	Stringer - Shim			

**PRIORITY CODE**

0 - Critical Safety Deficiency : EMERGENCY action required (Immediate or within 6 months)

1 - Very High Priority (Within 3 years)

2 - Medium Priority (Within 4 years)

3 - Low Priority (Within 5 years-assess again at next Detailed Inspection)

## DETAILED TIMBER BRIDGE INSPECTION SUMMARY

Bridge No:	3142	Region:	WHEATBELT REGION
River Name:	Narrogin Brook	SLK:	0.61
Road:	Havelock St	Road No:	4180025
LGA:	Town of Narrogin		

---

### 1.0 General

Bridge no. 3142 located on Havelock St in the Shire of Narrogin is a two span bridge crossing Narrogin Brook. The structure requires maintenance in particular the waterway continues silt up and this has resulted in only minimal drilling results being available, excavation is required to improve headroom.

### 2.0 Preventative Maintenance

Preventative maintenance to be undertaken on a 5 year periodic basis. Areas of concern have been identified below. Fungicide treatment of all timber elements in accordance with Specification 850 is required.

### 3.0 Routine Maintenance

Not required.

### 4.0 Specific Maintenance

#### 4.1 Substructure

Undertake works to improve access for elements not inspected.  
(span2 1 & 2)

#### 4.2 Superstructure

Not required.

### 5.0 BCI

Not Available.

### 6.0 Load Rating

Not required.



Paul Olsen  
Engineering Associate

February 10 2015



# TIMBER BRIDGE DETAILED INSPECTION REPORT





## GENERAL INFORMATION - SHEET 1


Bridge No.: 3142

Region:	<u>Wheatbelt</u>	Latitude (S):	<u>-32.943295</u>
		Longitude (E):	<u>117.185440</u>
Road Name:	<u>Havelock St</u>	Road No:	<u>4180025</u>
Local Government:	<u>Narrogin (T)</u>	Owner:	<u>Local Authority</u>
Crossing Name:	<u>Narrogin Brook</u>	SLK:	<u>0.61</u>
Number of Lanes:	<u>2</u>	Length (m):	<u>16.35</u>
Total Width (m):	<u>6.82</u>	Max. Head Room (m):	<u>1.20</u>
Inc. or Excl. Footpath		Min. Head Room (m):	<u>0.80</u>
No. of Spans:	<u>2</u>	Width between Kerbs (m):	<u>6.82</u>
		Concrete Overlay (Y/N):	<u>Y</u>

Piers are numbered along the bridge in ascending order from ABUTMENT 1 to ABUTMENT 2.  
Piles are numbered across the bridge in ascending order from LEFT to RIGHT.  
Stringers are numbered across the bridge in ascending order from LEFT to RIGHT.

Inside and outside kerb depths noted in corners of sketch.

Exposed Deck Ends (RCO only): LHS  RHS 



This Bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Inspection Manual for Western Australian Bridges and Culverts.

Inspected by: S. MAILE P. FISH

Checked by: POLSON K McPHIE

Date: 25-11-14

Date: 4-2-15





# SITE CONDITIONS



Structure No.: 3142

<b>DRIVE THROUGH</b>	Visible Line of Sight from Abut. 1: 30m	
	Visible Line of Sight from Abut. 2: 200m	
	Traffic Sign Positioning Abut. 1 end:	
	Traffic Sign Positioning Abut. 2 end: 1m and SHOULDER	
<b>PARKING POSITION</b> (Maximum distance from edge of lane/road to car)	> 3 m	<input checked="" type="checkbox"/> Position: AB 2 L.H.S.
	1.2 to 3 m	<input type="checkbox"/> Position:
	0 to 1.2 m	<input type="checkbox"/> Position:
<b>ACCESS TO ABUTMENTS</b> (Describe access conditions at each wing)	Abutment 1:	
	LHS:	LOW HEAD ROOM.
	RHS:	
	Abutment 2:	
	LHS:	
	RHS:	
<b>ACCESS TO PIERS</b> (Describe access conditions along each side of the structure)	Vegetation: THICK GROWTH ON RHS. HIGH GRASS ON L.H.S.	
	LHS:	
	RHS:	AS ABOVE
<b>PIER HEADROOM</b>	Minimum (m):	1.1m
	Maximum (m):	
<b>POTENTIAL HAZARDS</b>	Railing/Posts: LOW HEAD ROOM.	
	Bolts:	
	Services:	
	Other:	
<b>FENCES</b>  None	Timber:	Location:
	Wire/Mesh:	Location:
	Electrified:	Location:
	Barbed Wire:	Location:
	Other (Specify):	Location:
<b>WATER</b>	Depth (m): 0.1m	
	Flow Rate: Small	
	Algae: No (Access may be restricted by toxic algae)	
	Tide: No	
	Location: SPAN 1	
	Side of bridge: L.H.S.	
<b>POWERLINES</b>	Horizontal distance from edge of deck (m): 3m	
	Estimated vertical height above deck (m): 5m	

Signature

Date

25-11-14



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GUARDRAIL INFORMATION

Bridge No.: 3142

### Barrier Type

None

RHS Rails No. of Rails (on bridge):

Thriebeam

W Beam

Tric-Bloc Concrete Barrier

Reinforced Concrete Barrier (Type F)

Constant Slope Concrete Barrier

Other Concrete Profiles

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS
X		X	X		X	X		X

### Post Type

None

Concrete

Timber

Steel Type: \_\_\_\_\_

X		X	X		X	X		X

[Types: C Section (C), I Section (I), RHS (R), Square Hollow Section SHS (S), Tubular (T), Steel PFC (PFC), Steel Channel (Ch)]

Off bridge:

Number of Posts off Bridge

Length of Barrier off Bridge (m)

2		3				3		2
4.6		5.2				5.2		4.5

### Visibility Barrier

Timber No. of Rails (on bridge):

Steel Pipe(s) No. of Pipes (on bridge):

Guide Posts

Balustrade

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS

### Top Rails

Steel Pipe

Steel RHS/Channel

Steel C Section (C)

Timber

X		X	X		X	X		X

### End Terminals

Standard End Terminal Types:

WAMELT

SKT-350

ET-2000

X-350

Crash Cushion

Transitions to another barrier system

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS

Non Standard End Terminal Types:

None

Turn-down

Bullnose

Fishtail

Other

X								X
		X				X		

Structural problem found? (Y/N)

N

If yes, comment below.





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## ROUTINE INFORMATION

Bridge No.: 3142

SCUPPERS LOCATION, TYPE & CONDITION  (R619)		None <input checked="" type="checkbox"/> LHS <input type="checkbox"/> RHS <input type="checkbox"/>	Box <input type="checkbox"/> PVC pipe <input type="checkbox"/> Hole in deck <input type="checkbox"/>
		Not Reg'd	Through Deck <input type="checkbox"/> Through Kerb <input type="checkbox"/>
FLASHING TYPE & CONDITION		None <input checked="" type="checkbox"/> PVC pipe <input type="checkbox"/> PGI <input type="checkbox"/>	
BOLT TIGHTENING REQUIRED (R654)		Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
TERMITES (R656)		Active <input type="checkbox"/> Not Active <input checked="" type="checkbox"/>	None Found
PREVENTATIVE FUNGICIDE (R657)		Treated <input type="checkbox"/> Not Treated <input checked="" type="checkbox"/>	TREAT SILL BEAMS
ATTACHED FENCES & OTHER WATERWAY OBSTRUCTIONS (R727)		O.K.	
ROAD SURFACE & KERBING CONDITION (R643)	ON BRIDGE	Road Surface: Bitumen on R.C.O. - OK. Kerbing: None	
	APPROACHES	Road Surface: Bitumen - MINOR CRACKS AT ABUT APP. - OK. Kerbing: None	
VEGETATION (R563)		Requires Clearing: LHS <input type="checkbox"/> Abut 1 <input type="checkbox"/> RHS <input type="checkbox"/> Abut 2 <input type="checkbox"/> Thick Growth on R.H.S.	
STREAM BED CONDITION (General comments and details of location, depth & extent of scour, undermining and silt build up.) (R489)			
SERVICES (Type, Size & Location)		Type	Size (mm) Location
		None	
BRIDGE CONDITION		Priority for Engineering Assessment Low <input checked="" type="checkbox"/> Medium <input type="checkbox"/> High <input type="checkbox"/> Urgent <input type="checkbox"/>	

Comments:





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## GENERAL INFORMATION - SHEET 2

Bridge No.: 3142

### Bridge Status

Built/In Use ☒

Not Used ☐

Date Built 01/09/1935

Skew (angle) 29

Skewed Width (m) 7800

### Widening

Left Hand side ☐ Width (m) \_\_\_\_\_  
Date \_\_\_\_\_

Right Hand side ☐ Width (m) \_\_\_\_\_  
Date \_\_\_\_\_

### Surface Type

Unsurfaced ☐  
Rubberised Seal ☐

Bitumen Seal ☒  
Tiles ☐

Asphalt ☐  
Steel Plate ☐

### Pavement Type

Unpaved ☒

Gravel ☐

Material Unknown ☐

### Footpath Left

Left Kerb (m) - Path (m) \_\_\_\_\_ Right Kerb (m) \_\_\_\_\_

### Footpath Right

Left Kerb (m) - Path (m) \_\_\_\_\_ Right Kerb (m) \_\_\_\_\_

### Median

Left Kerb (m) - Median (m) \_\_\_\_\_ Right Kerb (m) \_\_\_\_\_

Horizontal Clearance Left (m) \_\_\_\_\_

Horizontal Clearance Right (m) \_\_\_\_\_

### Bridge Function 1

Road Bridge ☒

Rail Bridge ☐

Pedestrian Bridge ☐

### Bridge Function 2

Over Water ☒

Over Road ☐

Over Rail ☐

Over Road & Rail ☐

Over Road & Water ☐

Over Rail & Water ☐

Stock Underpass ☐

Pedestrian Underpass ☐

### Concrete Overlay at Kerb Face

Permanent Formwork ☒

Off Form Edge ☐

## SIGNAGE

### Load Limits

Abutment 1 End

14 Tonne

Abutment 2 End

14 Tonne

### Width Markers

Abutment 1

LHS ☒

RHS ☒

Abutment 2

LHS ☒

RHS ☒

Is position of Width Markers a true indication of the bridge width? ☒ (N) N

### Other Signs

No Overtaking or Passing

Abutment 1

LHS ☐

RHS ☐

Abutment 2

LHS ☐

RHS ☐

No Overtaking on Bridge

Abutment 1

LHS ☐

RHS ☐

Abutment 2

LHS ☐

RHS ☐

One Lane Bridge

Abutment 1

LHS ☐

RHS ☐

Abutment 2

LHS ☐

RHS ☐

Low Clearance .....m

Abutment 1

LHS ☐

RHS ☐

Abutment 2

LHS ☐

RHS ☐

Narrow Bridge Sign

Abutment 1

LHS ☐

RHS ☐

Abutment 2

LHS ☐

RHS ☐

Give Way

Abutment 1

LHS ☐

RHS ☐

Abutment 2

LHS ☐

RHS ☐

### Crossing Sign:

### Other

Abutment 1

LHS ☐

RHS ☐

Abutment 2

LHS ☐

RHS ☐

Abutment 1

LHS ☐

RHS ☐

Abutment 2

LHS ☐

RHS ☐

### Signage Condition Legend

Good

1

Poor

3

Fair

2

None (missing)

4



# TIMBER BRIDGE DETAILED INSPECTION REPORT



## ELEMENT SPACING SHEET 2


Bridge No.: 3142

All measurements (cumulative) are taken from the reference point as indicated by the star ☆


### Pier Pile Centres

Mark in RHS edge of deck and dimension last pile to RHS edge of deck


PIER No. ...1....



PIER No. ....



PIER No. ....




### Typical Stringer Spacing


Mark in RHS edge of deck and dimension last stringer to RHS edge of deck

Note: Stringer spacings must be measured in every span with additional stringers. Use additional sheets as required.


SPAN No. ...1....



SPAN No. ...2....



SPAN No. ....








# TIMBER BRIDGE DETAILED INSPECTION REPORT



## SILL BEAM ABUTMENT 1

Bridge No: 3142

Mark in  
extent of  
Abrasion  
or other  
Damage



☼ = Drill Location

Sill Beam	Dimens. (mm)	Mat. Type	Drilling (mm)	SILL BEAM CONDITION BELOW STRINGER NUMBER												Condition State
				1	2	3	4	5	6	7	8	9	10	11	12	
1	H	IAR	Solid (Front)	130	110	100	*	*								2
	400		Rot/ Pipe	80	160	150										
	V		Solid (Rear)	190	130	150										
2	H	IAR	Solid (Front)						360							1
	360		Rot/ Pipe													
	V		Solid (Rear)													
3	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
4	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
5	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													
6	H		Solid (Front)													
			Rot/ Pipe													
	V		Solid (Rear)													

Sheeting: LHS: }  
CENTRE LINE: } OFS BUT HAS CONCRETE BEHIND.  
RHS: }



Saturated Sill beams: \_\_\_\_\_

Comments: STONE PROUD OF CONCRETE. MINOR CRACK AT L.H. CORNER. - OK

\* - UNABLE TO DRILL DUE TO LOW HEADROOM - TYPICAL TROUT REPORT.



# SILL BEAM PIER



Pier No. \

Sill Beam	Dimens. (mm)	Mat. Type	Drilling (mm)	SILL BEAM CONDITION BELOW STRINGER NUMBER												Condition State
				1	2	3	4	5	6	7	8	9	10	11	12	
1	H	J	Solid (Front)	A20	*	*	*	*	*	A20						
	V		Rot/ Pipe													
	290		Solid (Rear)													
2	H		Solid (Front)													
	V		Rot/ Pipe													
			Solid (Rear)													
3	H		Solid (Front)													
	V		Rot/ Pipe													
			Solid (Rear)													
4	H		Solid (Front)													
	V		Rot/ Pipe													
			Solid (Rear)													
5	H		Solid (Front)													
	V		Rot/ Pipe													
			Solid (Rear)													

Total Number of Corbels: 7

Typical Corbel Height (mm): LHS 290 RHS 290

Corbel No:

Material Type:

Requires Bolting:

Condition State:

A1/A2 End

A1/A2 End

1	2	3	4	5	6	7	8	9	10	11	12
3	5	5	5	5	5	5					

Ironwork Condition:

Saturated bedlogs:

Comments:

Minor cracks in concrete & some pitting. OK  
Bedlog is in 3 sections.




# TIMBER BRIDGE DETAILED INSPECTION REPORT



## SILL BEAM ABUTMENT 2

Bridge No: 3142



Sill Beam	Dimens. (mm)	Mat. Type	Drilling (mm)	SILL BEAM CONDITION BELOW STRINGER NUMBER												Condition State
				1	2	3	4	5	6	7	8	9	10	11	12	
1	H	MCN	Solid (Front)	CONCRETE												
	V		Rot/ Pipe													
			Solid (Rear)													
2	H		Solid (Front)													
	V		Rot/ Pipe													
			Solid (Rear)													
3	H		Solid (Front)													
	V		Rot/ Pipe													
			Solid (Rear)													
4	H		Solid (Front)													
	V		Rot/ Pipe													
			Solid (Rear)													
5	H		Solid (Front)													
	V		Rot/ Pipe													
			Solid (Rear)													
6	H		Solid (Front)													
	V		Rot/ Pipe													
			Solid (Rear)													

Sheeting: LHS: \_\_\_\_\_ Saturated Sill beams: \_\_\_\_\_

CENTRE LINE: N/A \_\_\_\_\_

RHS: \_\_\_\_\_

Comments: Minor Crack At L.H. Corner OK.





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## DETAIL SHEET

Span No: 1

Bridge No: 3142

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	JAR	JAR	JAR	JAR								

Abutment 1 End	H Diameter (mm)	410	510	360	520	450	460							
	V Measurement (mm)	360	360	360	360	360	360							
	Drill Vertical	Solid (B)	110	180	160	*	*	220						
		Rot												
		Pipe	210	110	70			80						
		Rot												
	Solid (T)	30	70	130			60							
	Drill Horiz.	Left	180											
		Right	210											
Split	V	Bolt Rad					-	-						
	H	Bolt Rad												
Propped														
Condition State		2	2	2			2							

Mid Span	H Diameter (mm)	440	440	460	430	450	490							
	V Measurement (mm)	460	450	390	440	480	480							
	Drill Vertical	Solid (B)	460	*	*	*	*	2000						
		Rot												
		Pipe						TO						
		Rot						TOP						
	Solid (T)													
	Drill Horiz.	Left					150							
		Right					100							
Split	V	Bolt Rad						-						
	H	Bolt Rad												
Propped														
Condition State		1					2							

NOTE:  
Drill is only 1800 long.  
Pipes given to 4800 only.  
Tight Ropes.

Abutment 2 End	H Diameter (mm)	430	410	480	440	600	440							
	V Measurement (mm)	360	360	360	360	360	360							
	Drill Vertical	Solid (B)	360	*	*	*	*	120						
		Rot												
		Pipe						TO						
		Rot						TOP						
	Solid (T)													
	Drill Horiz.	Left					100							
		Right					150							
Split	V	Bolt Rad	-					-						
	H	Bolt Rad	-											
Propped														
Condition State		1					3							

Cond. of Spiking Plank Not Applicable ☐ Size V 110 Condition S 90 R 10 %

Cond. of Decking (Solid/Rot) S 80 R 20 % Cond of Deck Ends S - R - %

Decking Size (mm) V 120 x H 225 Decking Timber Type JAR

Span Length from Centreline Supports (m) 7.80 Clear Span Length 6.74 Saturated stringers:

Deck Condition State Percentage: Condition 1  Condition 2 80 Condition 3  Condition 4 20

Comments: Bonddeck used LHS to Str 2 & Str 5 to RHS.

Old termite nest at Ab 1 end between Str 2 & 3. - Not Active





# TIMBER BRIDGE DETAILED INSPECTION REPORT



## DETAIL SHEET

Span No: 2

Bridge No: 3142

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	STE	JAR	STE	JAR	JAR	JAR	JAR							

Abutment 1 End	H Diameter (mm)		190	390	190	500	400	610	400										
	V Measurement (mm)		460	360	450	360	360	360	360										
	Drill Vertical	Solid (B)	UB	*	UB	*	*	*	130										
		Rot																	
		Pipe							130										
		Rot																	
		Solid (T)							100										
	Drill Horiz.	Left																	
		Right																	
	Split	V	Bolt Rad																
		H	Bolt Rad																
	Propped																		
Condition State									2										

Mid Span	H Diameter (mm)		190	430	190	400	420	440	440										
	V Measurement (mm)		460	450	450	450	430	520	500										
	Drill Vertical	Solid (B)	UB	*	UB	*	*	*	160										
		Rot																	
		Pipe							78										
		Rot							TOP										
		Solid (T)							1										
	Drill Horiz.	Left							110										
		Right							170										
	Split	V Bolt Rad																	
		H Bolt Rad																	
	Propped																		
Condition State			1		1				2										

Abutment 2 End	H Diameter (mm)		190	460	190	370	450	470	510							
	V Measurement (mm)		460	340	450	310	370	370	370							
	Drill Vertical	Solid (B)	UB	*	UB	*	*	*	140							
		Rot														
		Pipe							76							
		Rot							TOP							
	Drill Horiz.	Solid (T)							1							
		Left							180							
	Split	Right							210							
		V	Bolt Rad													
	H	Bolt Rad														
		Propped														
Condition State									2							

Cond. of Spiking Plank Not Applicable ☐ Size V 120 Condition S 90 R 10 %

Cond. of Decking (Solid/Rot) S 70 R 30 % Cond of Deck Ends S - R - %

Decking Size (mm) V 120 x H 225 Decking Timber Type JAR

Span Length from Centreline Supports (m) 7.43 Clear Span Length 6.70 Saturated stringers:

Condition 1 Condition 2 Condition 3 Condition 4

Deck Condition State Percentage:  70  30


Comments: Boulder used L.H.S to Str 2 & Str 6 to R.H.S. Boulder used

L.H.S to R.H.S 2m out From Abut Face.











ROUND THE DEMENSIONS ON THE HALFCAP BEARING ON THE PILE AT BOTH ABUTMENT SIDES OF THE PILE. i.e. ABUTMENT N° 1 & ABUTMENT N° 2



## LEGEND

### MATERIAL TYPE

- J - JARRAH
- W - WANDOO
- S - STEEL
- U - UNKNOWN TIMBER

### SPLITS

- ✓ TICK ONLY IF REQUIRED

### PRIORITY BOLT/BAND

- U - A.S.A.P.
- H - HIGH PRIORITY
- M - ROUTINE MAINTENANCE
- L - LOW PRIORITY

FOR AUDIT  
PURPOSES  
ONLY

### GENERAL

- P - PIPE
- R - ROT
- F - FRIABLE
- S - SOLID
- N/A - NOT APPLICABLE
- V - VERTICAL
- H - HORIZONTAL
- LHS - LEFT HAND SIDE
- RHS - RIGHT HAND SIDE
- Dia - PIPE DIAMETER
- Circ - CIRCUMFERENCE
- A1 - ABUTMENT No. 1
- A2 - ABUTMENT No. 2
- Str - STRINGER
- H/C - HALFCAP
- H/CAP - HALFCAP
- Blz - BLAZE
- CL - CENTRE LINE
- O/A - OVERALL
- GL - GROUND LEVEL
- Ht - HEIGHT
- Ft - FEET
- W - WIDTH BETWEEN WALING
- Cond - CONDITION
- U/S - UNSOUND (STRUCTURALLY)
- SG - SPIRAL GRAIN

NOTE: All dimensions are of solid timber excluding sap wood and any surface rot on piles and stringers

/SE Documents/Management System Manual/Dwgs/timber\_repair.dwg





**TIMBER BRIDGE  
DETAILED INSPECTION  
REPORT**



**PHOTOGRAPHIC RECORD**

**Bridge No.:** 3142

Photo No.	Camera No.	Caption
1		BRIDGE NO
2		O/A View FROM AB 1
3		L.H.S View FROM AB 1
4		R.H.S View FROM AB 1
5		LOAD LIMIT SIGN 14 T.
6		AB 1 L.H. Wing Wall
7		AB 1 R.H. Wing Wall
8		AB 2 L.H. Wing Wall
9		AB 2 R.H. Wing Wall
10		AB 1 FACE FROM R.H.S.
11		STR LAYOUT w SPAN 1 FROM R.H.S.
12		PIER 1 LAYOUT FROM R.H.S.
13		AB 2 FACE FROM R.H.S.
14		Minor Crack At AB 1 Approach L.H.S.
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		

# **Bridge**

## **Pioneer Drive**

### **Pedestrian Bridge**

### **L2 Inspection**





Enquiries: Gavin Johnston on 08 9323 4431  
Our Ref: 04/8279  
Your Ref:

ABN: 50 860 676 021

## ASSET MANAGER STRUCTURES WHEATBELT SOUTH REGION

BRIDGE No.: 9250  
OVER: Northam - Cranbrook Hwy And Rail  
AT SLK: 167.89  
ON: Northam Cranbrook  
ROAD No.: M031  
LGA: Narrogin (T)

1. Please find enclosed the detailed inspection report for the above structure.
2. Attached is a schedule of work items that are required to be undertaken in order to maintain structural integrity and extend the life of the structure.
3. The work items have been entered into BMS for programming purposes.

*FOR*  
Gavin Johnston  
BRIDGE CONDITION MANAGER

*[Signature]* 25/10/2013

Enc.

Don Aitken Centre, Waterloo Crescent, East Perth or PO Box 6202 EAST PERTH Western Australia 6892  
Telephone: (08) 9323 4111 Facsimile: (08) 9323 4136 TTY: (08) 9428 2230  
Email: [dac@mainroads.wa.gov.au](mailto:dac@mainroads.wa.gov.au) Website: [www.mainroads.wa.gov.au](http://www.mainroads.wa.gov.au)





# **WORK ITEMS - SUMMARY** **CONCRETE & STEEL BRIDGES**

**BRIDGE No. 9250**

**(A) GENERAL SUPPORTING ACTIVITIES**

BMS Item No.	ITEM DESCRIPTION	WORK REQD	PRIORITY CODE	COMMENTS
G005	Bridge - Durability Survey (L3)			
G009	Bridge - Load Rating			
G010	Bridge - Monitor Defect			

**(B) PREVENTATIVE MAINTENANCE**

BMS Item No.	ITEM DESCRIPTION	WORK REQD	PRIORITY CODE	COMMENTS
P102	Bridge - Maintain Fastener			

**(C) ROUTINE MAINTENANCE**

BMS Item No.	ITEM DESCRIPTION	WORK REQD	PRIORITY CODE	COMMENTS
R201	Bearing - Maintain	Y	2	Treat corrosion and replace nut to the bolts along the bearing plates to abutment 2.
R202	Bridge - Remove Graffiti			
R203	Bridge - Repair Scour (Minor)			
R205	Bridge - Clear Debris and Vegetation			
R207	Deck Surface - Maintain	Y	1	Repair cracking, rotting and trip hazards to the surfacing. Reapply anti-slip coating.
R208	Drainage - Maintain			
R209	Expansion Joint - Maintain			
R210	Fence - Remove			
R212	Guardrail - Maintain / Repair	Y	1	Pier protection barriers are of inadequate length and require extending
R213	Kerb - Repair (Minor) - Non Structural			
R214	Lighting - Maintain			
R215	Sign - Maintain			

**(D) SPECIFIC WORKS**

BMS Item No.	ITEM DESCRIPTION	WORK REQD	PRIORITY CODE	COMMENTS
S504	Abutment - Repair (Non-Timber)			
S401	Approach Slab - Install			
S407	Approach Slab - Repair			
S601	Beam - Repair			
S607	Bearer - Repair	Y	1	Repair timber bearers
S619	Bearing - Repair			
S513	Bracing - Replace			
S350	Bridge - Repair Scour (Major)			
S308	Bridge - Widen Embankment			
S324	Bridge - Control Corrosion	Y	2	Treat corrosion to the railings, holding down bolts, columns, bracing, beams, tie-beams and cross-beams.
S516	Capbeam - Repair			
S519	Column - Repair			
S413	Deck - Repair			
S431	Deck Joint - Repair			
S531	Diaphragm - Repair			
S455	Expansion Joint - Repair			
S534	Footpath - Repair			
S461	Footpath - Repair			
S537	Footpath Railing - Repair			
S467	Guardrail - Install			
S473	Kerb - Repair			
S555	Mechanically Stabilised Earth Wall - Repair			
S558	Pier - Repair			
S564	Pile - Repair			
S567	Pile Cap - Repair			
S385	Services - Repair			
S479	Slab - Repair			
S585	Wing Wall - Extend			
S588	Wing Wall - Repair			

**PRIORITY CODE**

- 1 - High Priority
- 2 - Medium Priority
- 3 - Low Priority (monitor)

**INDICATIVE TIMEFRAME**

- Within 3 years
- Within 4-6 years
- Assess again at next Detailed (Level 2)
- Inspection (7 years for non-timber bridges)

*Note: Add additional standard work items to the above lists as required.*

*Refer to Detailed Visual Bridge Inspection Guidelines for Concrete & Steel Bridges for full listing.*

## DETAILED CONCRETE AND STEEL BRIDGE INSPECTION SUMMARY

<b>Bridge No.:</b>	9250	<b>Region:</b>	Wheatbelt South Region
<b>Crossing Name:</b>	Northam - Cranbrook Hwy And Rail	<b>SLK:</b>	167.89
<b>Road:</b>	Northam Cranbrook	<b>Road No.:</b>	M031
<b>LGA:</b>	Narrogin (T)		

---

### 1.0 GENERAL

This is a steel I-beam structure with timber decking, although the bridge is a mix of both timber and steel elements. In 2000 the footbridge was modified due to construction of the Northam-Cranbrook Highway, date of original construction is unknown. Generally the bridge is considered to be in a reasonable condition.

### 2.0 SUBSTRUCTURE

#### 2.1 Abutments

Minor surface corrosion is common throughout abutment 1. The bolts to the bearing plates within abutment 2 are also badly corroded.

#### 2.2 Piers


Surface corrosion is common throughout piers 1 and 5 - 9. The holding down bolts to pier 7 are badly corroded and the nuts have sheared off. Shrinkage cracking to the exposed sections of the footings to piers 2 - 4 was also noted.

### 3.0 SUPERSTRUCTURE

Surface corrosion is common to the beams, tie-beams and bracing of spans 1 and 6 - 9. Within span 7 there are some cross-beams which are also suffering minor surface corrosion. The timber bearers within spans 2 and 5 - 7 are also splitting through the centre.

### 4.0 RECOMMENDATIONS

1. Treat corrosion and replace nut to the bolts along the bearing plates to abutment 2.
2. Repair cracking, rotting and trip hazards to the surfacing. Reapply anti-slip coating.
3. Pier protection barriers are of inadequate length and require extending.
4. Repair timber bearers.
5. Treat corrosion to the railings, holding down bolts, columns, bracing, beams, tie-beams and cross-beams.
6. Change to a hybrid structure.

  
J Hesketh  
STRUCTURES INSPECTOR

8th February 2013





# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT




<b>Bridge Number:</b>	9250		<b>Date:</b>	08-February-2013	
<b>Structure Type:</b>	Steel		<b>GPS Location</b>	<b>Lat.:</b>	-32.93528
<b>Superstructure:</b>	I-Beam		<b>Long.:</b>	117.18011	
<b>Responsibility Area:</b>	Wheatbelt South Region		<b>Road Number:</b>	M031	
<b>Road Name:</b>	Northam Cranbrook		<b>Owner:</b>	Local Authority	
<b>Local Govt.:</b>	Narrogin (T)		<b>SLK:</b>	167.89	
<b>Crossing Name:</b>	Northam - Cranbrook Hwy And Rail		<b>Skew:</b>	0 degrees	
<b>Total Width (m):</b>	2.12	<b>Max. H/Room (m):</b>	6.40	<b>Min. H/Room (m):</b>	0.59
<b>No. Spans:</b>	10	<b>Width Between Kerbs (m):</b>	2.12	<b>Length (m):</b>	85.53

Abutments are numbered in the direction of increasing SLK.

Piers are numbered along the bridge in ascending order from Abutment 1 to Abutment 2.

Piles and Columns are numbered across the bridge in ascending order from left to right when facing the direction of increasing SLK.

Beams are numbered across the bridge in ascending order from left to right when facing the direction of increasing SLK.



Mark in widening and footpath locations.

This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Bridge Guidelines for Level 2 inspections of concrete and steel bridges.

Inspected by: J Hesketh

Checked by: \_\_\_\_\_

Date: 08-February-2013

Date: \_\_\_\_\_





# SITE CONDITIONS



Bridge No.: 9250

DRIVE THROUGH	Visible Line of Sight from Abut. 1:	>200m
	Visible Line of Sight from Abut. 2:	>200m
TRAFFIC CONTROL (Describe if different to the generic TMP)	Abut. 1 end:	1m
	Abut. 2 end:	1m
PARKING POSITION	> 3 m	<input checked="" type="checkbox"/> Position: Fairway Street
	1.2 to 3 m	<input type="checkbox"/> Position:
	0 to 1.2 m	<input type="checkbox"/> Position:
ACCESS TO ABUTMENTS (Describe access conditions at each wing)	Abutment 1:	
	LHS:	From Ground level
	RHS:	From Ground level
	Abutment 2:	
	LHS:	From Ground level
	RHS:	From Ground level
ACCESS TO PIERS (Describe access conditions along each side of the structure)	Vegetation:	Ok
	LHS:	From Ground level
	RHS:	From Ground level
PIER HEADROOM	Minimum (m):	0.6
	Maximum (m):	6.4
POTENTIAL HAZARDS	Railing/Posts:	
	Bolts:	
	Services:	Street lighting
	Other:	
FENCES	Timber:	<input type="checkbox"/> Location:
	Wire/Mesh:	<input type="checkbox"/> Location: None
	Electrified:	<input type="checkbox"/> Location:
	Barbed Wire:	<input type="checkbox"/> Location:
	Other (Specify):	<input type="checkbox"/> Location:
	WATER	Depth (m):
POWERLINES	Flow Rate:	
	Algae:	{Access may be restricted by toxic algae}
	Tide:	
	Location:	
	Side of bridge:	None
	Horizontal distance from edge of deck (m):	
Estimated vertical height above deck (m):		

J Hesketh  
Signature

8th February 2013  
Date





# DETAILED BRIDGE INSPECTION REPORT

## Guardrail Information

Bridge No.: 9250

### Barrier Type

None

RHS Rails No. of Rails (on bridge):  
Thriebeam

Tric-Bloc Concrete Barrier

Reinforced Concrete Barrier (Type F)

Constant Slope Concrete Barrier

Other Concrete Profiles

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS

### Post Type

None

Concrete

Timber

Steel Type: \_\_\_\_\_

[Types: C Section (C), I Section (I), RHS (R), Square Hollow Section SHS (S), Tubular (T), Steel PFC (PFC), Steel Channel (Ch)]

Off bridge:

Number of Posts off Bridge

Length of Barrier off Bridge (m)


### Visibility Barrier

Timber No. of Rails (on bridge):

Steel Pipe(s) No. of Pipes (on bridge):

Guide Posts

Balustrade

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS
			X		X	X		X

### Top Rails

Steel Pipe

Steel RHS/Channel

Steel C Section (C)

Timber

						X		X

### End Terminals

Standard End Terminal Types:

WAMLT

SKT-350

ET-2000

X-350

Crash Cushion

Transitions to another barrier system

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS

Non Standard End Terminal Types:

None

Turn-down

Bullnose

Fishtail

Other


Structural problem found? (Y/N)

N

If Yes, comment below.



# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: BRIDGE

Group Number: N/A

General Items	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
Vegetation	Good condition			N			
Drainage	Good condition			N			
Pier Protection Barrier	The pier protection barriers are in good condition, however they are of inadequate length to effectively protect the pier from impact damage.		28 - 30	Y	R212	Guardrail - Maintain/Repair	1
Scour	None			N			
Signs and Lights	Street lighting along the footbridge			N			
Fences	None			N			
Services on Bridge (types, size, location)	Street lighting along the footbridge			N			





**Group Number:** 2

[illegible]



Bridge Number: 9250

Group: DECK

**Group Number:** N/A

[illegible]



# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: ABUTMENT

Group Number: 1

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Pile/Column	1-4	Steel	Existing	Linear m		100				Minor corrosion to the columns and the holding down bolts		26	Y	S324	Bridge - Control Corrosion	2
Bracing	1-28	Steel	Existing	Each		100				Minor corrosion to the bracing		25	Y	S324	Bridge - Control Corrosion	2
Footing	1-2	Concrete	Existing	m^2	100				75	Good Condition, however the majority of the footings are buried		25	N			
{Bearing Units shall only be assigned Condition States when structural. In this instance, 'structural' means that the bearing is a rocker, elastomeric or pot bearing. Mortar pad or thin rubber bearings shall be inspected with comments but the Condition State columns shall be greyed out in the inspection report template.}																



**Group Number:** 2

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Wing Wall	LHS	Concrete	Existing	m^2	100					Good condition		39	N			
Wing Wall	RHS	Concrete	Existing	m^2	100					Good condition		40	N			
Wall	1	Concrete	Existing	m^2	100					Good condition		5	N			
Bearing Unit	1-2	Rubber	Existing	Each						Bolts to the steel plates are corroded		55	Y	R201	Bearing - Maintain	1
Footings	1	Concrete	Existing	m^2	100					Good condition			N			

{Bearing Units shall only be assigned Condition States when structural. In this instance, 'structural' means that the bearing is a rocker, elastomeric or pot bearing.  
Mortar pad or thin rubber bearings shall be inspected with comments but the Condition State columns shall be greyed out in the inspection report template.}



# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: PIER

Group Number: 1

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Bracing	1-7	Steel	Existing	Each		100				Minor corrosion common throughout the bracing		21	Y	S324	Bridge - Control Corrosion	2
Column	1-2	Steel	Existing	Linear m		100				Minor corrosion common throughout both columns		21	Y	S324	Bridge - Control Corrosion	2
Footing	1-2	Concrete	Existing	m^2	100				75	Good Condition, however the majority of the footings are buried		21				
(Bearing Units shall only be assigned Condition States when structural. In this instance, 'structural' means that the bearing is a rocker, elastomeric or pot bearing. Mortar pad or thin rubber bearings shall be inspected with comments but the Condition State columns shall be greyed out in the inspection report template.)																

Bridge Number: 9250

Group: PIER

Group Number: 2

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Bracing	1-7	Steel	Existing	Each	100					Good condition		19	N			
Column	1-2	Steel	Existing	Linear m	100					Good condition		19	N			
Footing	1	Concrete	Existing	m^2	100				50	Hairline shrinkage cracking to the exposed concrete. Footing is partially buried		27	N			
Footing	2	Concrete	Existing	m^2					100	Buried			N			
{Bearing Units shall only be assigned Condition States when structural. In this instance, 'structural' means that the bearing is a rocker, elastomeric or pot bearing. Mortar pad or thin rubber bearings shall be inspected with comments but the Condition State columns shall be greyed out in the inspection report template.}																





# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: PIER

Group Number: 3

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Bracing	1-7	Steel	Existing	Each	100					Good condition		17	N			
Column	1-2	Steel	Existing	Linear m	100					Good condition		17	N			
Footing	1	Concrete	Existing	m^2	80	20			50	Shrinkage cracking to the exposed concrete. Footing is partially buried		31	N			
Footing	2	Concrete	Existing	m^2					100	Buried			N			
{Bearing Units shall only be assigned Condition States when structural. In this instance, 'structural' means that the bearing is a rocker, elastomeric or pot bearing. Mortar pad or thin rubber bearings shall be inspected with comments but the Condition State columns shall be greyed out in the inspection report template.}																



# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: PIER

Group Number: 4

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Bracing	1-7	Steel	Existing	Each	100					Good condition		15	N			
Column	1-2	Steel	Existing	Linear m	100					Good condition		15	N			
Footing	1	Concrete	Existing	m^2	80	20			50	Shrinkage cracking to the exposed concrete. Footing is partially buried		35	N			
Footing	2	Concrete	Existing	m^2					100	Buried			N			
{Bearing Units shall only be assigned Condition States when structural. In this instance, 'structural' means that the bearing is a rocker, elastomeric or pot bearing. Mortar pad or thin rubber bearings shall be inspected with comments but the Condition State columns shall be greyed out in the inspection report template.}																



# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: PIER

Group Number: 5

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Bracing	1-7	Steel	Existing	Each		100				Minor corrosion common throughout the bracing		53	Y	S324	Bridge - Control Corrosion	2
Column	1-2	Steel	Existing	Linear m		100				Minor corrosion common throughout both columns		53	Y	S324	Bridge - Control Corrosion	2
Footing	1	Concrete	Existing	m^2	100				75	Good Condition, however the majority of the footings are buried		53	N			
{Bearing Units shall only be assigned Condition States when structural. In this instance, 'structural' means that the bearing is a rocker, elastomeric or pot bearing. Mortar pad or thin rubber bearings shall be inspected with comments but the Condition State columns shall be greyed out in the inspection report template.}																



Bridge Number: 9250

Group: PIER

Group Number: 6

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Bracing	1-7	Steel	Existing	Each		100				Minor corrosion common throughout the bracing		51	Y	S324	Bridge - Control Corrosion	2
Column	1-2	Steel	Existing	Linear m		100				Minor corrosion common throughout both columns		51	Y	S324	Bridge - Control Corrosion	2
Footing	1	Concrete	Existing	m^2	100				75	Good Condition, however the majority of the footings are buried		51	N			
{Bearing Units shall only be assigned Condition States when structural. In this instance, 'structural' means that the bearing is a rocker, elastomeric or pot bearing. Mortar pad or thin rubber bearings shall be inspected with comments but the Condition State columns shall be greyed out in the inspection report template.}																



# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: PIER

Group Number: 7

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Bracing	1-7	Steel	Existing	Each		90		10		Minor corrosion common throughout the bracing. Holding down bolts badly corroding and sheared off.		36	Y	S324	Bridge - Control Corrosion	2
Column	1-2	Steel	Existing	Linear m		100				Minor corrosion common throughout both columns		11	Y	S324	Bridge - Control Corrosion	2
Footing	1	Concrete	Existing	m^2	100				75	Good Condition, however the majority of the footings are buried		11	N			
{Bearing Units shall only be assigned Condition States when structural. In this instance, 'structural' means that the bearing is a rocker, elastomeric or pot bearing. Mortar pad or thin rubber bearings shall be inspected with comments but the Condition State columns shall be greyed out in the inspection report template.}																

Bridge Number: 9250

Group: PIER

Group Number: 8

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Bracing	1-4	Steel	Existing	Each		100				Minor corrosion common throughout the bracing		9	Y	S324	Bridge - Control Corrosion	2
Column	1-2	Steel	Existing	Linear m		100				Minor corrosion common throughout both columns		9	Y	S324	Bridge - Control Corrosion	2
Footing	1	Concrete	Existing	m^2	100				75	Good Condition, however the majority of the footings are buried		9	N			
{Bearing Units shall only be assigned Condition States when structural. In this instance, 'structural' means that the bearing is a rocker, elastomeric or pot bearing. Mortar pad or thin rubber bearings shall be inspected with comments but the Condition State columns shall be greyed out in the inspection report template.}																





# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: PIER

Group Number: 9

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Bracing	1-4	Steel	Existing	Each		100				Minor corrosion common throughout the bracing		7	Y	S324	Bridge - Control Corrosion	2
Column	1-2	Steel	Existing	Linear m		100				Minor corrosion common throughout both columns		7	Y	S324	Bridge - Control Corrosion	2
Footing	1	Concrete	Existing	m^2	100				50	Good Condition, however the majority of the footings are buried		7	N			
{Bearing Units shall only be assigned Condition States when structural. In this instance, 'structural' means that the bearing is a rocker, elastomeric or pot bearing. Mortar pad or thin rubber bearings shall be inspected with comments but the Condition State columns shall be greyed out in the inspection report template.}																





# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: SPAN

Group Number: 2

Span Length (m): \_\_\_\_\_ (CL to CL)

Span Length (m): 11.184 (Clear Span)

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Beam	1-2	Steel	Existing	Linear m	100					Good condition		20	N			
Bearers	1-2	Jarrah	Existing	Each	50	50				Splitting through the centre of the timber bearers		20	Y	S607	Bearer - Repair	1
Bracing	1-5	Steel	Existing	Each	100					Good condition		20	N			
Tie Beam	1-6	Steel	Existing	Linear m	100					Good condition		20	N			
Spiking Beam	1-2	Jarrah	Existing	Each	100					Good condition		20	N			





# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: SPAN

Group Number: 3

Span Length (m): \_\_\_\_\_ (CL to CL)

Span Length (m): 11.002 (Clear Span)

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Beam	1-2	Steel	Existing	Linear m	80	20				Minor corrosion to the beams		18	Y	S324	Bridge - Control Corrosion	2
Bearers	1-2	Jarrah	Existing	Each	100					Good condition		18	N			
Bracing	1-5	Steel	Existing	Each	100					Good condition		18	N			
Tie Beam	1-6	Steel	Existing	Linear m	100					Good condition		18	N			
Spiking Beam	1-2	Jarrah	Existing	Each	100					Good condition		18	N			

**Group Number:** 4

**Span Length (m):** 11.029 (Clear Span)

[illegible]



# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: SPAN

Group Number: 5

Span Length (m): \_\_\_\_\_ (CL to CL)

Span Length (m): 9.827 (Clear Span)

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Beam	1-2	Steel	Existing	Linear m	100					Good condition	14	N				
Bearers	1-2	Jarrah	Existing	Each		100				Splitting through the centre of the timber bearers	14	Y	S607	Bearer - Repair		1
Bracing	1-5	Steel	Existing	Each		100				Minor corrosion common along the bracing	14	Y	S324	Bridge - Control Corrosion		2
Tie Beam	1-5	Steel	Existing	Linear m		100				Minor corrosion common along the tie-beams	14	Y	S324	Bridge - Control Corrosion		2
Spiking Beam	1-2	Jarrah	Existing	Each	100					Good condition	14	N				







# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: SPAN

Group Number: 7

Span Length (m): \_\_\_\_\_ (CL to CL)

Span Length (m): 5.873 (Clear Span)

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Beam	1-2	Steel	Existing	Linear m		100				Minor corrosion common along the beams		12	Y	S324	Bridge - Control Corrosion	2
Bearers	1-2	Jarrah	Existing	Each	50		50			Splitting through the centre of the timber bearers		12	Y	S607	Bearer - Repair	1
Bracing	1-5	Steel	Existing	Each		100				Minor corrosion common along the bracing		12	Y	S324	Bridge - Control Corrosion	2
Tie Beam	1-4	Steel	Existing	Linear m		100				Minor corrosion common along the tie-beams		12	Y	S324	Bridge - Control Corrosion	2
Spiking Beam	1-2	Jarrah	Existing	Each	100					Good condition		12	N			
Cross Beam	1-4	Steel	Existing	Linear m		100				Minor corrosion common along the cross-beams		54	Y	S324	Bridge - Control Corrosion	2



# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: SPAN

Group Number: 8

Span Length (m): \_\_\_\_\_ (CL to CL)

Span Length (m): 13.538 (Clear Span)

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Beam	1-2	Steel	Existing	Linear m		100				Water staining and minor corrosion common along the beams	10		Y	S324	Bridge - Control Corrosion	2
Bearers	1-2	Jarrah	Existing	Each	100					Good condition	10		N			
Bracing	1-7	Steel	Existing	Each		100				Water staining and minor corrosion common along the bracing	10		Y	S324	Bridge - Control Corrosion	2
Tie Beam	1-8	Steel	Existing	Linear m		100				Water staining and minor corrosion common along the tie-beams	10		Y	S324	Bridge - Control Corrosion	2
Spiking Beam	1-2	Jarrah	Existing	Each	100					Good condition	10		N			







# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250

Group: SPAN

Group Number: 10

Span Length (m): \_\_\_\_\_ (CL to CL)

Span Length (m): 5.837 (Clear Span)

Component Type	Component Number	Component Material	Modification Status	Unit	Percentage of Inspected Component in Each Condition State				Not Inspected (%)	Comments  Full description including details of: * Location of defect/condition/item * Description of defects including type, magnitude and extent	Sketch Number	Photograph Number	Work Required	Work Item Number	Work Description	Priority
					1	2	3	4								
Beam	1-2	Steel	Existing	Linear m	100					Water staining to the face of the beams		6	N			
Bearer	1-2	Jarrah	Existing	Each	100					Moisture has caused the paintwork to flake off along the top of the bearers		6	N			
Bracing	1-3	Jarrah	Existing	Each	100					Good condition		6	N			
Tie Beam	1-4	Jarrah	Existing	Linear m	100					Good condition		6	N			
Spiking Beam	1-2	Jarrah	Existing	Each	100					Good condition		6	N			



# DETAILED VISUAL (LEVEL 2) BRIDGE INSPECTION REPORT



Bridge Number: 9250


Crossing: Northam - Cranbrook Hwy And Rail

LGA: Narrogin (T)

Road Name: Northam Cranbrook

Inspector: J Hesketh

SLK: 167.89





# BRIDGE INSPECTION REPORT PHOTO SHEET

Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 1: Bridge identifier




Photo No. 2: LHS



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 3: RHS




Photo No. 4: Deck



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 5: Pilaster 2



Photo No. 6: Span 10



# BRIDGE INSPECTION REPORT PHOTO SHEET

Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 7: Pier 9



Photo No. 8: Span 9



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 9: Pier 8



Photo No. 10: Span 8



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 11: Pier 7



Photo No. 12: Span 7



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 13: Bracing to Pier 5 and 6



Photo No. 14: Span 5

# BRIDGE INSPECTION REPORT PHOTO SHEET

Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 15: Pier 4



Photo No. 16: Span 4



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 17: Pier 3




Photo No. 18: Span 3



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 19: Pier 2




Photo No. 20: Span 2

# BRIDGE INSPECTION REPORT PHOTO SHEET

Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 21: Pier 1



Photo No. 22: Span 1



# BRIDGE INSPECTION REPORT PHOTO SHEET

Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 23: LHS Elevation



Photo No. 24: RHS Elevation



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 25: Pilaster 1



Photo No. 26: Rusting to all Pilaster 1 bolts – minor surfacing rust to steel



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 27: cracking to surface concrete – Pier 2



Photo No. 28: Inadequate pier protection – Pier 2



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 29: Inadequate pier protection – Pier 3



Photo No. 30: Inadequate pier protection – Pier 4



# BRIDGE INSPECTION REPORT PHOTO SHEET

Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 31: cracking to concrete surfacing Pier 3



Photo No. 32: Timber bearing split

# BRIDGE INSPECTION REPORT PHOTO SHEET

Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 33: Minor surface corrosion common throughout



Photo No. 34: Carriageway surfacing



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 35: cracking to concrete 4



Photo No. 36: Bolts Pier 7 badly corroded – sheared off



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 37: Typical surface corrosion to Piers



Photo No. 38: Minor surface corrosion to beams - typical



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 39: Pilaster 2 LHS



Photo No. 40: Pilaster 2 RHS



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 41: A2 end view




Photo No. 42: A2 LHS



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 43: A2 RHS



Photo No. 44: Surfacing A2 cracked



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 45: Rusting to approach 2 rails



Photo No. 46: Minor trip hazard A2 end



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 47: A1 view



Photo No. 48: Cage on bridge



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 49: Rotten timber to deck – Span 2



Photo No. 50: Anti-slip surfacing come of the ramp section of deck



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 51: Pier 6



Photo No. 52: Span 6



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 53: Pier 5



Photo No. 54: Surface corrosion to Pier 5 and 6 bracing



Bridge No.:	9250	LGA:	Narrogin (T)	Date:	08/02/2013
Road Name:	Northam Cranbrook	SLK:	167.89		
Crossing:	Northam – Cranbrook Hwy & Rail	Inspector:	J Hesketh		



Photo No. 55: Corroded bolts to Pilaster 2

**Bridge 3142**  
**Doney Street**  
**Pedestrian Bridge**  
**L2 Inspection**



MRWA 51-4629-15

**DETAILED TIMBER BRIDGE INSPECTION SUMMARY**

Bridge No	4629	Region:	Wheatbelt South
River Name:	Narrogin Brook	SLK:	0.03
Road:	Doney Street	Road No:	0004
LGA:	Narrogin		

**1. General**

The bridge is very old and is used only by pedestrians.

**2. Substructure****2.1 Abutments**

Both abutments have failed sheeting that requires replacement.

**2.2 Fullcaps**

Fullcap ends at both piers are in poor condition. In many places fullcaps are tilted. Abutment 2 fullcap at its joint is drilling poorly.

**2.3 Corbels**

Pier 2 corbel 1 LHS end is rotted. In many places corbels are tilted.

**3. Superstructure**

Stringer 5 in span 1 has failed. There is a large hole in road surface above the stringer. Decking in many places is in poor condition.

**5. Recommendations**

Close the bridge for all traffic.

S. Savic

BRIDGE INSPECTIONS

24 April 2001

Copies done  
 Inspection date on BMS  
 Signature RB Fy Bruce Hall  
 Date 24.4.01



# ROUTINE MAINTENANCE SUMMARY REPORT OF BRIDGE NO:

4629

File : 51- 4629 -15 RIVER NAME: Narrogin Brook  
 LGA: Narrogin ROAD NAME: Doney Street  
 REGION: Wheatbelt South SLK: 0.03  
 Date : 24 April 2001

This summary report should be read in conjunction with the attached field inspection report.  
 A full inspection was carried out on this bridge and the following remarks may be applicable.  
 Where possible this will be shown by the form ie: ☐ Y for YES, and ☐ N for NO.

- |   |                                                                                                    |                            |
|---|----------------------------------------------------------------------------------------------------|----------------------------|
| A | Clean the scuppers and install flashings as required.                                              | <input type="checkbox"/> N |
| B | Tighten all the bolts in the bridge and replace the rusty ones.                                    | <input type="checkbox"/> N |
| C | Treat the structure for active termites.                                                           | <input type="checkbox"/> N |
| D | Preventative timber treatment to piles, stringers and ends of all exposed timber.                  | <input type="checkbox"/> N |
| E | Straighten, tighten the bolts, minor repairs and paint the guardrail on the bridge.                | <input type="checkbox"/> N |
| F | Replace the width marker boards and the signing on the bridge.                                     | <input type="checkbox"/> N |
| G | Remove debris and farmers fences under the bridge.                                                 | <input type="checkbox"/> N |
| H | The approaches at the ends of the bridge require repairs.                                          | <input type="checkbox"/> N |
| I | Deck joint maintenance.                                                                            | <input type="checkbox"/> N |
| J | All vegetation around the bridge should be cleared including debris and weed build-up along kerbs. | <input type="checkbox"/> N |
| K | Embankment status.                                                                                 | <input type="checkbox"/> N |
| L | Monitor scour.                                                                                     | <input type="checkbox"/> N |

## PRIORITY FOR ENGINEERING ASSESSMENT:

LOW ☐ MEDIUM ☐ HIGH ☐ URGENT ☐ Y

(Signed)

*J. Hone*

MAIN ROADS  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PL  
Date: 29.3.2001  
Checked By: S. SAVIC  
Date: 24.04.01

Inspection No: 3  
Bridge No: 4629

Region : WHEAT BELT SOUTH

Local Government : NARROGIN

Road No. : 004

Road Name : DONEY ST SLKm : 0.03

Stream Name : NARROGIN BROOK Overall Length: 11.850m

Width Overall : 10.600m Head Room : 1.400m  
(between  $\text{C}$  of supports at abutments)

Spans : 3 Width Between Kerbs: 10.440m Existing Conc Overlay: 1 (N)


## GENERAL INFORMATION

Piers are numbered along the bridge in ascending order from ABUTMENT 1 to ABUTMENT 2.


Piles are numbered across the bridge in ascending order from LEFT to RIGHT.

Stringers are numbered across the bridge in ascending order from LEFT to RIGHT.

Pavement depths noted in corners of sketch.





 **MAIN ROADS**  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PL  
Date: 29.3.01  
Checked By: SS  
Date: 24.4.01

Inspection No: 3  
Bridge No: 4629

## GENERAL INFORMATION (cont.)

VEGETATION	MEDIUM GROWTH REQS CLEARING.
STREAM BED CONDITION	MUDDY. GOOD - WATER DEPTH 0.200M MAIN STREAM FLOW SPANS 1 & 2
FENCING AND PAINT CONDITION	NONE
RBING	TIMBER 200V X 80H AT A1 R/S ONLY (1.0m ONLY) WEATHERED - FAIR. THE REST OF KERB IS MISSING PHOTO
SCUPPERS / FLASHINGS	NONE
ROAD SURFACE CONDITION	SEALED CRACKED + MINOR UNDULATIONS TWO - OUT - FAIR <u>large hole (w.c.c.t.)</u>
APPROACHES	SEALED CRACKED MINOR UNDULATIONS - FAIR. MAJOR SCOURING AD R/S DUE TO STORM WATER DRAINAGE PIPE - PHOTOS.
SIGNING	NONE REQS 4x WIDTH MARKERS
MITES	ACTIVE SPAN 1 STRS 5 & 6, SPAN 3 STRS 2, 11. ACTIVE ABUT 2 STR 8.
PREVENTIVE FUNGICIDE	NOT TREATED
SERVICES	NONE. 7x 120MM GALV WATER PIPES 1.000M R/S OF BRIDGE NOT ATTACHED.
ATTACHED FENCES AND OTHER WATERWAY OBSTRUCTIONS	NONE
BRIDGE CONDITION	PRIORITY FOR ENGINEERING ASSESSMENT LOW <input type="checkbox"/> MEDIUM <input type="checkbox"/> HIGH <input type="checkbox"/> URGENT <input checked="" type="checkbox"/>

COMMENTS : ALL STRS ARE SQUARE SAWN. ALL SPANS  
BEDROGS BELOW SUB PILES DRILLED IN FEW LOCATIONS - CONSIDERED  
SOLID T/O.






Inspection No: 3  
 Bridge No: 4629



# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PL  
 Date: 29.3.01  
 Checked By: SS  
 Date: 24.4.01

## PILE CENTRES




## PIER PILES




## STRINGER SPACING

SPAN N° 1+3




SPAN N° 2



**MAIN ROADS**  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PLDate: 29.3.01Checked By: SSDate: 24.04.01Inspection No: 3Bridge No: 4629

ABUTMENT : 1

PILE NO	DIA mm	TIMBER DRILLING			EXTENT OF ROT		PILE SPLITS		BLAZE MARKINGS		
		Solid	Rot	Pipe	Below GL	Above GL	Type	RQS Band	Marking Ft / m	Ht H/C to Blz	Ht Blz to GL
1	300	120		30		AT TOP	Lv ↓	✓ 2	-	0.800	-
2	270	115		20			-		-	0.500	-
3	250	105		20		AT TOP	-		-	0.300	-
4	260	110		20			-		-	0.300	-
5	280	240					-		-	0.300	-
6	300	130		20			Lv ↓	✓ 2	-	0.0	-
7											
8											
9											
10											
11											
12											
13											
14											
15											

**SHEETING - WINGWALLS** LHS : NATURAL GROUND - MINOR SCOURING - FAIR

RHS : NATURAL GROUND

**SHEETING - ABUTMENT** C : TOP SHT 10/S REST SOLID

LHS : SOLID

RHS : TOP SHT U/S REST SOLID

**WING CAP CONDITION** : NATURAL GROUND

**FULL CAPS / SILL BEAMS** - SIZE : 300 x 300 No. 1 ① LHS END 20/PIPE

**COMMENTS** : REST SOLID WEATHERED + TERMITE DAMAGE

SOLID RHS END SOLID

TOP SHEET HAS FAILED BEHIND STRS 7,8,9,10,11

FULL CAPS ARE JOINED BETWEEN PILES 2+3 5+6 BOTH ABUTS.

FULL CAPS ARE PLACED ON CORBELS THAT ARE PLACED ON PILES

IRON WORK HAS HEAVY RUST. T/OUT.



MAIN ROADS  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

LIBRARY  
Inspected By: PL

Date: 29.3.01

Checked By: SS

Date: 24.4.01

Inspection No: 3

Bridge No: 4629


## SPECIAL COMMENTS

BRIDGE PART: .....

ABUT 1 CORBELS  
#1 BADLY WEATHERED AT LHS END SOLID BUT LOOSE  
PHOTOS. REST OF CORBELS SOLID.

BED LOG AT ABUT 1 EXCAVATED LHS BELOW PILE 1  
0.900m BELOW. BED LOG Ø 400 SOLID

ALL PILES ARE STUB PILES PLACED ON BEDLOGS  
ALL OUTSIDE CORBELS ARE TILTED SLIGHTLY ON PILES



THIS DRAWING IS EXAGGERATED AT ANGLE





Inspection No: 3  
Bridge No: 4629

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PL  
Date: 29.3.01  
Checked By: SS  
Date: 29.4.01

PIER NO : 1

PILE NO	DIA mm	TIMBER DRILLING			EXTENT OF ROT		SPLITS		BLAZE MARKINGS			HALF CAPS
		Solid	Rot	Pipe	Below GL	Above GL	Type	RQS Band ?	Marking Ft / m	Ht H/C to Blz	Ht Blz to GL	Sags (mm)
1	320	140		20		AT TOP	LV ↑	✓ 2	-	0.800	-	
2	250	105		20		AT TOP	LV ↓	✓ 1	-	0.800	-	
3	260	100		30		AT TOP	MV ↑		-	0.800	-	
4	260	230					MV ↑		-	0.900	-	
5	300	120		30		AT TOP	NUM LV ↑	✓ 2	-	0.900	-	
6	280	100		40		AT TOP	NUM LV ↓	✓ 1	-	0.900	-	
7												
8												
9												
10												


CORBELS : OK  
IRONWORK : HEAVY RUST  
WALERS : SIZE N/A x -  
BRACING : SIZE 220V x 70H SPLIT AT ENDS REST OK.  
FULL HALF CAPS : SIZE 300 x 300 LHS END SOLID. L-SOLID.  
COMMENTS : RHS END-SOLID.

PILES 1, 2, 3, 5, 6 HAVE SUBSIDED DUE TO SETTLEMENT OF BEDLOGS. MAINLY 1, 2, 3, 6 APPROX 50-60MM

CORBELS 1 & 6 HAVE TILTED OVER - PHOTO

FULL CAP IS JOINED OVER PILE 3 + BETWEEN PILES 4+5  
BEDLOG EXCAVATED AT PILE 1 0.900M BELOW. BEDLOG Ø 400  
APPROX SOLID BED<sup>LOG</sup> IS WANDOO

\* END VIEW OF FULL CAP LHS - PHOTOS.



PIER 1 SUBSIDED LHS 60-70MM - PHOTO

RHS POSSIBLY SUBSIDED 20-30MM

PILE 4 (CENTER OF PIER) IS AT CORRECT HEIGHT? 70MM ABOVE STRING LINE - PHOTO.





MAIN ROADS  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PLDate: 29.3.01Checked By: SSDate: 29.4.01

Inspection No: 3  
Bridge No: 4629

PIER NO : 2

PILE NO	DIA mm	TIMBER DRILLING			EXTENT OF ROT		SPLITS		BLAZE MARKINGS			HALF CAPS
		Solid	Rot	Pipe	Below GL	Above GL	Type	RQS Band ?	Marking Ft/m	Ht H/C to Blz	Ht Blz to GL	Sags (mm)
1	300	SEE BELOW					LV ↓	✓ 1	→ 0.600	—		
2	290	115		30		AT TOP	NUM LV ↓	✓ 2	→ 0.700	—		
3	270	105		30		AT TOP	LV ↓	✓ 2	— 0.700	—		
4	340	170					LV ↓	✓ 2	— 0.500	—		
5	320	130		30		AT TOP	MV ↓		— 0.800	—		
6	320	140		20		AT TOP	NUM LV ↓	✓ 1	— 0.800	—		
7												
8												
9												
10												

CORBELS : #1 REQ'S REPLACING

IRONWORK : HEAVY RUST

WALERS : SIZE — x N/A

BRACING : SIZE 220V x 70H

FULL HALF CAPS : SIZE 300 x 300

COMMENTS : FULL CAP WEATHERED - OK. L SOLID

RHS END 20/PIPE REST SOLID

FULL CAP JOINED BETWEEN PILES 2+3 PLUS 4+5

BED LOG EXCAVATED AT PILE 1 0.900m DOWN. Ø 400 APPROX SOLID.

CORBEL 1 VERY LARGE PIPE + TERMITE DAMAGE

AT LHS END. CONTACT TO PILE 50mm x 80mm APPROX


AT RHS TOP OF PILE. CORBEL AT THAT POINT A2 30/s

A1. 100/s AT CONTACT POINT. #6 A1 100/s A2 90/s

PILE 1 A1. 80/s

CORBEL 1 END VIEW LHS. PHOTO

RHS 70/s LHS 80/s







MAIN ROADS  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PLDate: 29.3.01Checked By: SSDate: 24.4.01Inspection No: 3Bridge No: 4629

ABUTMENT: 2

LHS

RHS

PILE NO	DIA mm	TIMBER DRILLING			EXTENT OF ROT		PILE SPLITS		BLAZE MARKINGS		
		Solid	Rot	Pipe	Below GL	Above GL	Type	RQS Band	Marking Ft / m	HI HAC to Blz	HI Blz to GL
1	300	120		30		AT TOP	LV ↓	✓	-	0.100	-
2	320	SEE COMMENTS SHT.			0.400+	TO TOP	-		-	0.400	-
3	290	125		20			-		-	0.400	-
4	280	140					mv ↑		-	0.400	-
5	300	120		30			LV ↑	✓	-	0.300	-
6	300	SEE COMMENTS SHT.				TOP 300 OF PILE	LV ↑	✓	-	0.300	-
7											
8											
9											
10											
11											
12											
13											
14											
15											

SHEETING - WINGWALLS

LHS : NATURAL GROUND - MAJOR SCOURING - PHOTO

RHS : NATURAL GROUND - OK

SHEETING - ABUTMENT

C : TOP SHT U/S REST SOLID

LHS : SOLID

RHS : TOP SHT U/S REST SOLID

WING CAP CONDITION

FULL CAPS.

: NATURAL GROUND RHS - OK, LHS MAJOR SCOUR

HALE CAPS / SHT BEAMS

- SIZE: 300 x 300 No. 1 LHS END 20/PIPE

COMMENTS

: REST SOLID WEATHERED AT END - OK.

FULL CAP AT PILE 4 - 130'S FRONT 40'S BACK REST PIPE. FULL CAP

BELOW STR 6 - 130'S FRONT PIPE TO BACK. VERTICLE 90'S BOTTOM 60'S TOP

REST PIPE. BED LOG BELOW PILE 6 EXCAVATED 0.900m DOWN

Ø 300 SOLID. TOP SHEETING U/S BETWEEN STRS 4 + 11.

MAIN ROADS Western Australia

Dundas\BDGINSPE.DOC

Shire of Narrogin

IRON WORK HAS HEAVY RUST.

09/95

Bridges Asset Management Plan 2020-2030

Page | 245



MAIN ROADS  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PL

Date: 29.3.01

Checked By: SS

Date: 24.4.01

Inspection No: 3  
Bridge No: 4629


## SPECIAL COMMENTS

BRIDGE PART: .....

ABUT 2

CORBEL 1 A1 100/s A2 80/s ONLY SEATED  
RHS OF PILE DUE TO CORBEL TILTING

FULL CAP UNDER STR 8



VERTICLE DRILL RESULTS

70/s BOTTOM 20/s TOP ?

FULL CAP BELOW STR 9 50/s FRONT 20/s BACK  
REST IS PIPE. VERTICLE 40/s BOTTOM 50/s TOP  
REST PIPE

FULL CAP BELOW STR 10 40/s FRONT 40/s BACK  
REST PIPE. VERTICLE 30/s BOTTOM 90/s TOP REST PIPE.

FULL CAP RHS END BELOW STR 11 50/s FRONT 60/s BACK  
REST PIPE.

CORBEL 2 SEATED LHS DUE TO TILTING 160/s FRONT 90/s  
BACK REST PIPE & ROT.

PILE 2 A2-70/s

PILE 6 A2-50/s

LHS 70/s



RHS 70/s

LHS 50/s



RHS 60/s

A1-60/s

A1-50/s



MAIN ROADS  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PL

Date: 29.3.01

Checked By: SS

Date: 24.4.01

Inspection No: 3  
Bridge No: 4629

STRINGERS - SPAN NO : 1

FAILED

\*REFER TO LEGEND FOR DRILLING LOCATIONS

STRINGER NO		1	2	3	4	5	6	7	8	9	10	11	12
A B U T 1 E N D	H DIAMETER	260	260	260	260	260	260	260	290	260	260	260	
	V MEASUREMENT	260	260	260	260	260	260	260	260	260	260	260	
	DRILL VERT	Solid		110	110	110	110	110	90	110	60	110	100
		Rot											
		Pipe		20	20	20	20	20	P <sub>TOP</sub>	20	P <sub>TOP</sub>	20	30
	DRILL HORIZ.	Left							100		80		
		Right							50		60		
	VERTICAL SPLIT	Large											
		Minor											
	HORIZ. SPLIT	Large											
		Minor											
E N D	RQS	V.Split											
	BOLTING?	H.Split											

M I D S P A N	H DIAMETER	260	260	260	260	260	260	260	260	260	260	260	
	V MEASUREMENT	260	260	260	260	260	260	260	260	260	260	260	
	DRILL VERT	Solid		130	120	80	130	100	130	110	110	110	100
		Rot											
		Pipe			P <sub>TOP</sub>	50		30		20	20	20	30
	DRILL HORIZ.	Left				70	70						
		Right				100	90						
	SPLIT	Vert											
		Horiz											
	RQS	V.Split											
	BOLTING?	H.Split											

A B U T E N D	H DIAMETER	260	260	260	260	260	260	260	260	260	260	260	
	V MEASUREMENT	120	260	260	260	140	120	120	120	120	260	130	
	DRILL VERT	Solid		40	70	130	130	50	60	70	40	60	110
		Rot											
		Pipe		20	60			20		P <sub>TOP</sub>	20		20
	DRILL HORIZ.	Left			70				90				110
		Right			80				90				90
	VERTICAL SPLIT	Large											
		Minor											
	HORIZ. SPLIT	Large											
		Minor											
E N D	RQS	V.Split											
	BOLTING?	H.Split											

COND OF BEARERS : NOT APPLICABLE



SIZE



X



S



Rot



COND OF SPIKING PLANK : NOT APPLICABLE



SIZE



X



S



Rot



CONDITION OF DECKING : S/Rot

80 20 %

COND OF DECK ENDS : S/Rot

50 50 %

COMMENTS : STRS ARE PLACED ON FULL CAPS THRU-OUT.

ACTIVE TERMITES STRS 5,6,11. DECKING SIZE 220H X 120V

STR 5 U/S A2 END DUE TO LARGE HORIZONTAL SPLIT - PHOTO.

STRS OVERLAPPED NO'S 1,5,6,7,8,9,11



 MAIN ROADS  
Western Australia

TIMBER BRIDGE  
DETAILED INSPECTION  
REPORT

Inspected By: PL  
Date: 29.3.01  
Checked By: SS  
Date: 24.4.01

Inspection No: 3  
Bridge No: 4629

SPECIAL COMMENTS

BRIDGE PART: .....

SPAN 1 1PCE DECKING NEAR U/S BETWEEN  
STRS 8+9 PIER 1 END.



MAIN ROADS  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PL  
Date: 29.3.01  
Checked By: SS  
Date: 29.4.01

Inspection No: 3  
Bridge No: 4629

STRINGERS - SPAN NO : 2

\*REFER TO LEGEND FOR DRILLING LOCATIONS

STRINGER NO		1	2	3	4	5	6	7	8	9	10	11	12
A B U T 1  E N D	H DIAMETER	260	260	260	260	260	260	260	260	260	260	260	
	V MEASUREMENT	260	260	260	120	120	260	120	260	130	260	130	
	DRILL VERT	Solid	110	130	130	110	60	120	60	130	55	110	45
		Rot											
		Pipe	20			20		10			10	20	20
	DRILL HORIZ	Left											
		Right											
	VERTICAL SPLIT	Large		✓		✓					✓		
		Minor					✓						✓
	HORIZ SPLIT	Large											
	Minor												
RQS	V.Split		✓		✓					✓			
BOLTING?	H.Split												
M I D S P A N	H DIAMETER	260	260	260	260	260	260	260	260	260	260	260	
	V MEASUREMENT	260	260	260	260	260	260	260	260	260	260	260	
	DRILL VERT	Solid	100	130	110	130	130	110	130	130	130	100	110
		Rot											
		Pipe	30		20			20				30	20
	DRILL HORIZ	Left											
		Right											
	SPLIT	Vert		✓		✓					✓		
		Horiz											
	RQS	V.Split		✓		✓					✓		
BOLTING?	H.Split												
A B U T  E N D	H DIAMETER	260	260	260	260	260	260	260	260	260	260	260	
	V MEASUREMENT	120	260	260	120	120	120	120	260	120	260	120	
	DRILL VERT	Solid	40	100	130	60	60	40	60	130	40	130	40
		Rot											
		Pipe	20	30	20			20		20		20	
	DRILL HORIZ	Left								50			
		Right								90			
	VERTICAL SPLIT	Large	✓	✓		✓			✓	✓			
		Minor					✓						
	HORIZ SPLIT	Large				✓		✓	✓				
	Minor												
RQS	V.Split	✓	✓		✓		✓	✓	✓	✓			
BOLTING?	H.Split												

COND OF BEARERS : NOT APPLICABLE ☒

SIZE  X  S  Rot

COND OF SPIKING PLANK : NOT APPLICABLE ☒

SIZE  X  S  Rot

CONDITION OF DECKING : S/Rot   %

COND OF DECK ENDS : S/Rot   %

COMMENTS : .....



MAIN ROADS  
Western AustraliaTIMBER BRIDGE  
DETAILED INSPECTION  
REPORT

Inspected By: PL

Date: 29.3.01

Checked By: SS

Date: 24.4.01

Inspection No: 3

Bridge No: 4629

STRINGERS - SPAN NO: 3

\*REFER TO LEGEND FOR DRILLING LOCATIONS

STRINGER NO		1	2	3	4	5	6	7	8	9	10	11	12
A B U T 1 E N D	H DIAMETER	260	260	260	260	260	260	260	260	260	260	260	
	V MEASUREMENT	260	260	260	260	120	260	120	260	120	260	120	
	DRILL VERT	Solid	20	130	100	100	20	120	60	70	60	170	
		Rot											
		Pipe	P <sub>TO</sub> TOP		30	30	40	P <sub>TO</sub> TOP		60		20	20
	DRILL HORIZ	Left	60				120	60		80			
		Right	90				90	80		60			
	VERTICAL SPLIT	Large Minor	✓			✓	✓			✓	✓		
	HORIZ SPLIT	Large Minor										✓	
	RQS	V.Split H.Split	✓			✓	✓			✓	✓	✓	

M I D S P A N	H DIAMETER	260	260	260	260	260	260	260	260	260	260	260	
	V MEASUREMENT	260	260	260	260	260	260	260	260	260	260	260	
	DRILL VERT	Solid	70	110	110	110	110	70	130	80	130	130	60
		Rot											
		Pipe	P <sub>TO</sub> TOP	20	20	20	20	P <sub>TO</sub> TOP		P <sub>TO</sub> TOP		130	70
	DRILL HORIZ	Left	80					70		40		80	60
		Right	110					50		80		90	100
	SPLIT	Vert Horiz				L	L	L			L	L	L
	RQS	V.Split H.Split				✓	✓	✓			✓	✓	✓
	BOLTING?												

A B U T 2 E N D	H DIAMETER	260	260	260	260	260	260	260	260	260	260	260	
	V MEASUREMENT	260	260	260	260	260	260	260	260	260	260	260	
	DRILL VERT	Solid	90	80	130	80	90	40	120	50	110	110	70
		Rot											
		Pipe	40	50		P <sub>TO</sub> TOP	P <sub>TO</sub> TOP	P <sub>TO</sub> TOP		80	20	20	P <sub>TO</sub> TOP
	DRILL HORIZ	Left	110	80		70	80	80	70	60			70
		Right	100	90		130	110	40	70	40			50
	VERTICAL SPLIT	Large Minor				✓	✓				✓	✓	
	HORIZ SPLIT	Large Minor				✓							✓
	RQS	V.Split H.Split				✓	✓				✓	✓	✓

COND OF BEARERS : NOT APPLICABLE ✓

SIZE — X — S — Rot —

COND OF SPIKING PLANK : NOT APPLICABLE ✓

SIZE — X — S — Rot —

CONDITION OF DECKING : S/Rot 80 20 %

COND OF DECK ENDS : S/Rot 50 50 %

COMMENTS : STRS 2, 11 ACTIVE TERMITES. STR 7 IS SARRAH

STR 10 CROSS SECTION. PIPE IN STR 10 EXTENDS.

PIPE 1901 FROM A1 END TO NEAR A2 END

100 ACTIVE TERMITE NEST STR 8 A2 END





# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspection No:.....

Bridge No:.....



## LEGEND

LVS - LARGE VERTICAL SPLIT  
MVS - MINOR VERTICAL SPLIT  
LHS - LARGE HORIZONTAL SPLIT  
MHS - MINOR HORIZONTAL SPLIT  
LDS - LARGE DIAGONAL SPLIT  
MDS - MINOR DIAGONAL SPLIT  
RQS - REQUIRES BANDING/BOLTING

## PRIORITY BOLT/BAND

0 - A.S.A.P.  
1 - ROUTINE MAINTENANCE  
2 - LOW PRIORITY


P - PIPE  
F - FRIABLE  
S - SOLID  
N/A - NOT APPLICABLE  
V - VERTICAL  
H - HORIZONTAL  
D - PIPE DIAMETER  
W - WIDTH BETWEEN WALING  
GL - GROUND LEVEL  
Str - STRINGER  
Ht - HEIGHT  
CL - CENTRE LINE  
H/C - HALF CAP  
Blz - BLAZE  
O/A - OVERALL  
LHS - LEFT HAND SIDE  
RHS - RIGHT HAND SIDE  
Ft - FEET  
Cond - CONDITION  
US - UNSOUND (STRUCTURALLY)



NOTE: All dimensions are of solid timber excluding sap wood and any surface rot on piles and stringers



Scale 1 : 250 000  
(1cm = 2.5km)  
For scale bar see page 14







MAIN ROADS  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PL  
Date: 29.3.01  
Checked By: SS  
Date: 24.4.01

Inspection No: 3  
Bridge No: 4629

## PHOTOGRAPHIC RECORD

### PHOTO CHECK LIST

- General view of Bridge, for site information.
- Abutment detail, especially if scour a problem.
- Wing wall detail - show scale of piles.
- Pier detail - show widening if present.  
do half caps change in size, or are they repaired?
- Accident or fire damage, or vandalism?
- Significant services - how do they interact with abutments. piers?
- Footway details?
- Extent of scour holes, and subsequent structural damage (broken half caps, etc.).
- Are spans propped?
- Serious decay, termite attack or splitting of major members.

Where views of individual structural members are taken, details of Pier/Span No and Pile/Stringer No should be recorded with comments.

Several aspects from the check list may be included in each photograph. In darkened areas, flash photography should normally be used.

NEGATIVE NO (from camera dial)	CAPTION
12	4629
13	OVERAL VIEW FROM ABUT 1
14	LHS VIEW FROM ABUT 2
15	RHS VIEW FROM ABUT 1
16	MAJOR SCOUR AT ABUT 2 LHS APPROACH - FROM AZ ENA
17	MAJOR SCOUR AT ABUT 2 LHS APPROACH - FROM LHS
18	KERR MISSING BOTH SIDES TYPICAL
19	ABUT 1 LHS + LHS WING LAYOUT.
20	ABUT 1 LAYOUT - LHS
21	ABUT 1 LAYOUT RHS
22	ABUT 1 CORBEL 1 LHS END COND. NB FULL CAP
23	ABUT 1 CORBEL 1 TILTED
24	PIER 1 LAYOUT AT LHS FROM A1
25	PIER 1 LAYOUT AS RHS FROM A1





MAIN ROADS  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PLDate: 29.3.01Checked By: SSDate: 24.4.01Inspection No: 3Bridge No: 4629

## PHOTOGRAPHIC RECORD

### PHOTO CHECK LIST

- General view of Bridge, for site information.
- Abutment detail, especially if scour a problem.
- Wing wall detail - show scale of piles.
- Pier detail - show widening if present.  
do half caps change in size, or are they repaired?
- Accident or fire damage, or vandalism?
- Significant services - how do they interact with abutments. piers?
- Footway details?
- Extent of scour holes, and subsequent structural damage (broken half caps, etc.).
- Are spans propped?
- Serious decay, termite attack or splitting of major members.

Where views of individual structural members are taken, details of Pier/Span No and Pile/Stringer No should be recorded with comments.

Several aspects from the check list may be included in each photograph. In darkened areas, flash photography should normally be used.

NEGATIVE NO (from camera dial)	CAPTION
	NEW ROLL
0	4629
1	PIER 1 LHS END SHOWING SUBSIDENCE 60-70 MM FULL CAP COND + CORBEL 1 LHS END COND.
2	PIER 1 RHS END COND NB STR II A2 END LARGE HORIZONTAL SPLIT AT CHECK OUT.
3	SPAN 1 STR 5 A2 END COND FROM A1 LHS.
4	SPAN 1 STR 5 A2 END VIEW FROM BOTTOM.
5	PIER 2 LHS END COND NB CORBEL 1 COND.
6	PIER 1 LHS END A1 SIDE COND.
7	PIER 2 LHS END A2 SIDE COND OF CORBEL
8	PIER 1 PILE 4 AT CORRECT HEIGHT.
9	PIER 1 AT PILE 4 SHOWING TIEING BARS TYPICAL
10	PIER 2 RHS END COND NB OVERLAPPING STRS
11	PIER 2 LAYOUT FROM A1 RHS.
12	ABUT 2 LHS LAYOUT FROM LHS A1





MAIN ROADS  
Western Australia

# TIMBER BRIDGE DETAILED INSPECTION REPORT

Inspected By: PL

Date: 29.3.01

Checked By: SS

Date: 24.4.01

Inspection No: 3

Bridge No: 4629

## PHOTOGRAPHIC RECORD

### PHOTO CHECK LIST

- General view of Bridge, for site information.
- Abutment detail, especially if scour a problem.
- Wing wall detail - show scale of piles.
- Pier detail - show widening if present.  
do half caps change in size, or are they repaired?
- Accident or fire damage, or vandalism?
- Significant services - how do they interact with abutments. piers?
- Footway details?
- Extent of scour holes, and subsequent structural damage (broken half caps, etc.).
- Are spans propped?
- Serious decay, termite attack or splitting of major members.

Where views of individual structural members are taken, details of Pier/Span N<sup>o</sup> and Pile/Stringer No should be recorded with comments.

Several aspects from the check list may be included in each photograph. In darkened areas, flash photography should normally be used.

NEGATIVE N <sup>o</sup> (from camera dial)	CAPTION
13	ABUT 2 RHS LAYOUT FROM RHS A1
14	ABUT 2 LHS FULL CAP + CORBEL 1 COND.
15	ABUT 2 LHS FULL CAP + CORBEL 1 COND.
16	ABUT 2 LHS END FULL CAP + CORBEL FRONT VIEW
	NB END OF BRACING TYPICAL
17	ABUT 2 FULL CAP COND BELOW STRS 7, 8, 9
18	ABUT 2 RHS END FULL CAP + CORBEL 6 COND
19	SPAN 3 STR 10 SHOWING LARGE PIPE AT BOTTOM.
	ALMOST FULL LENGTH OF STR
20	STR OVERLAPS TYPICAL
	MAJOR FAILURE IN ROAD SURFACE OVER STR 5 SPAN 1
	STRINGER 5 SPAN 1 - SPLIT & BROKEN
	DECKING COLLAPSED AT STR 5 ABT 1 END



Region:	<b>Wheatbelt South</b>	Bridge No:	<b>4629</b>	Date:	<b>29.3.01</b>
Road:	<b>Doney St</b>	Road No:	<b>0004</b>	SLK:	<b>0.03</b>
Over:	<b>Narrogin Brook</b>	Spans:	<b>3</b>	Height:	<b>1.400m</b>
LGA:	<b>Narrogin</b>	Inspector:	<b>P. Lewkowski</b>	Length:	<b>11.850</b>



OVERALL VIEW FROM ABUTMENT 1



LEFT HAND SIDE VIEW FROM ABUTMENT 2



Region: **Wheatbelt South**  
Road: **Doney St**  
Over: **Narrogin Brook**  
LGA: **Narrogin**

Bridge No: **4629**  
Road No: **0004**  
Spans: **3**  
Inspector: **P. Lewkowski**

Date: **29.3.01**  
SLK: **0.03**  
Height: **1.400m**  
Length: **11.850**



RIGHT HAND SIDE VIEW FROM ABUTMENT 1



MAJOR SCOUR AT ABUTMENT 2 LEFT HAND SIDE APPROACH-FROM  
ABUTMENT 2 END



Region:	<b>Wheatbelt South</b>	Bridge No:	<b>4629</b>	Date:	<b>29.3.01</b>
Road:	<b>Doney St</b>	Road No:	<b>0004</b>	SLK:	<b>0.03</b>
Over:	<b>Narrogin Brook</b>	Spans:	<b>3</b>	Height:	<b>1.400m</b>
LGA:	<b>Narrogin</b>	Inspector:	<b>P. Lewkowski</b>	Length:	<b>11.850</b>



MAJOR SCOUR AT ABUTMENT 2 LEFT HAND SIDE APPROACH – FROM LEFT HAND SIDE





Region: **Wheatbelt South**  
Road: **Doney St**  
Over: **Narrogin Brook**  
LGA: **Narrogin**

Bridge No: **4629**  
Road No: **0004**  
Spans: **3**  
Inspector: **P. Lewkowski**

Date: **29.3.01**  
SLK: **0.03**  
Height: **1.400m**  
Length: **11.850**



ABUTMENT 1 LEFT HAND SIDE AND LEFT HAND SIDE WING LAYOUT



ABUTMENT 1 LAYOUT LEFT HAND SIDE



Region:	<b>Wheatbelt South</b>	Bridge No:	<b>4629</b>	Date:	<b>29.3.01</b>
Road:	<b>Doney St</b>	Road No:	<b>0004</b>	SLK:	<b>0.03</b>
Over:	<b>Narrogin Brook</b>	Spans:	<b>3</b>	Height:	<b>1.400m</b>
LGA:	<b>Narrogin</b>	Inspector:	<b>P. Lewkowski</b>	Length:	<b>11.850</b>



ABUTMENT 1 LAYOUT RIGHT HAND SIDE



ABUTMENT 1 CORBEL 1 LEFT HAND SIDE END CONDITION - NB FULL CAP



Region: **Wheatbelt South**  
 Road: **Doney St**  
 Over: **Narrogin Brook**  
 LGA: **Narrogin**

Bridge No: **4629**  
 Road No: **0004**  
 Spans: **3**  
 Inspector: **P. Lewkowski**

Date: **29.3.01**  
 SLK: **0.03**  
 Height: **1.400m**  
 Length: **11.850**



ABUTMENT 1 CORBEL 1 TILTED



PIER 1 LAYOUT AT LEFT HAND SIDE FROM ABUTMENT 1



Region:	Wheatbelt South	Bridge No:	4629	Date:	29.3.01
Road:	Doney St	Road No:	0004	SLK:	0.03
Over:	Narrogin Brook	Spans:	3	Height:	1.400m
LGA:	Narrogin	Inspector:	P. Lewkowski	Length:	11.850



PIER 1 LAYOUT AT RIGHT HAND SIDE FROM ABUTMENT 1



PIER 1 LEFT HAND SIDE SHOWING SUBSIDENCE 60-70MM FULL CAP  
CONDITION & CORBEL 1 LEFT HAND SIDE END CONDITION



Region:	Wheatbelt South	Bridge No:	4629	Date:	29.3.01
Road:	Doney St	Road No:	0004	SLK:	0.03
Over:	Narrogin Brook	Spans:	3	Height:	1.400m
LGA:	Narrogin	Inspector:	P. Lewkowski	Length:	11.850



PIER 1 RIGHT HAND SIDE END CONDITION - NB STRINGER 11 END LARGE HORIZONTAL SPLIT AT CHECK OUT



SPAN 1 STRINGER 5 ABUTMENT 2 END CONDITION FROM ABUTMENT 1 LHS Page 8



Region:	<b>Wheatbelt South</b>	Bridge No:	<b>4629</b>	Date:	<b>29.3.01</b>
Road:	<b>Doney St</b>	Road No:	<b>0004</b>	SLK:	<b>0.03</b>
Over:	<b>Narrogin Brook</b>	Spans:	<b>3</b>	Height:	<b>1.400m</b>
LGA:	<b>Narrogin</b>	Inspector:	<b>P. Lewkowski</b>	Length:	<b>11.850</b>



SPAN 1 STRINGER 5 ABUTMENT 2 END VIEW FROM BOTTOM



PIER 2 LEFT HAND SIDE END CONDITION-NB CORBEL 1 CONDITION



Region:	<b>Wheatbelt South</b>	Bridge No:	<b>4629</b>	Date:	<b>29.3.01</b>
Road:	<b>Doney St</b>	Road No:	<b>0004</b>	SLK:	<b>0.03</b>
Over:	<b>Narrogin Brook</b>	Spans:	<b>3</b>	Height:	<b>1.400m</b>
LGA:	<b>Narrogin</b>	Inspector:	<b>P. Lewkowski</b>	Length:	<b>11.850</b>



PIER 1 LEFT HAND SIDE END ABUTMENT 1 SIDE CONDITION



PIER 2 LEFT HAND SIDE END ABUTMENT 2 SIDE CONDITION OF CORBEL



Region: **Wheatbelt South**  
Road: **Doney St**  
Over: **Narrogin Brook**  
LGA: **Narrogin**

Bridge No: **4629**  
Road No: **0004**  
Spans: **3**  
Inspector: **P. Lewkowski**

Date: **29.3.01**  
SLK: **0.03**  
Height: **1.400m**  
Length: **11.850**



PIER 1 PILE 4 AT CORRECT HEIGHT



PIER 1 AT PILE 4 TIEING BARS – TYPICAL



Region: **Wheatbelt South**  
 Road: **Doney St**  
 Over: **Narrogin Brook**  
 LGA: **Narrogin**

Bridge No: **4629**  
 Road No: **0004**  
 Spans: **3**  
 Inspector: **P. Lewkowski**

Date: **29.3.01**  
 SLK: **0.03**  
 Height: **1.400m**  
 Length: **11.850**



PIER 2 RIGHT HAND SIDE END CONDITION – NB OVER LAPPING STRINGERS



PIER 2 LAYOUT FROM ABUTMENT 1 RIGHT HAND SIDE



Region:	Wheatbelt South	Bridge No:	4629	Date:	29.3.01
Road:	Doney St	Road No:	0004	SLK:	0.03
Over:	Narrogin Brook	Spans:	3	Height:	1.400m
LGA:	Narrogin	Inspector:	P. Lewkowski	Length:	11.850



ABUTMENT 2 LEFT HAND SIDE LAYOUT FROM LEFT HAND SIDE ABUT 1



ABUTMENT 2 RIGHT HAND SIDE LAYOUT FROM RIGHT HAND SIDE  
ABUTMENT 1



Region:	<b>Wheatbelt South</b>	Bridge No:	<b>4629</b>	Date:	<b>29.3.01</b>
Road:	<b>Doney St</b>	Road No:	<b>0004</b>	SLK:	<b>0.03</b>
Over:	<b>Narrogin Brook</b>	Spans:	<b>3</b>	Height:	<b>1.400m</b>
LGA:	<b>Narrogin</b>	Inspector:	<b>P. Lewkowski</b>	Length:	<b>11.850</b>



ABUTMENT 2 LEFT HAND SIDE FULL CAP & CORBEL 1 CONDITION



ABUTMENT 2 LEFT HAND SIDE FULL CAP & CORBEL 1 CONDITION



Region: **Wheatbelt South**  
 Road: **Doney St**  
 Over: **Narrogin Brook**  
 LGA: **Narrogin**

Bridge No: **4629**  
 Road No: **0004**  
 Spans: **3**  
 Inspector: **P. Lewkowski**

Date: **29.3.01**  
 SLK: **0.03**  
 Height: **1.400m**  
 Length: **11.850**



ABUTMENT 2 LEFT HAND SIDE FULL CAP & CORBEL FRONT VIEW – NB END OF BRACING TYPICAL



ABUTMENT 2 FULL CAP CONDITION BELOW STRINGERS 7, 8 & 9




Region: **Wheatbelt South**  
Road: **Doney St**  
Over: **Narrogin Brook**  
LGA: **Narrogin**

Bridge No: **4629**  
Road No: **0004**  
Spans: **3**  
Inspector: **P. Lewkowski**

Date: **29.3.01**  
SLK: **0.03**  
Height: **1.400m**  
Length: **11.850**



ABUTMENT 2 RIGHT HAND SIDE END FULL CAP & CORBEL 6 CONDITION



SPAN 3 STRINGER 10 SHOWING LARGE PIPE AT BOTTOM ALMOST FULL  
LENGTH OF STRINGER



Region: **Wheatbelt South**  
Road: **Doney St**  
Over: **Narrogin Brook**  
LGA: **Narrogin**

Bridge No: **4629**  
Road No: **0004**  
Spans: **3**  
Inspector: **P. Lewkowski**

Date: **29.3.01**  
SLK: **0.03**  
Height: **1.400m**  
Length: **11.850**



STRINGER OVERLAPS TYPICAL



MAJOR FAILURE IN ROAD SURFACE OVER STRINGER 5 ABUTMENT 1 END Page 17



Region: **Wheatbelt South**Bridge No: **4629**Date: **29.3.01**Road: **Doney St**Road No: **0004**SLK: **0.03**Over: **Narrogin Brook**Spans: **3**Height: **1.400m**LGA: **Narrogin**Inspector: **P. Lewkowski**Length: **11.850**

STRINGER 5 SPAN 1 SPLIT &amp; BROKEN



DECKING COLLAPSED AT STRINGER 5 ABUTMENT 1 END

Page intentionally left blank



# **Main Roads WA 10 Year Bridge program**

# MAIN ROADS WA 10 YEAR BRIDGE PROGRAM

Bridge No.	Road Name	SLK	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28	2028/29	2029/30	Inspection Date	Scope of Works
3122	Tarwonga Road	2.82			\$0					\$0					17-08-17	2020/21 - Preventative Maintenance - As per Shires schedule \$8,150; Refer D18#627892
3122	Tarwonga Road	2.82							\$1						17-08-17	2024/25 - Replace With Culvert - due in 2022. Only work required is Preventative Maintenance, to be done by the Shire. Then consider replacement at end of RCO life 2026/27; Waterways report Existing Bridge ARI 20 dry 50 wet; Option 1: single span 5m long Bridge ARI 10 dry 20 wet; Option 2: 3x 1500 dia pipe culvert ARI 10 dry 20 wet; Option 3: 3x1200x1200 box culvert ARI 10 dry 20 wet; [A J Humphreys - March 2019].
3125	Whimbin Rock Road	6.10	\$0				\$0								17-01-18	2018/19 - Preventative Maintenance - As per Shires schedule \$14,560; Refer D18#627892. 2018/19 - Preventative Maintenance - As per Shires schedule \$14,560; Refer D18#627892.
3125	Whimbin Rock Road	6.10		\$0		\$15,001									17-01-18	2019/20 - Substructure Repairs - Shire to undertake: Timber sheeting repairs Abutment 1 between piles 3 and 5, 5 and 9 (two bottom sheets), 10 and 11, Abutment 2 between piles 2 and 3 (three bottom sheets), 3 and 4, 5 and 6 (two bottom sheets), 8 and 9, 9 and 10 (two top sheets); Stringer/half-cap packing between Span 3 stringers 1 and 6, Abutment 2 full-cap; Bolt tightening; Stringer bolting 2021/22 - Substructure Repairs - Pot Abutment 2 pile 10 and repalce span 3 stringer 3. [AJ Humphreys - Sept 2019] Span 3 stringer 7 AB2 end; Wing capping replacement all wingwalls; Spiking rail repairs. [AJ Humphreys - Sept 2019]
3128A	Manaring Road	3.58						\$270,000							17-01-18	2023/24 - Replace With Culvert - 2x 2100 dia pipe culvert, Shire to design and construct, Refer D19#639389 for shires estimate.
3142	Havelock Street	0.61					\$0					\$0			25-11-14	2022/23 - Preventative Maintenance - As per Shires schedule \$11,100; Refer D18#627892 2027/28 - Preventative Maintenance - As per Shires schedule \$11,100; Refer D18#627892
3142	Havelock Street	0.61						\$0							25-11-14	2023/24 - Replace With Culvert - Consider for Replacement. Town of Narrogin to Design n Construct. Waterways report Complete; Existing Bridge ARI 50 dry; Option 1: 7x1800x1800 box culvert ARI 50 dry; Option 2: 5x 1800 dia pipe culvert ARI 20 dry 50 wet; Option 3: 4x1800x1800 box culvert ARI 20 dry 50 wet; Option 4: single span 12m long Bridge ARI 20 dry 50 wet; Shire need to do Preventive Maintenance - for funding. [A J Humphreys - Feb 2018]



## MAIN ROADS WA 10 YEAR BRIDGE PROGRAM

4551	Tarwonga Road	22.78		\$0					\$0						15-01-19	2019/20 - Preventative Maintenance - As per Shires schedule \$27,990; Refer D18#627892 2024/25 - Preventative Maintenance - As per Shires schedule \$27,990; Refer D18#627892
4551	Tarwonga Road	22.78				\$0					\$0				15-01-19	2021/22 - Substructure Repairs - Consider repairs to Pier 3 halfcap, Abutment 2 halfcap between piles 7 and 8; Settlement at Piers 1 and 2; Pier 3 pile 4 pot extension. Remove Prop at Abutment 2 stringer 1 not required, prop installed 2005 -repairs undertaken 2008. [AJ Humphreys Sept 2019] 2026/27 - No work – await next L2 Inspection - due in 2024. [A J Humphreys - Sept 2019]
4629	Former Station Access - Was Doney Street	0.04				\$0					\$0				29-03-01	2021/22 - Preventative Maintenance - Footbridge - As per Shires schedule \$11,080; Refer D18#627892 2026/27 - Preventative Maintenance - Footbridge - As per Shires schedule \$11,080; Refer D18#627892
9250	Northam Cranbrook	167.89					\$0					\$0			08-02-13	2022/23 - Preventative Maintenance - Footbridge - As per Shires schedule \$18,100; Refer D18#627892 2027/28 - Preventative Maintenance - Footbridge - As per Shires schedule \$18,100; Refer
9250	Northam Cranbrook	167.89								\$0					08-02-13	2025/26 - Substructure Repairs - Corrosion protection a bearing repairs, or await next DIR due in 2027 or until bridge recieve preventative maintenance. [AJ Humphreys - Nov 2018]
		Totals(\$)	\$0	\$0	\$0	\$15,001	\$0	\$270,000	\$1	\$0	\$0	\$0	\$0	\$0		

Page intentionally left blank




# **Shire of Narrogin**

## **Annual L1 Bridge Inspections 2020**



# TIMBER AND NON-TIMBER BRIDGE ROUTINE VISUAL INSPECTION REPORT (Level 1 Inspection)



Bridge Number:	3125	Crossing Name:	
Road Name:	Whimsy Rock	Road Number:	
SLK:		Local Authority:	SHIRE OF NARRAGIN
Responsibility Area:		Latitude:	
Inspected By:	C L D CURRI	Longitude:	
Inspection Date:	30-04-2020		

Have structural issues been found that require further investigation? (Y/N)


☒ N

Inspection Item	Defect		Comments (Including location and extent)	Maint. Required
	Yes	No		
<b>1. Road Surface</b> Signs and Delineators: missing, damaged, obscured Road Surface and Footpaths: material defects, surfacing defects, settlement, depressions, joint transitions, kerbing, shoulders	<input checked="" type="checkbox"/>	<input type="checkbox"/>	NEW WIDTH MARKERS NEEDED to be at POSTS AND REALIGNING - ROAD SURFACE NEEDS PREMIXING EITHER END	<input type="checkbox"/>
<b>2. Guardrails/Barriers</b> Accident damage, connections, alignment, material defects	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>3. Road Drainage</b> Scuppers, drains, gully traps, erosion	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>4. Waterways, Vegetation and Debris</b> Vegetation and debris in waterways and clearance envelope Embankment erosion, scour, damaged guide-banks	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>5. Footpaths</b> Drainage, even surface, surface condition, railing	<input type="checkbox"/>	<input type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
<b>6. Expansion Joints and Deck Joints</b> Loose/damaged fixings, damaged/missing seals, damage to deck/nosings, obstructions in gap, gaps closed, decks in contact/damaged	<input type="checkbox"/>	<input type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
<b>7. Bearings</b> Bearings displaced or damaged, seating, corrosion, seized	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>8. Superstructure</b> Material defects or damage to beams/stringers, fasteners, soffit, cross bracing or coatings Debris/dirt build-up, impact damage, excessive movement/vibration, dampness through deck, condition of air release holes	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>9. Substructure</b> Material defects to piles, footings, walls or capbeams Movement of abutment or wing walls Substructure protection (bridges over road/rail)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	WING CAPPIES NEEDS REPLACING ON ALL FOUR CORNERS OF BRIDGE	<input type="checkbox"/>





TIMBER AND NON-TIMBER  
BRIDGE ROUTINE VISUAL  
INSPECTION REPORT  
(Level 1 Inspection)



Defect Descriptions

Material	Defect Descriptions
Concrete	Cracking (hairline: $\leq 0.1$ mm) (fine: $> 0.1$ & $\leq 0.3$ mm) (medium: $> 0.3$ mm & $\leq 0.7$ mm) (heavy: $> 0.7$ mm), spalling, corrosion of reinforcement, rust staining, efflorescence
Steel	Bending, buckling, cracking, distortion, corrosion, protective coating damage/deterioration, loose fasteners
Timber	Splitting, crushing, rot, failure, termites/termite nest
Masonry	Cracking, opening of joints, mortar loss, bulging
Bituminous Surfacing	Cracking, crazing, breaking up, heaving, shoving, rutting
Protective Coating	Cracked, weathered, peeling, flaking, oxidising

General Comments

BRIDGE IS A THREE SPAN BRIDGE -

CONCRETE OVERLAY, STEEL POSTS AND RAILING, WOOD ABUTMENTS, WOOD PIERS,  
TIMBER DECKING -

PREVENTATIVE MAINTENANCE CARRIED OUT BY CRD CURRI IN FEBRUARY 2019

SKETCHING REPAIRS CARRIED OUT BY CRD CURRI IN APRIL 2020 -

WORK NEEDED :

APPROACHES TO BRIDGE BOTH ENDS NEEDED PREMIXING .

NEW WIDTH MARKERS NEEDED REALIGNING AND PUT ON POSTS .

NEW WING CAPPING NEEDED ON ALL FOUR CORNERS .

(3)

Ancillary Items (such as service attachments etc.)


This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Bridge Inspection Manual for Level 1 Inspections.

Signature: \_\_\_\_\_

Position: Maintenance Foreman Date: 30-04-2020



# TIMBER AND NON-TIMBER BRIDGE ROUTINE VISUAL INSPECTION REPORT (Level 1 Inspection)



Bridge Number:	H551	Crossing Name:	
Road Name:	BARWONGA	Road Number:	
SLK:		Local Authority:	SHIRE OF NARRAGIN
Responsibility Area:		Latitude:	
Inspected By:	CED WEL	Longitude:	
Inspection Date:	30-04-2020		

Have structural issues been found that require further investigation? (Y/N)


☒ N

Inspection Item	Defect		Comments (Including location and extent)	Maint. Required
	Yes	No		
<b>1. Road Surface</b> Signs and Delineators: missing, damaged, obscured Road Surface and Footpaths: material defects, surfacing defects, settlement, depressions, joint transitions, kerbing, shoulders	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>2. Guardrails/Barriers</b> Accident damage, connections, alignment, material defects	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>3. Road Drainage</b> Scuppers, drains, gully traps, erosion	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>4. Waterways, Vegetation and Debris</b> Vegetation and debris in waterways and clearance envelope Embankment erosion, scour, damaged guide-banks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	SCOURING AROUND BOTTOM OF PILE 4 ON PILE 3. (WEDS ROCKING)	<input type="checkbox"/>
<b>5. Footpaths</b> Drainage, even surface, surface condition, railing	<input type="checkbox"/>	<input type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
<b>6. Expansion Joints and Deck Joints</b> Loose/damaged fixings, damaged/missing seals, damage to deck/nosings, obstructions in gap, gaps closed, decks in contact/damaged	<input type="checkbox"/>	<input type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
<b>7. Bearings</b> Bearings displaced or damaged, seating, corrosion, seized	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>8. Superstructure</b> Material defects or damage to beams/stringers, fasteners, soffit, cross bracing or coatings Debris/dirt build-up, impact damage, excessive movement/vibration, dampness through deck, condition of air release holes	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>9. Substructure</b> Material defects to piles, footings, walls or capbeams Movement of abutment or wing walls Substructure protection (bridges over road/trail)	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>





TIMBER AND NON-TIMBER  
BRIDGE ROUTINE VISUAL  
INSPECTION REPORT  
(Level 1 Inspection)



Defect Descriptions

Material	Defect Descriptions
Concrete	Cracking (hairline: $\leq 0.1\text{mm}$ ) (fine: $> 0.1$ & $\leq 0.3\text{mm}$ ) (medium: $> 0.3\text{mm}$ & $\leq 0.7\text{mm}$ ) (heavy: $> 0.7\text{mm}$ ), spalling, corrosion of reinforcement, rust staining, efflorescence
Steel	Bending, buckling, cracking, distortion, corrosion, protective coating damage/deterioration, loose fasteners
Timber	Splitting, crushing, rot, failure, termites/termite nest
Masonry	Cracking, opening of joints, mortar loss, bulging
Bituminous Surfacing	Cracking, crazing, breaking up, heaving, shoving, rutting
Protective Coating	Cracked, weathered, peeling, flaking, oxidising

General Comments

BRIDGE IS A FOUR SPAN BRIDGE.

CONCRETE OVERLAY - STEEL POSTS AND RAILING.

TIMBER ABUTMENTS. TIMBER PIERS. TIMBER HALFPIERS, STRINGERS, DECKING AND GIRDERS.

PREVENTATIVE MAINTENANCE CARRIED OUT BY CED CURRI IN FEBRUARY 2020.

SCOURING AROUND BOTTOM OF PILE 4 ON PIER 3. (NEEDS RACKING)

①


Ancillary Items (such as service attachments etc.)

This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Bridge Inspection Manual for Level 1 Inspections.

Signature: [Signature] Position: Maintenance Foreman Date: 30-04-2020



# TIMBER AND NON-TIMBER BRIDGE ROUTINE VISUAL INSPECTION REPORT (Level 1 Inspection)



Bridge Number:	3122	Crossing Name:	
Road Name:	BARWONGA	Road Number:	
SLK:		Local Authority:	SHIRE OF NARROGIN
Responsibility Area:		Latitude:	
Inspected By:	CED CURRI	Longitude:	
Inspection Date:	30-04-2020		

Have structural issues been found that require further investigation? (Y/N)



Inspection Item	Defect		Comments (Including location and extent)	Maint. Required
	Yes	No		
<b>1. Road Surface</b> Signs and Defineators: missing, damaged, obscured Road Surface and Footpaths: material defects, surfacing defects, settlement, depressions, joint transitions, kerbing, shoulders	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>2. Guardrails/Barriers</b> Accident damage, connections, alignment, material defects	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>3. Road Drainage</b> Scuppers, drains, gully traps, erosion	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>4. Waterways, Vegetation and Debris</b> Vegetation and debris in waterways and clearance envelope Embankment erosion, scour, damaged guide-banks	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>
<b>5. Footpaths</b> Drainage, even surface, surface condition, railing	<input type="checkbox"/>	<input type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
<b>6. Expansion Joints and Deck Joints</b> Loose/damaged fixings, damaged/missing seals, damage to deck/nosings, obstructions in gap, gaps closed, decks in contact/damaged	<input type="checkbox"/>	<input type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
<b>7. Bearings</b> Bearings displaced or damaged, seating, corrosion, seized	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>8. Superstructure</b> Material defects or damage to beams/stringers, fasteners, soffit, cross bracing or coatings Debris/dirt build-up, impact damage, excessive movement/vibration, dampness through deck, condition of air release holes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	CORREL N° 8 HOLLOW / INKROUGH MIDDLE (WOODS BOLTING)	<input type="checkbox"/>
<b>9. Substructure</b> Material defects to piles, footings, walls or capbeams Movement of abutment or wing walls Substructure protection (bridges over road/rail)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	CHECK IN MASONRY WALL OF PIER. ABUTMENT WALLS AND PIER NEED RENDERING	<input type="checkbox"/>





TIMBER AND NON-TIMBER  
BRIDGE ROUTINE VISUAL  
INSPECTION REPORT  
(Level 1 Inspection)



Defect Descriptions

Material	Defect Descriptions
Concrete	Cracking (hairline: $\leq 0.1\text{mm}$ ) (fine: $> 0.1$ & $\leq 0.3\text{mm}$ ) (medium: $> 0.3\text{mm}$ & $\leq 0.7\text{mm}$ ) (heavy: $> 0.7\text{mm}$ ), spalling, corrosion of reinforcement, rust staining, efflorescence
Steel	Bending, buckling, cracking, distortion, corrosion, protective coating damage/deterioration, loose fasteners
Timber	Splitting, crushing, rot, failure, termites/termite nest
Masonry	Cracking, opening of joints, mortar loss, bulging
Bituminous Surfacing	Cracking, crazing, breaking up, heaving, shoving, rutting
Protective Coating	Cracked, weathered, peeling, flaking, oxidising

General Comments

BRIDGE IS A TWO SPAN BRIDGE.

CONCRETE OVERLAY, STEEL POSTS AND RAILING, MASONRY ABUTMENTS, MASONRY PIER, TIMBER STRINGERS AND CORBELS.

PREVENTATIVE MAINTENANCE NEEDED:

FUNGICIDE TREATMENT TO OUTSIDE STRINGERS.

FUNGICIDE TREATMENT TO BED LOGS.

END GRAIN TREATMENT

BOLT TIGHTENING.


CORBEL NEEDS BOLTING.

ABUTMENT AND PIER WALLS NEED RENDERING.

③

Ancillary Items (such as service attachments etc.)


This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Bridge Inspection Manual for Level 1 Inspections.

Signature: 

Position: Maintenance Foreman Date: 30-04-2020



# TIMBER AND NON-TIMBER BRIDGE ROUTINE VISUAL INSPECTION REPORT (Level 1 Inspection)



Bridge Number:	3128	Crossing Name:	
Road Name:	MANARING	Road Number:	
SLK:		Local Authority:	SHIRE OF NARRAGIN
Responsibility Area:		Latitude:	
Inspected By:	C.D. WILK	Longitude:	
Inspection Date:	30-04-2020		

Have structural issues been found that require further investigation? (Y/N)



Inspection Item	Defect		Comments (Including location and extent)	Maint. Required
	Yes	No		
<b>1. Road Surface</b> Signs and Delineators: missing, damaged, obscured Road Surface and Footpaths: material defects, surfacing defects, settlement, depressions, joint transitions, kerbing, shoulders	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>2. Guardrails/Barriers</b> Accident damage, connections, alignment, material defects	<input checked="" type="checkbox"/>	<input type="checkbox"/>	REPLACE FISHTAILS WITH BOLLARDS	<input type="checkbox"/>
<b>3. Road Drainage</b> Scuppers, drains, gully traps, erosion	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>4. Waterways, Vegetation and Debris</b> Vegetation and debris in waterways and clearance envelope Embankment erosion, scour, damaged guide-banks	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	SCOURING UNDER BRIDGE IN SPAN 1	<input type="checkbox"/>
<b>5. Footpaths</b> Drainage, even surface, surface condition, railing	<input type="checkbox"/>	<input type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
<b>6. Expansion Joints and Deck Joints</b> Loose/damaged fixings, damaged/missing seals, damage to deck/nosings, obstructions in gap, gaps closed, decks in contact/damaged	<input type="checkbox"/>	<input type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
<b>7. Bearings</b> Bearings displaced or damaged, seating, corrosion, seized	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>8. Superstructure</b> Material defects or damage to beams/stringers, fasteners, soffit, cross bracing or coatings Debris/dirt build-up, impact damage, excessive movement/vibration, dampness through deck, condition of air release holes	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>9. Substructure</b> Material defects to piles, footings, walls or capbeams Movement of abutment or wing walls Substructure protection (bridges over road/rail)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	ABUTMENT 2 RIGHT HAND SIDE. PIECE OF WING CAPPIRE NEEDS REPLACING.	<input type="checkbox"/>





# TIMBER AND NON-TIMBER BRIDGE ROUTINE VISUAL INSPECTION REPORT (Level 1 Inspection)



## Defect Descriptions

Material	Defect Descriptions
Concrete	Cracking (hairline: $\leq 0.1\text{mm}$ ) (fine: $> 0.1$ & $\leq 0.3\text{mm}$ ) (medium: $> 0.3\text{mm}$ & $\leq 0.7\text{mm}$ ) (heavy: $> 0.7\text{mm}$ ), spalling, corrosion of reinforcement, rust staining, efflorescence
Steel	Bending, buckling, cracking, distortion, corrosion, protective coating damage/deterioration, loose fasteners
Timber	Splitting, crushing, rot, failure, termites/termite nest
Masonry	Cracking, opening of joints, mortar loss, bulging
Bituminous Surfacing	Cracking, crazing, breaking up, heaving, shoving, rutting
Protective Coating	Cracked, weathered, peeling, flaking, oxidising

## General Comments

BRIDGE IS A TWO SPAN BRIDGE.

WOOD POSTS & STEEL RAILING.

TIMBER ABUTMENTS (ABUTMENT 1 PILES DRIVEN)

(ABUTMENT 2 PILES SITTING ON BEDROCK / MASONRY FOOTING)

(PIER PILES SITTING ON BEDROCK / MASONRY FOOTING)

TIMBER STRINGERS & DECKING AND CORBELS. (NO OVERLAY)

PREVENTATIVE MAINTENANCE NEEDED:

FUNGICIDE TREATMENT TO PILES.

FUNGICIDE TREATMENT TO BEDROCK.

FUNGICIDE TREATMENT TO CURB SIDE STRINGERS.

END GRAIN TREATMENT.

BOLT TIGHTENING.

②

Ancillary Items (such as service attachments etc.)

This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Bridge Inspection Manual for Level 1 Inspections.


Signature: \_\_\_\_\_

Position: Maintenance Foreman Date: 30-04-2020





# TIMBER AND NON-TIMBER BRIDGE ROUTINE VISUAL INSPECTION REPORT (Level 1 Inspection)



Bridge Number:	3142	Crossing Name:	
Road Name:	HAVERLOCK STREET	Road Number:	
SLK:		Local Authority:	SHIRE OF NARROGIN
Responsibility Area:		Latitude:	
Inspected By:	CAD WRM	Longitude:	
Inspection Date:	30-04-2020		

Have structural issues been found that require further investigation? (Y/N)


☒ N

Inspection Item	Defect		Comments (including location and extent)	Maint. Required
	Yes	No		
<b>1. Road Surface</b> Signs and Delineators: missing, damaged, obscured Road Surface and Footpaths: material defects, surfacing defects, settlement, depressions, joint transitions, kerbing, shoulders	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>2. Guardrails/Barriers</b> Accident damage, connections, alignment, material defects	<input checked="" type="checkbox"/>	<input type="checkbox"/>	REPLACE FISHTAILS WITH BULLNOSES (two wood posts needed)	<input type="checkbox"/>
<b>3. Road Drainage</b> Scuppers, drains, gully traps, erosion	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>4. Waterways, Vegetation and Debris</b> Vegetation and debris in waterways and clearance envelope Embankment erosion, scour, damaged guide-banks	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>5. Footpaths</b> Drainage, even surface, surface condition, railing	<input type="checkbox"/>	<input type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
<b>6. Expansion Joints and Deck Joints</b> Loose/damaged fixings, damaged/missing seals, damage to deck/nosings, obstructions in gap, gaps closed, decks in contact/damaged	<input type="checkbox"/>	<input type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
<b>7. Bearings</b> Bearings displaced or damaged, seating, corrosion, seized	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>8. Superstructure</b> Material defects or damage to beams/stringers, fasteners, soffit, cross bracing or coatings Debris/dirt build-up, impact damage, excessive movement/vibration, dampness through deck, condition of air release holes	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>9. Substructure</b> Material defects to piles, footings, walls or capbeams Movement of abutment or wing walls Substructure protection (bridges over road/rail)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	ABUTMENT WALLS NEED RENDERING.	<input type="checkbox"/>





TIMBER AND NON-TIMBER  
BRIDGE ROUTINE VISUAL  
INSPECTION REPORT  
(Level 1 Inspection)



Defect Descriptions

Material	Defect Descriptions
Concrete	Cracking (hairline: $\leq 0.1\text{mm}$ ) (fine: $>0.1$ & $\leq 0.3\text{mm}$ ) (medium: $>0.3\text{mm}$ & $\leq 0.7\text{mm}$ ) (heavy: $>0.7\text{mm}$ ), spalling, corrosion of reinforcement, rust staining, efflorescence
Steel	Bending, buckling, cracking, distortion, corrosion, protective coating damage/deterioration, loose fasteners
Timber	Splitting, crushing, rot, failure, termites/termite nest
Masonry	Cracking, opening of joints, mortar loss, bulging
Bituminous Surfacing	Cracking, crazing, breaking up, heaving, shoving, rutting
Protective Coating	Cracked, weathered, peeling, flaking, oxidising

General Comments

BRIDGE IS A TWO SPAN BRIDGE -  
MASONRY ABUTMENTS AND WINGS - MASONRY PIER -  
CONCRETE TOP - TIMBER DECKING - WOOD STRINGERS - WOOD POSTS AND STEEL RAILING  
  
PREVENTATIVE MAINTENANCE NEEDED -  
FUNGICIDE TREATMENT TO JILL BEAMS AND OUTSIDE STRINGERS -  
END GRAIN TREATMENT -  
BOLT TIGHTENING -  
REPLACE FISHTAILS WITH BULLNOSES -  
ABUTMENT WALLS NEED RENDERING -  
TWO NEW WOOD POSTS -

(3)

Ancillary Items (such as service attachments etc.)

This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Bridge Inspection Manual for Level 1 Inspections.

Signature: [Signature] Position: Maintenance Foreman Date: 30-04-2020



# TIMBER AND NON-TIMBER BRIDGE ROUTINE VISUAL INSPECTION REPORT (Level 1 Inspection)



Bridge Number:	4629	Crossing Name:	
Road Name:	DOWEL STREET	Road Number:	
SLK:		Local Authority:	SHIRE OF NARROGIN
Responsibility Area:		Latitude:	
Inspected By:	C. D. WILK	Longitude:	
Inspection Date:	30-04-2020		

Have structural issues been found that require further investigation? (Y/N)


N

Inspection Item	Defect		Comments (Including location and extent)	Maint. Required
	Yes	No		
<b>1. Road Surface</b> Signs and Delineators: missing, damaged, obscured Road Surface and Footpaths: material defects, surfacing defects, settlement, depressions, joint transitions, kerbing, shoulders	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>2. Guardrails/Barriers</b> Accident damage, connections, alignment, material defects	<input checked="" type="checkbox"/>	<input type="checkbox"/>	TERMITE DAMAGE to ONE POST AND RAIL WOOD POSTS NEEDED LIGHTENING.	<input type="checkbox"/>
<b>3. Road Drainage</b> Scuppers, drains, gully traps, erosion	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>4. Waterways, Vegetation and Debris</b> Vegetation and debris in waterways and clearance envelope Embankment erosion, scour, damaged guide-banks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	BULLBUSINES LOGGING CREEK.	<input type="checkbox"/>
<b>5. Footpaths</b> Drainage, even surface, surface condition, railing	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>6. Expansion Joints and Deck Joints</b> Loose/damaged fixings, damaged/missing seals, damage to deck/nosings, obstructions in gap, gaps closed, decks in contact/damaged	<input type="checkbox"/>	<input checked="" type="checkbox"/>	NOT APPLICABLE.	<input type="checkbox"/>
<b>7. Bearings</b> Bearings displaced or damaged, seating, corrosion, seized	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>8. Superstructure</b> Material defects or damage to beams/stringers, fasteners, soffit, cross bracing or coatings Debris/dirt build-up, impact damage, excessive movement/vibration, dampness through deck, condition of air release holes	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>
<b>9. Substructure</b> Material defects to piles, footings, walls or capbeams Movement of abutment or wing walls Substructure protection (bridges over road/rail)	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>





TIMBER AND NON-TIMBER  
BRIDGE ROUTINE VISUAL  
INSPECTION REPORT  
(Level 1 Inspection)



Defect Descriptions

Material	Defect Descriptions
Concrete	Cracking (hairline: $\leq 0.1\text{mm}$ ) (fine: $> 0.1$ & $\leq 0.3\text{mm}$ ) (medium: $> 0.3\text{mm}$ & $\leq 0.7\text{mm}$ ) (heavy: $> 0.7\text{mm}$ ), spalling, corrosion of reinforcement, rust staining, efflorescence
Steel	Bending, buckling, cracking, distortion, corrosion, protective coating damage/deterioration, loose fasteners
Timber	Splitting, crushing, rot, failure, termites/termite nest
Masonry	Cracking, opening of joints, mortar loss, bulging
Bituminous Surfacing	Cracking, crazing, breaking up, heaving, shoving, rutting
Protective Coating	Cracked, weathered, peeling, flaking, oxidising

General Comments

BRIDGE IS A THREE SPAN BRIDGE.

CONCRETE TOP, STEEL STRINGERS, WOOD PILES AND PILES,  
ONE CONCRETE ABUTMENT, ONE WOOD ABUTMENT, WOOD POSTS AND RAILING.

PREVENTATIVE MAINTENANCE NEEDED:

FUNGICIDE treatment to twelve PILES.

END GRAIN treatment.

TIGHTEN WOOD POSTS.

FIX termite damage.

④

Ancillary Items (such as service attachments etc.)

This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Bridge Inspection Manual for Level 1 Inspections.

Signature: 

Position: Maintenance Foreman Date: 30-04-2020

Page intentionally left blank



# **Shire of Narrogin Annual Bridge Routine Maintenance Checklist Template**

## Shire of Narrogin Annual Bridge Routine Maintenance Checklist Template

Bridge No: \_\_\_\_\_

Frequency	Elements	Activities	Completed ✓
<b><u>Annual Routine Maintenance</u></b>	Inspections	Annual Visual Inspections	
	Drainage - Deck	Clean deck gully drains / scuppers / down pipes	
	Drainage -	Clean, repair drainage systems inside abutments	
	Guard railing	Clean / repaint	
		Repair accident damage	
		Install / Replace delineators	
		Replace broken bolts, tighten loose bolts	
	Expansion Joints / Deck Joints	Clean seals	
		Replace broken bolts, tighten loose bolts	
	Bearings	Clean bearings	
	Approaches	Level pavements	
		Lines	
		Kerbs	
	Signs	Width markers, Signs	
	Deck	Clean fascia panels, repair / replace damaged removable	
	Other	Remove debris & vegetation from roadway, waterway, under	
		Remove Graffiti	
		Clean plaques	
		Maintain landscaping / artwork	
		Minor Scour repairs	
		Maintain access doors & security / locks	
		Remove fences attached to bridges	
		Termates Eradicate	
		Maintain Footpaths	



# **Shire of Narrogin Five Year Bridge Preventative Maintenance Checklist Template**

## Shire of Narrogin Five Year Bridge Preventative Maintenance Checklist Template

Preventative Maintenance for Bridge No: \_\_\_\_\_

Description of Works	Specification 850	Y/N
<b>1 Superstructure</b>		
1.01 Seal all exposed timber decking end grain	850.93.01	
1.02 Reseal all exposed timber decking end grain	850.93.01	
1.03 Guardrail maintenance - timber	850.93.11	
Replace fishtails with bullnoses		
1.04 Deck drainage	850.93.07	
1.05 Removal of deck vegetation	Table 850.1	
1.06 Regulatory and warning signs	Table 850.1	
1.07 Treatment of decking planks - top surface	850.41.07	
1.08 Treatment (fungicide) of gravel pavement	Table 850.1	
1.09 Fungicide treatment of timber stringers - spiral grain	850.93.03	
1.10 Fungicide treatment of outside timber stringers	850.93.02,03	
1.11 Fungicide treatment of ends of wandoo stringers (end spans only)	Table 850.1	
1.12 Stringer / corbel bolting and repair splits	850.29,30	
<b>2 Substructure</b>		
2.01 Seal all exposed timber end grain	850.93.01	
Abutment / wingwall piles	850.93.01	
Abutment sheeting	850.93.01	
Halfcaps	850.93.01,06	
Fullcaps	850.93.01,06	
Braces	850.36 and 93.01	
Walers	850.36 and 93.01	
2.02 Reseal all exposed timber end grain	850.93.01	
Abutment / wingwall piles	850.93.01	
Abutment sheeting	850.93.01	
Halfcaps	850.93.01,06	
Fullcaps	850.93.01,06	
Braces	850.36 and 93.01	
Walers	850.36 and 93.01	
2.03 Tighten all existing bolts and fasteners	850.35	
2.04 Tighten all existing bolts and fasteners within 1.5m of ground line	850.34	
2.05 Fungicide treatment of timber piles at ground line	850.93.04	
2.06 Fungicide treatment of timber piles in permanent water	850.93.04	
2.07 Fungicide treatment of bedlogs and bearers (in contact with ground)	850.93.05	
2.08 Fungicide treatment of timber bearers, pier bedlogs (off ground)	850.93.05	
2.09 Pile banding and repair splits	850.28	
2.10 Vegetation and debris clearance under bridge	850.93.08	
2.11 Marine organism protection	Table 850.1	
<b>3 Specific Works</b>		
3.01 Repair gaps in the abutment / wingwall sheeting - pgi strips		
3.02 Repair rotten abutment / wingwall sheeting - new timber sheet.		
3.03 Scour repairs		
3.04 Reinstall wingwall capping		
3.05 Remove old bolts - dangerous		
3.06 Remove fences off bridge or guardrailling		
3.07 Packing of Halfcaps		
3.08 Packing of Stringers and Corbels		
3.09 Render Masonary Abutments and or Pier walls		

Routine Maintenance - Typically 1 year interval

Periodic Maintenance - Typically 5 year interval

Specific Works - As required

Specification 850 is located on the Main Roads Western Australia website. [//www.mainroads.wa.gov.au/](http://www.mainroads.wa.gov.au/)